


**Final Postflight Hardware Evaluation Report  
RSRM-32 (STS-57)**


**November 1993**


Prepared by:

  
Postfire Hardware Evaluation

Approved by:

  
Project Engineer,  
Postfire Hardware Evaluation

  
Supervisor,  
Postfire Hardware Evaluation

  
Program Manager,  
Flight Motor Support

  
Release

Concurrence by:

Thomas Wind  
Case Design

Jeff Halenstich for ALAN CARLISLE  
Joints & Seals Design

Daniel Duncan  
Integration Design

Mark E. Clark  
Nozzle Design

Cal H. Zep  
Igniter / Instrumentation /  
Electrical Design

Walt F. Lark 3 Nov 75  
Thermal Insulation Design

David Bartell per Telecon  
Quality, Performance Evaluation

Craig Walker  
Systems Assurance

## Table of Contents

<u>Section</u>	<u>Description</u>	<u>Page</u>
<b>1.0</b>	<b>INTRODUCTION .....</b>	<b>1</b>
<b>2.0</b>	<b>REFERENCES .....</b>	<b>1</b>
<b>3.0</b>	<b>EVALUATION SUMMARY .....</b>	<b>2</b>
3.1	CEI Specification Compliance .....	2
<b>4.0</b>	<b>HARDWARE ASSESSMENT RESULTS .....</b>	<b>2</b>
4.1	S&A Devices .....	4
4.2	Nozzle .....	4
4.2.1	Nozzle Metal Components – Excluding Joints .....	4
4.2.2	Nozzle Internal Joints .....	4
4.2.2.1	Nose Inlet-to-Flexible Bearing-to-Cowl (Joint 2) .....	4
4.2.2.2	Nose Inlet-to-Throat (Joint 3) .....	5
4.2.2.3	Throat-to-Forward Exit Cone (Joint 4) .....	5
4.2.2.4	Aft End Ring-to-Fixed Housing (Joint 5) .....	6
4.2.3	Cowl Insulation Segments .....	7
4.2.4	Flexible Bearing Protector, Flexible Bearing, and Flexible Boot .....	7
4.2.4.1	Flexible Bearing Protector .....	7
4.2.4.2	Flexible Bearing .....	7
4.2.4.3	Flexible Boot .....	7
4.2.5	Nozzle Throat Diameter Measurement .....	7
4.2.6	Nozzle Phenolic Bondlines .....	8
4.2.6.1	Ultrasonic Inspection of Fixed Housing Assemblies ....	8
4.2.7	Nozzle Phenolic Sections .....	9
4.3	Leak Check Port Plugs, SIIs, and Ports .....	9
4.4	Case Factory Joints .....	9

## Table of Contents (Cont.)

<b><u>Section</u></b>	<b><u>Description</u></b>	<b><u>Page</u></b>
4.5	Insulation .....	11
4.5.1	NBR and Castable Inhibitor Debris .....	11
4.5.2	NBR Inhibitor Measurement .....	11
4.5.3	Igniter Insulation Measurement .....	11
<b>5.0</b>	<b>SPECIAL ISSUES SUMMARY .....</b>	<b>12</b>
5.1	Insulation .....	12
5.1.1	Internal Insulation .....	12
5.1.2	Igniter Insulation .....	12
5.2	Case, Seals, and Joints .....	12
5.2.1	Case .....	12
5.2.2	Seals .....	12
5.2.3	Joints .....	13
5.3	Nozzle .....	13
<b>APPENDIX A</b>	<b>POSTFLIGHT OBSERVATION RECORDS (PFORS)</b>	
<b>APPENDIX B</b>	<b>NOZZLE POSTFIRE DATA</b>	
<b>APPENDIX C</b>	<b>INSULATION POSTFIRE DATA</b>	

## List of Tables

<u>Table</u>	<u>Description</u>	<u>Page</u>
I	Summary of RSRM-32 Problems .....	2
II	Problem Summary for RSRM-32 .....	3
III	Flexible Boot Performance Margins of Safety .....	7
IV	Nozzle Phenolic Bondline Failure Mode Summary .....	8
V	Nozzle Char and Erosion Minimum Margins of Safety Summary ..	10
VI	Igniter Insulation Safety Adapter Factor Summary .....	11
VII	FEC Bondline Adhesive Thickness .....	17
VIII	Cowl Char and Erosion Measurement .....	18

## List of Acronyms

<u>Acronym</u>	<u>Definition</u>
CCP	Carbon Cloth Phenolic
CEI	Contract End Item
DR	Discrepancy Report
ECP	Engineering Change Proposal
ET	External Tank
GCP	Glass Cloth Phenolic
ID	Inside Diameter
IFA	In-Flight Anomaly
KSC	Kennedy Space Center
LDI	Low Density Indication
LH	Left Hand
NASA	National Aeronautics and Space Administration
OBR	Outer Boot Ring
OD	Outside Diameter
PEEP	Postflight Engineering Evaluation Plan
PFAR	Postfire Anomaly Record
PFOR	Postfire Observation Record
PR	Problem Report
RH	Right Hand
RSRM	Redesigned Solid Rocket Motor
RTV	Room Temperature Vulcanized (Rubber)
S&A	Safe and Arm Device
SCP	Silica Cloth Phenolic
SII	SRM Ignition Initiator
SPR	Significant Problem Report
STS	Space Transportation System
TWR	Thiokol Wasatch Report

## 1.0 INTRODUCTION

This document is the final report for the postflight assessment of the RSRM-32 (STS-57) flight set. This report presents the disassembly evaluations performed at the Thiokol facilities in Utah and is a continuation of the evaluations performed at KSC (TWR-64239).

The PEEP for this assessment is outlined in TWR-50051, Revision B. The PEEP defines the requirements for evaluating RSRM hardware. Special hardware issues pertaining to this flight set requiring additional or modified assessment are outlined in TWR-64237.

All observed hardware conditions were documented on PFORs which are included in Appendix A. Observations were compared against limits defined in the PEEP. Any observation that was categorized as Reportable or had no defined limits was documented on a Preliminary PFAR by the assessment engineers. Preliminary PFARs were reviewed by the Thiokol SPAT Executive Board to determine if elevation to PFARs was required.

## 2.0 REFERENCES

- CPW1-3600A Prime Equipment Contract End Item Detail Specification, Part I of Two Parts; Performance, Design, and Verification Requirements, Space Shuttle Redesigned Solid Rocket Motor CPW1-3600A For Space Shuttle Solid Rocket Motor Project, Operational Flight Motors (RSRM-4 and subsequent)
- TWA-1993 KSC and Clearfield Photo Log, RSRM-32 (STS-57)
- TWR-50050 KSC Postflight Engineering Evaluation Plan
- TWR-50051 Clearfield Postflight Engineering Evaluation Plan
- TWR-64237 Postflight Hardware Special Issues, RSRM-32 (STS-57), Clearfield
- TWR-64239 KSC Ten-Day Postflight Hardware Evaluation Report, RSRM-32 (STS-57)

### 3.0 EVALUATION SUMMARY

The engineering evaluation of the RSRM hardware showed that, in general, it performed as expected.

Table I provides a numerical summary of all postflight-related Squawks/Preliminary PFARs, PFARs, IFAs, and SPRs for RSRM-32.

Table I. RSRM-32 Summary				
	<u>Squawks/Prelim. PFARs</u>	<u>PFARs</u>	<u>IFAs</u>	<u>SPRs</u>
KSC	4	3	0	0
Clearfield	<u>2</u>	<u>2</u>	<u>0</u>	<u>0</u>
Total	6	5	0	0

Table II lists all RSRM-32 problems including Squawks and Preliminary PFARs that were not elevated to PFARs.

### 3.1 CEI Specification Compliance

Based on hardware evaluations, as defined in the KSC and Clearfield PEEPs, all CEI (CPW1-3600A) motor performance requirements were met.

### 4.0 HARDWARE ASSESSMENT RESULTS

This section outlines the significant observations from the postflight hardware evaluation at Thiokol's Utah facilities. The internal nozzle joints were disassembled on July 7-9, 1993 at the Clearfield H-6 facility. The S&As were disassembled on July 9, 1993 at Final Assembly's M-66A facility. The final factory joint demate occurred on October 25, 1993.

All observations were recorded on PFORs which provide a detailed checklist for hardware conditions. The completed PFORs can be found in Appendix A. Appendices B and C contain the measurements and safety factor data for the nozzle and insulation components, respectively.



Table II. Problem Summary for RSRM-32

PEAR/SQUAWK/ PRELIM. PFAR NUMBER	TYPE	ELEVATED FROM	SPR NUMBER	IFA NUMBER	EVALUATION LOCATION	COMPONENT	SPAT/ RPRB DATE	DESCRIPTION
57-010	SQUAWK	360T032B-01	N/A	N/A	KSC	JPS/TPS	06/30/93	FOREIGN MATERIAL ON IGNITER HEATER POWER CABLE CONNECTOR
57-011	SQUAWK	360T032A-02	N/A	N/A	KSC	CASE	06/30/93	MEDIUM CORROSION ON AFT DOME TANG SKIRT STUB
57-013	SQUAWK	N/A	N/A	N/A	KSC	NOZZLE	07/01/93	SCRATCHES ON FIXED HOUSING RADIAL BOLT HOLE SPOTFACE SEALING SURFACE
57-017	SQUAWK	360T032B-03	N/A	N/A	KSC	PORTS/PLUGS	07/07/93	SCRATCH & RAISED METAL ON SEALING SURFACE OF FWD FIELD JOINT
57C-01	PRELIM.	360T032A-04	N/A	N/A	H-5/H-7	NOZZLE	07/15/93	ADJUSTABLE VENT PORT PLUG (TOP PLUG)
57C-02	PRELIM.	360T032B-05	N/A	N/A	H-5/H-7	NOZZLE	07/09/93	GAS PATHS THROUGH RTV IN JOINT 2
57C-03	PRELIM.	N/A	N/A	N/A	H-5/H-7	CASE	10/01/93	AEC PLY LIFTING IN THE CCP
360T032B-01	PFAR	57-010	N/A	N/A	KSC	JPS/TPS	07/02/93	CORROSION/PITTING ON FORWARD DOME FACTORY JOINT TANG SEAL SURFACE
360T032A-02	PFAR	57-011	N/A	N/A	KSC	CASE	07/02/93	FOREIGN MATERIAL IN IGNITER HEATER POWER CABLE CONNECTOR
360T032B-03	PFAR	57-017	N/A	N/A	KSC	PORTS/PLUGS	07/08/93	CORROSION/PITTING ON AFT DOME SKIRT TANG (UNPAINTED REGION)
360T032A-04	PFAR	57C-01	N/A	N/A	H-5/H-7	NOZZLE	07/15/93	SCRATCH & RAISED METAL ON SEALING SURFACE OF FORWARD FIELD JOINT
360T032B-05	PFAR	57C-02	N/A	N/A	OTHER	NOZZLE	07/15/93	JOINT ADJUSTABLE VENT PORT TOP PLUG
								GAS PATHS THROUGH RTV IN JOINT 2
								AFT EXIT CONE PLY LIFTING IN CCP

#### 4.1 S&A Devices

(Reference PFORs A-1-to-A-2, A-65-to-A-66)

Both S&A devices were in good condition with no O-ring or seal surface damage observed. There was typical soot on the SII tips at both degree locations (18 and 198) for both S&As. There was typical sooting to the primary O-ring (No. 1) on both rotor shafts. There was additional sooting to the rotor and bore surfaces on the left side. There was also typical erosion and heat affect on the LH BB-to-basket and basket shower cap environmental O-rings.

#### 4.2 Nozzle

(Reference PFORs A-7, A-71)

##### 4.2.1 Nozzle Metal Components - Excluding Joints

All nozzle metal components were in good condition.

##### 4.2.2 Nozzle Internal Joints

##### 4.2.2.1 Nose Inlet-to-Flexible Bearing-to-Cowl (Joint 2)

(Reference PFORs A-8-to-A-12, A-72-to-A-76)

This is the first flight with back filled RTV in Joint 2.

LH

One anomalous condition was observed. Typical scalloped shaped soot was observed to the bolt hole circle intermittently full circumference. Soot reached the primary O-ring at two locations, 108-150 degrees and 306-330 degrees. Both locations corresponded to gas paths through the RTV. Preliminary PFAR 57C-01 was written on this condition. Soot did not go past the O-ring footprint. No O-ring or seal damage was observed. Traces of water were observed in the joint following demate.

The RTV backfill was below the char line over the full circumference to the nose inlet housing aft face. RTV did not reach the primary O-ring. Gas penetration into the joint was observed at 132.5 and 318 degrees. Heat affected paint, CCP and GCP/SCP was observed in the joint. Eroded GCP and adhesive was present at the gas path locations.

Typical corrosion was observed in the joint.

RH

The RTV backfill was below the char line over the full circumference to the nose inlet housing aft face. RTV did not reach the primary O-ring. No gas penetration into the joint was observed.

No O-ring or seal surface damage was observed.

Typical light-to-medium corrosion was observed intermittently full circumference upstream of primary O-ring between bolt holes.

No separations were observed on the cowl assembly or the nose inlet assembly.

#### 4.2.2.2 Nose Inlet-to-Throat (Joint 3)

(Reference PFORs A-13-to-A-17, A-77-to-A-81)

LH

The RTV backfill was below the char line over the full circumference. RTV did not reach the primary O-ring. No gas penetration into the joint was observed.

No O-ring or seal surface damage was observed.

Typical light corrosion was observed inboard of the primary O-ring intermittently full circumference.

Typical postburn bondline edge separations were observed on the forward end of the throat assembly. No separations were noted on the nose inlet assembly.

RH

The RTV backfill was below the char line over the full circumference. RTV did not reach the primary O-ring. No gas penetration into the joint was observed.

No O-ring or seal surface damage was observed.

Typical light corrosion was observed inboard of the primary O-ring intermittently full circumference.

Typical postburn bondline edge separations were observed on the forward end of the throat assembly. No separations were noted on the nose inlet assembly.

#### 4.2.2.3 Throat-to-Forward Exit Cone (Joint 4)

(Reference PFORs A-18-to-A-22, A-82-to-A-85)

LH

The RTV backfill was below the char line over the full circumference. RTV reached the primary O-ring intermittently around the circumference. No gas penetration into the joint was observed.

Light corrosion was observed on the forward exit cone housing secondary seal surface at 0-to-6 and 354 degrees. Medium-to-heavy corrosion observed on throat housing primary seal surface full circumference. This corrosion is splashdown related and is a nominal condition. No O-ring damage was observed.

Typical postburn bondline edge separations were observed on the throat assembly aft end and the forward exit cone forward end.

RH

The RTV backfill was below the char line over the full circumference. RTV reached the primary O-ring intermittently around the circumference. No gas penetration into the joint was observed.

No O-ring or seal surface damage was observed.

Typical postburn bondline edge separations were observed on the throat assembly aft end and the forward exit cone forward end.

No seal or joint anomalies were noted.

#### 4.2.2.4 Aft End Ring-to-Fixed Housing (Joint 5) (Reference PFORs A-23-to-A-28, A-86-to-A-91)

LH

The RTV coverage was nominal. The RTV extended forward to the aft end ring/bearing protector interface intermittently around the circumference. The RTV reached the primary O-ring at 290 degrees. Intermittent voids due to the assembly process were noted in the RTV. No gas penetration into the joint was observed.

Light corrosion was observed on the fixed housing sealing surfaces at 110 degrees. Missing paint and corrosion was observed on the aft end ring flange lip at 260 through 265 degrees. Seventy-one of the seventy-two Packings-with-Retainers had typical disassembly damage to the elastomer. No seal surface damage was observed. No O-ring damage was observed.

Typical postburn separations were observed.

RH

The RTV coverage was nominal. The RTV extended forward to the aft end ring/bearing protector interface intermittently around the circumference. The RTV reached the primary O-ring from 0-to-70 and 185-to-255 degrees. Intermittent voids due to the assembly process were noted in the RTV. No gas penetration into the joint was observed.

No anomalous conditions were observed. Medium-to-heavy corrosion observed on the aft end ring flange lip full circumference. All seventy-two Packings-with-Retainers had typical disassembly damage to the elastomer. No seal surface damage was observed. No O-ring damage was observed.

Typical postburn separations were observed.

#### 4.2.3 Cowl Insulation Segments (Reference PFORs A-29, A-92)

The LH and RH cowl insulation segments were in nominal condition and showed typical failure modes at removal.

#### 4.2.4 Flexible Bearing Protector, Flexible Bearing, and Flexible Boot (Reference PFORs A-30-to-A-31, A-93-to-A-94)

##### 4.2.4.1 Flexible Bearing Protector

Both flexible bearing protectors were in nominal condition. No burn-through or abnormal heat effects were observed.

##### 4.2.4.2 Flexible Bearing

Both flexible bearings were in good condition. No heat effects were observed.

##### 4.2.4.3 Flexible Boot

The performance of the flexible boots was nominal. The flexible boot remaining plies and margins of safety are summarized in Table III.

**Table III. Flexible Boot Performance Margins of Safety**

Degree Location	Left Hand			Right Hand		
	Remaining Plies	Maximum Affected Depth (in.)	Margin of Safety	Remaining Plies	Maximum Affected Depth (in.) *	Margin of Safety
0	3.7	1.17	0.42	3.1	1.37	0.21
90	3.2	1.34	0.24	3.2	1.34	0.24
180	3.5	1.24	0.34	3.4	1.27	0.31
270	3.1	1.37	0.21	3.1	1.37	0.21

#### 4.2.5 Nozzle Throat Diameter Measurement (Reference PFORs A-32, A-95)

The average LH nozzle postfire throat diameter was 55.867 inches (erosion rate of 8.23 mils/sec based on an action time of 122.0 sec). The average RH nozzle postfire throat diameter was 55.925 inches (erosion rate of 8.47 mils/sec based on an action time of 121.9 sec). RSRM postfire throat diameters have ranged from 55.787 to 56.072 inches.

#### 4.2.6 Nozzle Phenolic Bondlines

(Reference PFORs A-33-to-A-39, A-96-to-A-102)

All bondlines were in good condition. Primary, secondary and total bondline failure modes are recorded in Table IV. Typical adhesive voids were observed in all bondlines.

**Table IV. Nozzle Phenolic Bondline Failure Mode\* Summary**

	Metal-to-Adhesive			Within Adhesive			Adhesive-to-GCP/SCP			Within GCP/SCP			GCP/SCP-to-CCP			Within CCP		
	P	S	T	P	S	T	P	S	T	P	S	T	P	S	T	P	S	T
Aft Exit Cone, LH	13	—	13	—	—	—	—	—	—	87	—	87	—	—	—	—	—	—
Aft Exit Cone, RH	1	—	1	—	—	—	—	—	—	99	—	99	—	—	—	—	—	—
Fwd Exit Cone, LH	61	—	61	—	—	—	39	—	39	—	—	—	—	—	—	—	—	—
Fwd Exit Cone, RH	33	—	33	—	—	—	67	—	67	—	—	—	—	—	—	—	—	—
Throat Assembly, LH	100	—	100	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
Throat Assembly, RH	99.6	—	99.6	—	—	—	0.4	—	0.4	—	—	—	—	—	—	—	—	—
Nose Inlet Rings, LH	90	—	90	—	—	—	10	—	10	—	—	—	—	—	—	—	—	—
Nose Inlet Rings, RH	96	—	96	—	—	—	4	—	4	—	—	—	—	—	—	—	—	—
Nose Cap, LH	—	36	36	—	—	—	—	64	64	—	—	—	100	—	—	—	—	—
Nose Cap, RH	—	39	39	—	—	—	—	61	61	—	—	—	100	—	—	—	—	—
Cowl, LH	4	—	4	—	—	—	95.4	—	95.4	0.6	—	—	—	—	—	—	—	—
Cowl, RH	14	—	14	—	—	—	85.5	—	85.5	0.5	—	—	—	—	—	—	—	—
Fixed Housing, LH	—	0.25	0.25	—	—	—	—	99.75	99.75	100	—	—	—	—	—	—	—	—
Fixed Housing, RH	—	1	1	—	—	—	—	99	99	100	—	—	—	—	—	—	—	—

P = Primary  
S = Secondary  
T = Total

\* All failure modes are expressed as percentages of the total bondline.

##### 4.2.6.1 Ultrasonic Inspection of Fixed Housing Assemblies

Ultrasonic inspection did not detected any large unbonds on either LH or RH assemblies. Several very small indications were detected. The smaller ultrasonic indications could not be verified during bondline assessment.

#### 4.2.7 Nozzle Phenolic Sections

(Reference PFORs A-40-to-A-47, A-103-to-A-110)

Char and erosion margins of safety are summarized in Table V. Measurement stations that contain an "N/A" means that data was not available due to missing material. The LH aft exit cone liner was not recovered and therefore is not included. A small portion of the RH aft exit cone was recovered and measurement were taken. All stations showed positive margins of safety. The char and erosion data tables for each component liner can be found in Appendix B. The RH aft exit cone had evidence of ply lifting in the CCP. Preliminary PFAR 57C-02 was written on this condition.

#### 4.3 Leak Check Port Plugs, SII's, and Ports

(Reference PFORs A-3-to-A-6, A-48-to-A-57; A-67-to-A-70, A-111-to-A-116)

A hair-like fiber was found on the leak check plug shoulder seal (right side (B), 126 degrees). This fiber was photographed and removed for analysis. It was later determined by those present that this fiber was a result of disassembly

No anomalous conditions were observed on any of the internal nozzle joint leak check ports, plugs, or O-rings.

#### 4.4 Case Factory Joints

(Reference PFORs A-58-to-A-64, A-121-to-A-127)

A combination of chemlock and corrosion was present on the sealing surface of the RH forward dome factory joint at 119, 186 and 297 degrees. Upon removal of the corrosion with scotchbrite, pitting was present from one to seven mils in depth. Preliminary PFAR 57C-03 was written on this condition.

All other factory joints were in good condition with no O-ring heat effect or erosion observed.

**Table V. Nozzle Char and Erosion Minimum Margins of Safety Summary**

Hardware	Stations*												
Forward Exit Cone, LH	1 0.30	4 0.26	4.6 0.22	8 0.22	12 0.12	16 N/A	20 N/A	24 N/A	28 0.07	32 0.20	32.9 0.27	34 0.33	
Forward Exit Cone, RH	1 N/A	4 N/A	4.6 N/A	8 N/A	12 N/A	16 N/A	20 N/A	24 N/A	28 N/A	32 N/A	32.9 N/A	34 N/A	
Throat Assembly, LH	1 0.15	2 0.13	4 0.11	6 0.08	8 0.04	10 0.18	12 0.23	14 0.27	16 0.31	18 0.33	20 0.39	22 0.39	23 0.21
Throat Assembly, RH	1 0.13	2 0.11	4 0.11	6 0.07	8 0.04	10 0.11	12 0.20	14 0.24	16 0.28	18 0.37	20 0.42	22 0.38	23 0.22
Nose Inlet Rings, LH	28 0.15	30 0.32	32 0.12	34 0.36	36 0.31	38 0.15	39 0.12						
Nose Inlet Rings, RH	28 0.15	30 0.28	32 0.17	34 0.35	36 0.33	38 0.21	39 0.15						
Nose Cap, LH	1.5 0.64	4 0.59	6 0.67	8 0.65	10 0.68	12 0.72	14 0.68	16 0.63	18 0.51	20 0.44	22 0.12	24 0.02	26 0.06
Nose Cap, RH	1.5 0.54	4 0.50	6 0.84	8 0.79	10 0.88	12 0.88	14 0.77	16 0.76	18 0.52	20 0.42	22 0.12	24 0.01	26 0.08
Cowl/OBR, LH	0.3 0.03	1 0.14	2 0.28	3 0.41	4 0.58	5 0.53	6 0.68	6.8 0.43	8 0.22	9 0.30	10 0.42	11.3 0.37	
Cowl/OBR, RH	0.3 0.06	1 0.13	2 0.19	3 0.39	4 0.49	5 0.60	6 0.59	6.8 0.40	8 0.22	9 0.32	10 0.35	11.3 0.41	
Fixed Housing, LH	0 1.80	1 0.72	2 0.60	3 0.62	4 0.66	5 0.71	6 0.67	7 0.76	8 0.97	9 1.61	10.75 0.62		
Fixed Housing, RH	0 2.43	1 0.84	2 0.69	3 0.62	4 0.78	5 0.71	6 0.74	7 0.83	8 1.00	9 2.37	10.75 0.55		
Aft Exit Cone, LH	84 N/A	90 N/A	96 N/A	102 N/A	108 N/A	114 N/A	119 N/A						
Aft Exit Cone, RH	84 N/A	90 N/A	96 N/A	102 0.15	108 0.03	114 0.26	119 N/A						

\* Station locations are shown in bold with the respective margin of safety shown below.



#### 4.5 Insulation

As specified in the Clearfield PEEP, insulation measurements and inspections were not taken on the RSRM-32 motors internal insulation. Insulation measurements were taken on the LH and RH igniter adapters and can be found in Table 6.

##### 4.5.1 NBR and Castable Inhibitor Debris

No significant NBR or castable inhibitor debris was found during the internal inspection at KSC.

##### 4.5.2 NBR Inhibitor Measurement

All NBR inhibitor thickness measurements were taken and added to the database. The data is summarized in Appendix C.

##### 4.5.3 Igniter Adapter Insulation Measurement

Igniter adapter insulation safety factors are summarized in Tables NO TAGI. All required safety factors were met.

**Table VI. Igniter Adapter Insulation Safety Factor Summary**

<u>Description</u>	<u>Minimum Compliance Safety Factor*</u>	<u>Station</u>	<u>Degree Location</u>	<u>Minimum Actual Safety Factor*</u>	<u>Station</u>	<u>Degree Location</u>
LH Adapter	3.05	11	150.0	3.65	11	150.0
RH Adapter	3.03	11	270.0	3.62	11	270.0

\* Minimum required safety factor of 1.5 for the adapter acreage.

## 5.0 SPECIAL ISSUES SUMMARY

Special postflight hardware issues were identified based on preflight conditions documented in DRs, PRs, ECPs, IFAs, or by anomalous conditions observed in the evaluation of previous flight motors. The following section outlines, by component, the condition and postflight assessment results for the special issues identified on this flight set (reference TWR-64237).

### 5.1 Insulation

#### 5.1.1 Internal Insulation

- 1. Condition:** The RH nozzle-to-case joint flap thickness on the aft segment was identified to be below the minimum requirement intermittently over the full circumference. No repair was made on this condition.

**Reference:** DR 409141-01

**Results:** The Clearfield planning failed to include the action for this special issue and the RH aft segment was rinsed out prior to a sample of the joint flap being removed. No results were obtained.

#### 5.1.2 Igniter Insulation

There are no Clearfield Special Issues for the igniter insulation component on this flight set.

### 5.2 Case, Seals, and Joints

#### 5.2.1 Case

- 1. Condition:** During splashdown/recovery, debris strikes the case segment interior insulation. Impacts have been observed to cut through the insulation to the case exposing bare metal. This results in corrosive pitting on the case ID at these impact regions. This is suspected to be tied into "spider pitting."

**Reference:** PFAR 360T030B-10

**Results:** This evaluation was not performed. The "spider pitting" team determined that the information would not meet the report deadline and therefore canceled the request for the data.

#### 5.2.2 Seals

There are no Clearfield Special Issues for the Seals component on this flight set.

### 5.2.3 Joints

There are no Clearfield Special Issues for the Joints component on this flight set.

### 5.3 Nozzle

#### 1. Condition:

The LH Joint 4 primary O-ring groove in the GCP exceeds the depth requirements by 0.008 inch at 90 and 270 degrees.

**Reference:** DR 413107-01

**Results:** No abnormal conditions observed in the Joint 4 O-ring groove. Performance was nominal with the deeper groove at 90 and 270 degrees.

**2. Condition:** The LH inner boot ring has wetline indications on the forward end at 2-to-9.5, 13-to-16, 323-to-327 and 333-to-337 degrees. These indications are approximately 0.05 inch outboard of the bondline.

**Reference:** DR 410998-01

**Results:** There was no sign of growth in the wetline areas.

**3. Condition:** Part of the improvement to the Joint 2 assembly method is the complete bonding of the cowl segments to the cowl housing and cowl SCP.

**Reference:** ECP SRM-2756, STS-57 FRRT, page 91

**Results:** No unbonds or anomalous conditions were observed on either LH or RH cowl segments.

**4. Condition:** Part of the improvement to the Joint 2 assembly method is the changing from the "butter" application of the RTV to the backfill method of applying the RTV.

**Reference:** ECP SRM-2756, STS-57 FRRT, page 91

**Results:** The RTV backfill reached the nose inlet aft end surface on both LH and RH joints. Two gas paths were observed in the LH joint. One gas path was located 318 degrees. Soot entered the joint and extended to the primary O-ring at 306-to-330 degrees. Charred CCP, GCP and SCP were observed below the char line. Eroded GCP was observed with a maximum depth of 0.003 inch. Heat affected paint was present on forward end ring flange OD. The gas path at 132 was located at a RTV repair and is discussed in Special

Issue 5. Intermittent encapsulated voids with maximum diameter of 0.10 inch were present in the LH joint.

One large encapsulated void was present in the RH joint. The void measured 0.39 inch circumferential by 0.775 inch radial and was located at 354 degrees. This void was located at a RTV repair location. The repair depth was great enough to assure that the RTV was below the char line at this location.

- 5. Condition:** LDI present in the LH Joint 2 RTV located at 133.5 degrees and measuring 0.150 inch circumferentially by 1.625 inches radially. It was repaired by injecting RTV into it.

**Reference:** DR 410545-02

**Results:** A gas path was observed at 132 degrees at the RTV repair. Soot entered the joint and extended to the primary O-ring at 108-to-150-degrees. Charred CCP, GCP and SCP were observed below the char line. Eroded GCP was observed with a maximum depth of 0.006 inch. Heat affected paint was present on forward end ring flange OD. This was the first joint to have a RTV repair.

- 6. Condition:** The RH bearing protector has nine voids that were repaired by filling the voids with silicone paste compound per process finalization procedures.

**Reference:** Insulation Work Center

**Results:** No abnormal conditions observed at the repair locations.

- 7. Condition:** Nozzle Work Center Design Engineering (NWCDE) is gathering data relating to the correlation of bondline voids and LDIs. Evaluation of the cowl, nose cap and forward nose ring is needed for both the LH and RH nozzles.

**Reference:** Nozzle Work Center

**Results:** Nine adhesive voids were documented on the LH forward nose ring-to-nose inlet housing bondline. Five adhesive voids were documented on the LH nose cap-to-nose inlet housing bondline. No pit repair locations were documented on the LH nose inlet bondlines. No adhesive voids or pit repair locations were documented on the LH cowl bondlines.

Two adhesive voids were documented on the RH forward nose ring-to-nose inlet housing bondline. Four adhesive voids were documented on the RH nose cap-to-nose inlet housing bondline. No pit repair locations were documented on the RH nose inlet bondlines. No adhesive voids or pit repair locations were documented on the RH cowl bondlines.

- 8. Condition:** LDIs in LH nose cap-to-forward nose ring interface at 19, 20, 27, 48, 131, 132, 149, 150, 157, 283, 299, 306 and 314 degrees.

**Reference:** DRs 410535-01 and 410545-01

**Results:** Adhesive voids were documented near the LDI locations at 27, 48, 131, 132, 149, 157, 283, 299 and 306 degrees. No indications of the LDIs were found at 19, 20, 150 and 314 degrees.

- 9. Condition:** LDIs in the nose cap-to-nose inlet housing bondline at 1, 16, 33, 79, 163, 177 and 316 degrees.

**Reference:** DRs 410535-02 and 410545-03

**Results:** Adhesive voids were documented near the LDI locations at 1, 163, 177, and 316 degrees. No indications of the LDIs were found at 16, 33, and 79 degrees.

- 10. Condition:** LDIs in the LH forward nose ring-to-nose inlet housing bondline. The two worst cases are located at 110 and 290 degrees on the forward end of the nose inlet housing.

**Reference:** DR 410535-03

**Results:** No indications of the LDIs were found. X-Ray assessment of the forward nose ring sections for LDIs was not performed.

- 11. Condition:** LDIs in the RH nose cap-to-nose inlet housing bondline at 32, 128, 145, 212 and 245 degrees.

**Reference:** DRs 410536-01 and 413901-01

**Results:** Adhesive voids were documented near the LDI locations at 1, 163, 177 and 316 degrees. No indications of the LDIs were found at 16, 33 and 79 degrees.

- 12. Condition:** LDIs in the RH nose cap-to-forward nose ring interface at 182 degrees.

**Reference:** DRs 410536-02 and 413901-03

**Results:** No indications of the LDI was found.

- 13. Condition:** Part of the improvement to the Joint 2 assembly method is bonding of the cowl housing and the cowl SCP before joint assembly.

**Reference:** ECP SRM-2756, STS-57 FRRT, page 91

**Results:** The amount of metal-to-adhesive separation was much lower than previous cowl bondlines (typically 100 percent metal-to-adhesive). The metal-to-adhesive separations were 4 percent and 14 percent for the LH and RH, respectively.

- 14. Condition:** LDIs in the RH aft exit cone GCP from 270-to-277 degrees and approximately 37.0 inches from the forward end. The LDI measures 4.0 inches axially by 7.97 inches circumferentially.

**Reference:** DR 410567-01

**Results:** This Special Issues was written for the aft exit cone assembly originally assigned to this flight. There was switch-out of the RH aft exit cone assembly. The original assembly was returned to Thiokol. This Special Issue will be performed when this assembly is flown. The aft exit cone assembly with DR 410567 is scheduled to flight on RSRM-38B.

- 15. Condition:** The LH aft exit cone assembly experienced an out-of-family temperature condition of 111 degrees during in-plant transportation.

**Reference:** TWR-64976, S&MA Preflight Assessment, page 63

**Results:** No abnormal bondline separation modes observed.

- 16. Condition:** The LH forward exit cone assembly experienced an out-of-family bondline shim-to-coeflex differential (i.e. bondline thickness smaller than the shim).

**Reference:** TWR-64976, S&MA Preflight Assessment, page 66

**Results:** The bondline separation was typical of past forward exit cones. The bondline separated 61 percent metal-to-adhesive and 39 percent adhesive-to-GCP.

The shims appeared to uniform in thickness and were measured in on location. The adjacent adhesive thickness was also measured.

**Table VII. FEC Bondline Adhesive Thickness**

Degree	Bondline Location of Shim	Shim Thickness	Adjacent Adhesive Thickness
0	fwd	0.063	0.063
0	aft	0.065	0.060
45	fwd	0.064	0.074
45	aft	0.065	0.062
90	fwd	0.062	0.061
90	aft	0.062	0.063
135	fwd	0.064	0.075
135	aft	0.063	N/A
180	fwd	0.062	0.061
180	aft	0.065	0.062
225	fwd	0.063	0.069
225	aft	0.065	0.065
270	fwd	0.063	0.060
270	aft	0.062	0.066

**17. Condition:** The cowl ply angle has been changed from 0 degrees to -50 degrees on both the LH and RH cowls.

**Reference:** ECP SRM-2674, STS-57 FRRT, page 94

**Results:** Erosion and char measurements were completed and are comparable to the -50 degree ply angle full RSRM static test cowl measurements (FSM-02 and FSM-03). All margin of safety calculations were positive.

**Table VIII. Cowl Char and Erosion Measurements**

		RSRM-32A		RSRM-32B		FSM-02		FSM-03	
Station		Max	Min	Max	Min	Max	Min	Max	Min
0.3	Erosion	0.31	0.28	0.29	0.24	0.37	0.23	0.35	0.23
	Char	0.72	0.78	0.73	0.73	0.63	0.67	0.61	0.67
1.0	Erosion	0.32	0.26	0.30	0.23	0.35	0.22	0.35	0.22
	Char	0.66	0.70	0.73	0.71	0.57	0.62	0.60	0.62
2.0	Erosion	0.27	0.22	0.30	0.24	0.26	0.16	0.36	0.16
	Char	0.69	0.67	0.72	0.72	0.58	0.67	0.57	0.67
3.0	Erosion	0.26	0.20	0.25	0.21	0.27	0.14	0.33	0.14
	Char	0.65	0.66	0.65	0.76	0.60	0.69	0.58	0.69
4.0	Erosion	0.24	0.18	0.24	0.20	0.24	0.13	0.30	0.13
	Char	0.62	0.72	0.68	0.75	0.61	0.69	0.64	0.69
5.0	Erosion	0.20	0.18	0.19	0.17	0.23	0.11	0.23	0.11
	Char	0.78	0.69	0.73	0.77	0.62	0.72	0.67	0.72
6.0	Erosion	0.16	0.14	0.17	0.15	0.21	0.13	0.20	0.13
	Char	0.70	0.76	0.69	0.80	0.59	0.75	0.82	0.75
6.8	Erosion	0.25	0.15	0.20	0.12	NA	NA	NA	NA
	Char	0.82	0.87	0.91	0.84	NA	NA	NA	NA

**18. Condition:** The RH aft exit cone is the first component to fly with NARC CCP.

**Reference:** ECP SRM-1999R2, STS-57 FRRT, page 97


**Results:** The remaining sections of CCP attached to the housing were measured. Ply lifting was observed the full circumference and axial length of the recovered CCP. All margins of safety calculations were positive. The ply lifted region was included in the char measurements. The ply lift investigation is summarized in TWR-65606, "HPM/RSRM Aft Exit Cone Ply Lift Summary".



**19. Condition:** The LH aft exit cone CCP has high interlaminar double shear strength. This CCP material was dispositioned "limited use" after this AEC was manufactured. The LH AEC was then stored until the TEM-09 AEC with similar material properties was fired and performed nominally. This AEC was then dispositioned "use as is".

**Reference:** DRs 402834-01 and 409214-01

**Results:** Several sections of CCP were recovered from the inside of the LH motor. Sections were shipped to the Clearfield facility. The sections were misplaced at Clearfield and the assessment cannot be completed.



## **Appendix A**

### **Postflight Observation Records (PFORs)**

## **Final Postflight Hardware Evaluation Report**

### **RSRM-32 (STS-57)**

**November 1993**

**Prepared for:**

**NATIONAL AERONAUTICS AND SPACE ADMINISTRATION  
GEORGE C. MARSHALL SPACE FLIGHT CENTER  
MARSHALL SPACE FLIGHT CENTER, ALABAMA 35812**

<b>Contract No.</b>	<b>NAS8-38100</b>
<b>DR No.</b>	<b>4-23</b>
<b>WBS No.</b>	<b>4C601-04-01</b>
<b>ECS No.</b>	<b>SS4775</b>

***Thiokol* CORPORATION**  
**SPACE OPERATIONS**

**P.O. Box 707, Brigham City, Utah 84302-0707 (801) 863-3511**

## REQUIRED PFOR LIST

<u>PFOR</u>	<u>Side</u>	Final Ten-Day Report Page <u>Number</u>
S&A Device (Barrier-Booster and Environmental Seal Regions)	LH	A-1
S&A Rotor Shaft O-rings (Detailed)	LH	A-2
SII and Port (At Removal) - 18 Degrees	LH	A-3
SII and O-rings (Detailed) - 18 Degrees	LH	A-4
SII and Port (At Removal) - 198 Degrees	LH	A-5
SII and O-rings (Detailed) - 198 Degrees	LH	A-6
Nozzle Metal Components - Excluding Joints	LH	A-7
Nozzle Internal Joint 2 (Nose Inlet-to-Flex Bearing-to-Cowl)		
Nozzle Internal Joint RTV - Joint 2	LH	A-8
Nozzle Internal Joint Phenolics - Joint 2	LH	A-9
Nozzle Internal Joint Seals and Metal - Joint 2	LH	A-10
Nozzle Internal Joint Drawing Worksheet - Joint 2	LH	A-11
Nozzle Internal Joint O-rings (Detailed) - Joint 2	LH	A-12
Nozzle Internal Joint 3 (Nose Inlet-to-Throat)		
Nozzle Internal Joint RTV - Joint 3	LH	A-13
Nozzle Internal Joint Phenolics - Joint 3	LH	A-14
Nozzle Internal Joint Seals and Metal - Joint 3	LH	A-15
Nozzle Internal Joint Drawing Worksheet - Joint 3	LH	A-16
Nozzle Internal Joint O-rings (Detailed) - Joint 3	LH	A-17
Nozzle Internal Joint 4 (Throat-to-Forward Exit Cone)		
Nozzle Internal Joint RTV - Joint 4	LH	A-18
Nozzle Internal Joint Phenolics - Joint 4	LH	A-19
Nozzle Internal Joint Seals and Metal - Joint 4	LH	A-20
Nozzle Internal Joint Drawing Worksheet - Joint 4	LH	A-21
Nozzle Internal Joint O-rings (Detailed) - Joint 4	LH	A-22



# REQUIRED PFOR LIST

<u>PFOR</u>	<u>Side</u>	<u>Final Ten-Day Report Page Number</u>
<b>Nozzle Phenolic Sections</b>		
Nozzle Phenolic Sections - Aft Exit Cone	LH	A-40
Nozzle Phenolic Sections - Forward Exit Cone	LH	A-41
Nozzle Phenolic Sections - Throat Assembly	LH	A-42
Nozzle Phenolic Sections - Forward Nose and Aft Inlet Rings	LH	A-43
Nozzle Phenolic Sections - Nose Cap	LH	A-44
Nozzle Phenolic Sections - Cowl	LH	A-45
Nozzle Phenolic Sections - Fixed Housing	LH	A-46
Nozzle Phenolic Sections - Outer Boot Ring and Flexible Boot	LH	A-47
<b>Leak Check Port Plugs and Ports</b>		
Barrier-Booster Leak Check Port Plug and Port (At Removal) - 126 Degrees	LH	A-48
Barrier-Booster Leak Check Port Plug and O-ring (Detailed) - 126 Degrees	LH	A-49
Nozzle Internal Joint Leak Check Port Plug and Port (At Removal) - Joint 2	LH	A-50
Nozzle Internal Joint Leak Check Port Plug and O-ring (Detailed) - Joint 2	LH	A-51
Nozzle Internal Joint Leak Check Port Plug and Port (At Removal) - Joint 3	LH	A-52
Nozzle Internal Joint Leak Check Port Plug and O-ring (Detailed) - Joint 3	LH	A-53

## REQUIRED PFOR LIST

<u>PFOR</u>	<u>Side</u>	<u>Final Ten-Day Report Page Number</u>
Leak Check Port Plugs and Ports (Cont.)		
Nozzle Internal Joint Leak Check Port Plug and Port (At Removal) - Joint 4	LH	A-54
Nozzle Internal Joint Leak Check Port Plug and O-ring (Detailed) - Joint 4	LH	A-55
Nozzle Internal Joint Leak Check Port Plug and Port (At Removal) - Joint 5	LH	A-56
Nozzle Internal Joint Leak Check Port Plug and O-ring (Detailed) - Joint 5	LH	A-57
Case Factory Joints		
Case Factory Joint - Forward Dome	LH	A-58
Case Factory Joint - Forward Cylinder/Cylinder	LH	A-59
Case Factory Joint - Forward Center	LH	A-60
Case Factory Joint - Aft Center	LH	A-61
Case Factory Joint - ET Attach/Stiffener	LH	A-62
Case Factory Joint - Stiffener/Stiffener	LH	A-63
Case Factory Joint - Aft Dome	LH	A-64
S&A Device (Barrier-Booster and Environmental Seal Regions)	RH	A-65
S&A Rotor Shaft O-rings (Detailed)	RH	A-66
SII and Port (At Removal) - 18 Degrees	RH	A-67
SII and O-rings (Detailed) - 18 Degrees	RH	A-68
SII and Port (At Removal) - 198 Degrees	RH	A-69
SII and O-rings (Detailed) - 198 Degrees	RH	A-70
Nozzle Metal Components - Excluding Joints	RH	A-71

REQUIRED PFOR LIST (Cont.)

<u>PFOR</u>	<u>Side</u>	<u>Final Ten-Day Report Page Number</u>
Nozzle Internal Joint 2 (Nose Inlet-to-Flex Bearing-to-Cowl)		
Nozzle Internal Joint RTV - Joint 2	RH	A-72
Nozzle Internal Joint Phenolics - Joint 2	RH	A-73
Nozzle Internal Joint Seals and Metal - Joint 2	RH	A-74
Nozzle Internal Joint Drawing Worksheet - Joint 2	RH	A-75
Nozzle Internal Joint O-rings (Detailed) - Joint 2	RH	A-76
Nozzle Internal Joint 3 (Nose Inlet-to-Throat)		
Nozzle Internal Joint RTV - Joint 3	RH	A-77
Nozzle Internal Joint Phenolics - Joint 3	RH	A-78
Nozzle Internal Joint Seals and Metal - Joint 3	RH	A-79
Nozzle Internal Joint Drawing Worksheet - Joint 3	RH	A-80
Nozzle Internal Joint O-rings (Detailed) - Joint 3	RH	A-81
Nozzle Internal Joint 4 (Throat-to-Forward Exit Cone)		
Nozzle Internal Joint Phenolics - Joint 4	RH	A-82
Nozzle Internal Joint Seals and Metal - Joint 4	RH	A-83
Nozzle Internal Joint Drawing Worksheet - Joint 4	RH	A-84
Nozzle Internal Joint O-rings (Detailed) - Joint 4	RH	A-85
Nozzle Internal Joint 5 (Aft End Ring-to-Fixed Housing)		
Nozzle Internal Joint RTV - Joint 5	RH	A-86
Nozzle Internal Joint Phenolics - Joint 5	RH	A-87
Nozzle Internal Joint Seals and Metal - Joint 5	RH	A-88
Nozzle Internal Joint Drawing Worksheet - Joint 5	RH	A-89
Nozzle Internal Joint O-rings (Detailed) - Joint 5	RH	A-90
Nozzle Internal Joint Packings With Retainers (Detailed) - Joint 5	RH	A-91

REQUIRED PFOR LIST (Cont.)

<u>PFOR</u>	<u>Side</u>	<u>Final Ten-Day Report Page Number</u>
Cowl Insulation Segments	RH	A-92
Flexible Bearing Protector, Flexible Bearing, and Flexible Boot	RH	A-93
Flexible Bearing Protector Measurements	RH	A-94
Nozzle Throat Diameter Measurements	RH	A-95
Nozzle Phenolic Bondlines		
Nozzle Phenolic Bondline - Aft Exit Cone Assembly	RH	A-96
Nozzle Phenolic Bondline - Forward Exit Cone Assembly	RH	A-97
Nozzle Phenolic Bondline - Throat Assembly	RH	A-98
Nozzle Phenolic Bondline - Forward Nose and Aft Inlet Rings	RH	A-99
Nozzle Phenolic Bondline - Nose Cap	RH	A-100
Nozzle Phenolic Bondline - Cowl Assembly	RH	A-101
Nozzle Phenolic Bondline - Fixed Housing Assembly	RH	A-102
Nozzle Phenolic Sections		
Nozzle Phenolic Sections - Aft Exit Cone	RH	A-103
Nozzle Phenolic Sections - Forward Exit Cone	RH	A-104
Nozzle Phenolic Sections - Throat Assembly	RH	A-105
Nozzle Phenolic Sections - Forward Nose and Aft Inlet Rings	RH	A-106
Nozzle Phenolic Sections - Nose Cap	RH	A-107
Nozzle Phenolic Sections - Cowl	RH	A-108
Nozzle Phenolic Sections - Fixed Housing	RH	A-109
Nozzle Phenolic Sections - Outer Boot Ring and Flexible Boot	RH	A-110



REQUIRED PFOR LIST

<u>PFOR</u>	<u>Side</u>	<u>Final Ten-Day Report Page Number</u>
Leak Check Port Plugs and Ports		
Barrier-Booster Leak Check Port Plug and Port (At Removal) - 126 Degrees	RH	A-111
Barrier-Booster Leak Check Port Plug and O-ring (Detailed) - 126 Degrees	RH	A-112
Nozzle Internal Joint Leak Check Port Plug and Port (At Removal) - Joint 2	RH	A-113
Nozzle Internal Joint Leak Check Port Plug and O-ring (Detailed) - Joint 2	RH	A-114
Nozzle Internal Joint Leak Check Port Plug and Port (At Removal) - Joint 3	RH	A-115
Nozzle Internal Joint Leak Check Port Plug and O-ring (Detailed) - Joint 3	RH	A-116
Leak Check Port Plugs and Ports (Cont.)		
Nozzle Internal Joint Leak Check Port Plug and Port (At Removal) - Joint 4	RH	A-117
Nozzle Internal Joint Leak Check Port Plug and O-ring (Detailed) - Joint 4	RH	A-118
Nozzle Internal Joint Leak Check Port Plug and Port (At Removal) - Joint 5	RH	A-119
Nozzle Internal Joint Leak Check Port Plug and O-ring (Detailed) - Joint 5	RH	A-120

REQUIRED PFOR LIST

<u>PFOR</u>	<u>Side</u>	Final Ten-Day Report Page <u>Number</u>
Case Factory Joints		
Case Factory Joint - Forward Dome	RH	A-121
Case Factory Joint - Forward Cylinder/Cylinder	RH	A-122
Case Factory Joint - Forward Center	RH	A-123
Case Factory Joint - Aft Center	RH	A-124
Case Factory Joint - ET Attach/Stiffener	RH	A-125
Case Factory Joint - Stiffener/Stiffener	RH	A-126
Case Factory Joint - Aft Dome	RH	A-127

POSTFLIGHT OBSERVATION RECORD (PFOR)  
S&A Device (Barrier-Booster and Environmental Seal Regions)

Motor No.: RSRM-32	Side: Left (A)	Date: 7-9-93
Assessment Engineer(s)/Inspector(s): <u>S. Eden, M. Nolan, M. Lyon, L. McCauley</u>		
<b>Barrier-Booster Bore and Rotor:</b>		
	Yes	No
a. Soot to or past O-rings?	<input checked="" type="checkbox"/>	<input type="checkbox"/>
b. Sooted metal surfaces?	<input checked="" type="checkbox"/>	<input type="checkbox"/>
c. Heat affected or eroded O-ring (installed)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
d. O-ring damage (installed)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
e. Foreign material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
f. Heat affected or eroded metal?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
g. Metal damage?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
h. Excessive grease?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
i. Corrosion?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
j. Teflon retainer damage?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
<b>Environmental Seal Regions:</b>		
k. Environmental O-ring assembly damage (visible without magnification)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
l. Foreign material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
<p>Notes / Comments</p> <p>1- Typical soot to primary O-ring(#1) and rotor and bore surfaces.</p> <p>Note: slight heat affect and erosion on both the B-B-to-basket and basket shower cap environmental O-rings. (Typical condition)</p>		
Preliminary PFAR(s)? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No      Preliminary PFAR Number(s): _____ Clarification Form(s)? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No      Number of Forms Attached: _____		

POSTFLIGHT OBSERVATION RECORD (PFOR)  
S&A Rotor Shaft O-rings (Detailed)

Motor No.: RSRM-32	Side: Left (A)	Date: 7-9-93																																				
Assessment Engineer(s)/Inspector(s): S. Eden, M. Lyon, C. Taylor, L. MacCauley																																						
<p><u>Forward Primary O-ring: #2</u></p> <table style="width: 100%;"> <thead> <tr> <th style="width: 60%;"></th> <th style="width: 10%;">Yes</th> <th style="width: 10%;">No</th> <th style="width: 20%;">Comment #</th> </tr> </thead> <tbody> <tr> <td>a. Heat affected or eroded O-ring?</td> <td style="text-align: center;">_____</td> <td style="text-align: center;">✓ _____</td> <td>_____</td> </tr> <tr> <td>b. O-ring defects/damage?</td> <td style="text-align: center;">_____</td> <td style="text-align: center;">✓ _____</td> <td>_____</td> </tr> </tbody> </table> <p><u>Aft Primary O-ring: #1</u></p> <table style="width: 100%;"> <tbody> <tr> <td>c. Heat affected or eroded O-ring?</td> <td style="text-align: center;">_____</td> <td style="text-align: center;">✓ _____</td> <td>_____</td> </tr> <tr> <td>d. O-ring defects/damage?</td> <td style="text-align: center;">_____</td> <td style="text-align: center;">✓ _____</td> <td>_____</td> </tr> </tbody> </table> <p><u>Forward Secondary O-ring: #4</u></p> <table style="width: 100%;"> <tbody> <tr> <td>e. Heat affected or eroded O-ring?</td> <td style="text-align: center;">_____</td> <td style="text-align: center;">✓ _____</td> <td>_____</td> </tr> <tr> <td>f. O-ring defects/damage?</td> <td style="text-align: center;">_____</td> <td style="text-align: center;">✓ _____</td> <td>_____</td> </tr> </tbody> </table> <p><u>Aft Secondary O-ring: #3</u></p> <table style="width: 100%;"> <tbody> <tr> <td>g. Heat affected or eroded O-ring?</td> <td style="text-align: center;">_____</td> <td style="text-align: center;">✓ _____</td> <td>_____</td> </tr> <tr> <td>h. O-ring defects/damage?</td> <td style="text-align: center;">_____</td> <td style="text-align: center;">✓ _____</td> <td>_____</td> </tr> </tbody> </table>				Yes	No	Comment #	a. Heat affected or eroded O-ring?	_____	✓ _____	_____	b. O-ring defects/damage?	_____	✓ _____	_____	c. Heat affected or eroded O-ring?	_____	✓ _____	_____	d. O-ring defects/damage?	_____	✓ _____	_____	e. Heat affected or eroded O-ring?	_____	✓ _____	_____	f. O-ring defects/damage?	_____	✓ _____	_____	g. Heat affected or eroded O-ring?	_____	✓ _____	_____	h. O-ring defects/damage?	_____	✓ _____	_____
	Yes	No	Comment #																																			
a. Heat affected or eroded O-ring?	_____	✓ _____	_____																																			
b. O-ring defects/damage?	_____	✓ _____	_____																																			
c. Heat affected or eroded O-ring?	_____	✓ _____	_____																																			
d. O-ring defects/damage?	_____	✓ _____	_____																																			
e. Heat affected or eroded O-ring?	_____	✓ _____	_____																																			
f. O-ring defects/damage?	_____	✓ _____	_____																																			
g. Heat affected or eroded O-ring?	_____	✓ _____	_____																																			
h. O-ring defects/damage?	_____	✓ _____	_____																																			
<p>Notes / Comments</p>																																						
<p>Preliminary PFAR(s)? _____ Yes    <u>✓</u> No    Preliminary PFAR Number(s): _____</p> <p>Clarification Form(s)? _____ Yes    <u>✓</u> No    Number of Forms Attached: _____</p>																																						

POSTFLIGHT OBSERVATION RECORD (PFOR)  
SII and Port (At Removal) - 18 Degrees

Motor No.: RSRM-32	Side: Left (A)	Date: 7-9-93
--------------------	----------------	--------------

Assessment Engineer(s)/Inspector(s): S. Eden, M. Lyon, C. Taylor, L. MacCauley

SII and Port:

	Yes	No	Comment #
a. Soot to or past O-ring?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
b. Sooted surfaces?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	1
c. Heat affected or eroded O-ring (installed)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
d. O-ring damage (installed)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
e. Eroded metal?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
f. Foreign material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
g. Excessive grease?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
h. Medium or heavy corrosion?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
i. Metal damage?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

Notes / Comments

1 - Typical soot to tip of SII.

Preliminary PFAR(s)? ☐ Yes ☒ No Preliminary PFAR Number(s): \_\_\_\_\_

Clarification Form(s)? ☐ Yes ☒ No Number of Forms Attached: \_\_\_\_\_

REVISION \_\_\_\_\_

DOC NO.	TWR-64240	VOL
SEC	PAGE	A-3

POSTFLIGHT OBSERVATION RECORD (PFOR)  
SII and O-rings (Detailed) - 18 Degrees

Motor No.: RSRM-32	Side: Left (A)	Date: 7-9-93	
Assessment Engineer(s)/Inspector(s): S. Eden, M. Lyon, C. Taylor, L. MacCauley			
<u>SII:</u>	Yes	No	Comment #
a. Foreign material between the O-ring and SII?	_____	_____ <input checked="" type="checkbox"/> _____	_____
b. Eroded metal?	_____	_____ <input checked="" type="checkbox"/> _____	_____
c. Seal surface/thread damage?	_____	_____ <input checked="" type="checkbox"/> _____	_____
<u>Primary O-ring:</u>			
d. Heat affected or eroded O-ring?	_____	_____ <input checked="" type="checkbox"/> _____	_____
e. O-ring defects/damage?	_____	_____ <input checked="" type="checkbox"/> _____	_____
<u>Secondary O-ring:</u>			
f. Heat affected or eroded O-ring?	_____	_____ <input checked="" type="checkbox"/> _____	_____
g. O-ring defects/damage?	_____	_____ <input checked="" type="checkbox"/> _____	_____
Notes / Comments			
Preliminary PFAR(s)? _____ Yes _____ <input checked="" type="checkbox"/> No Preliminary PFAR Number(s): _____			
Clarification Form(s)? _____ Yes _____ <input checked="" type="checkbox"/> No Number of Forms Attached: _____			



POSTFLIGHT OBSERVATION RECORD (PFOR)  
SII and O-rings (Detailed) - 198 Degrees

Motor No.: RSRM-32	Side: Left (A)	Date: 7-9-93
Assessment Engineer(s)/Inspector(s): S. Eden, M. Lyon, C. Taylor, L. MacCauley		
<p><u>SII:</u></p> <p>a. Foreign material between the O-ring and SII?</p> <p>b. Eroded metal?</p> <p>c. Seal surface/thread damage?</p> <p><u>Primary O-ring:</u></p> <p>d. Heat affected or eroded O-ring?</p> <p>e. O-ring defects/damage?</p> <p><u>Secondary O-ring:</u></p> <p>f. Heat affected or eroded O-ring?</p> <p>g. O-ring defects/damage?</p>	<p>Yes</p> <p>_____</p> <p>_____</p> <p>_____</p> <p>_____</p> <p>_____</p> <p>_____</p> <p>_____</p>	<p>No</p> <p>✓ _____</p> <p>✓ _____</p> <p>✓ _____</p> <p>✓ _____</p> <p>✓ _____</p> <p>✓ _____</p> <p>✓ _____</p>
<p>Comment #</p> <p>_____</p> <p>_____</p> <p>_____</p> <p>_____</p> <p>_____</p> <p>_____</p> <p>_____</p>		
<p>Notes / Comments</p>		
<p>Preliminary PFAR(s)? _____ Yes _____ <u>✓</u> No _____ Preliminary PFAR Number(s): _____</p> <p>Clarification Form(s)? _____ Yes _____ <u>✓</u> No _____ Number of Forms Attached: _____</p>		





POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Internal Joint RTV - Joint 2

Motor No.: RSRM-32	Side: Left (A)	Date: 9 July 93
Assessment Engineer(s)/Inspector(s): JIM PASSMAN, TREVOR FRESTON, WAYNE SPERRY		

Joint RTV:	Yes	No	Comment #
a. Gas penetration?	✓		(1)
b. RTV not below char line?	✓		(1)
c. Uncured/reverted RTV?		✓	
d. Voids within RTV?	✓		(2)
e. Grease inhibiting RTV backfill?		✓	
f. Foreign material?		✓	

Notes / Comments

Special Issue 3.3.4 TWO GAS PATHS WERE FOUND THROUGH THE BACKFILLED RTV, ALLOWING SOOT TO REACH PRIMARY O-RING. OVERALL THE JOINT BACKFILL WAS IN GOOD CONDITION. RTV REACHED NOSE INLET HOUSING FULL CIRC AND COWL BOUNDLINE FULL CIRC.



(1) GAS PATHS THROUGH RTV LOCATED AT 132.5° AND 318°, SOOT REACHED PRIMARY O-RING AT 108°-150° AND 306°-330°. HEAT AFFECTED CCP, SCP, AND GCP WAS ALSO PRESENT AT GAS PATH LOCATIONS.

See SKETCHES BELOW FOR DIMENSIONS. EROSION TO THE GCP OCCURRED AT THE GAS PATH LOCATIONS. APPROX. MEASUREMENTS ARE SHOWN BELOW.

(2) VERY FEW VOIDS OF .100 DIAM. OR LESS

Special Issue 3.3.5

A GAS PATH WAS FOUND AT CDI REPAIR LOCATION AT 132.5°.



Preliminary PFAR(s)? ☒ Yes ☐ No

Clarification Form(s)? ☐ Yes ☒ No

Preliminary PFAR Number(s): ETC-01


Number of Forms Attached: \_\_\_\_\_

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Internal Joint Phenolics - Joint 2

Motor No.: RSRM-32	Side: Left (A)	Date: 9 July 93
Assessment Engineer(s)/Inspector(s): Jim PASSMAN, TREVOR FRESTON, WAYNE SPERRY		
<b>Joint Phenolics:</b>		
a. Heat affected or eroded CCP (below the char line), GCP/SCP, or adhesive?	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/> Comment # (2)
b. Physical damage?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
c. Edge separations (metal-to-adhesive, within adhesive, adhesive-GCP/SCP, within GCP/SCP, GCP/SCP-to-CCP, or within CCP)?	<input type="checkbox"/>	<input checked="" type="checkbox"/> (1)
d. Phenolics axially displaced from the housing?	<input type="checkbox"/>	<input checked="" type="checkbox"/>

Notes / Comments

- NOSE INLET
- (1) RTV COVERED BONDLINE BETWEEN PHENOLICS AND HOUSING, AREAS WHERE RTV WAS REMOVED SHOWED NO EDGE SEPS. NO EDGE SEPS. FOUND ON COWL BONDLINE.
- (2) HEAT AFFECTED SCP, CCP AND GCP IN LINE WITH GAS PATHS AT 132.5° AND 318°. SLIGHT EROSION WAS EVIDENT ON THE GCP, SCP AND CCP. APPROX DEPTHS ON THE GCP ARE SHOWN IN SKETCHES ON PFOR A-8.



Preliminary PFAR(s)? ☒ Yes ☐ No Preliminary PFAR Number(s): 57C-01

Clarification Form(s)? ☐ Yes ☒ No Number of Forms Attached: \_\_\_\_\_

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Internal Joint Seals and Metal - Joint 2

Motor No.: RSRM-32	Side: Left (A)	Date: 7-9-83
Assessment Engineer(s)/Inspector(s): W. Sperry, M. Offeller		

Joint Seals and Metal:	Yes	No	Comment #
a. Soot to or past O-rings?	✓		2
b. Sooted joint surfaces?	✓		3
c. Heat affected or eroded O-rings (installed)?		✓	
d. O-ring damage (installed)?		✓	
e. Heat affected or eroded metal?		✓	
f. RTV to primary O-ring?		✓	
g. RTV past primary O-ring?		✓	
h. Foreign material?	✓		1
i. Excessive grease? (including in threaded and through bolt holes)		✓	
j. Metal damage? (including index pin and bolt holes (through, threaded/ helical coil inserts))		✓	
k. Bent or broken bolts?		✓	

Notes / Comments

271, 311, 312, 298, 288 degree locations

- 1- Aluminum Oxide Corrosion downstream of secondary O-ring <sup>on</sup> both mating surfaces at ↗
- 2- Soot to primary O-ring at two locations (gas paths) 108-150° and 306°-330°
- 3- Soot upstream of primary O-ring full circumference with corresponding intermitted <sup>light</sup> corrosion.
- 4- HEAT AFFECTED PAINT WAS FOUND ON BOARING FWD END RING FLANGE O.D. IN LINE WITH GAS PATHS AT 132.5° AND 318°.

Preliminary PFAR(s)? ☒ Yes ☐ No  
Clarification Form(s)? ☒ Yes ☐ No

Preliminary PFAR Number(s): 57C-01  
Number of Forms Attached: 1

PFOR CLARIFICATION FORM  
General



Motor No.: RSRM-32 Side: ☒ Left (A) ☐ Right (B) Date: 7-13-93

Assessment Engineer(s)/Inspector(s): J. Passman, T. Freston, V. Gunther

Description: Hardness & Electrical Conductivity Test Results on metal surfaces at

Sketch Observations Below (include locations and sizes of sketched features): Gaspaths in joint 2

HARDNESS TESTING OF JOINT METAL SURFACES IN GAS PATH REGIONS:

	DEGREE LOCATION	RADIAL LOCATION FROM CHAMFER	Rockwell C HARDNESS
 <p>FWD END RING</p> <p>~.125</p> <p>POINT AREA AFFECTED + MISSING</p>	132.5°	.125	45
		.250	44
		.375	44
		<del>.500</del>	
	318°	.125	45
		.250	44
 <p>COWL</p> <p>.250</p> <p>PITTING (CORROSION)</p>	132.5°	.250	88
		.500	88
	318°	.250	88
		.500	88

ELECTRICAL CONDUCTIVITY TEST IN OF METAL SURFACES: %IACS

COWL	132.5°	41.4	41.2	40.4	41.3	41.4	41.5
	318°	41.2	41.4	40.5	39.3	41.2	41.1
NOSE INLET	132.5°	39.0	38.9	38.9	39.5	38.8	39.1
	318°	39.4	39.6	39.3	39.6	39.4	39.3

NOTE: Rockwell 'C' hardness of 44 is acceptable for D6AC steel  
Rockwell 'B' hardness of 88 is acceptable for 7075-T73 aluminum  
Electrical conductivity of 38 and above is acceptable for 7075-T73 aluminum

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Internal Joint Drawing Worksheet - Joint 2

Motor No.: RSRM-32


Side: Left (A)

Date: 9 July 93

Assessment Engineer(s)/Inspector(s): JIM PASSMAN, TREVOR FRESTON, WAYNE SPERRY

Sketch Observations Below (include locations and sizes of sketched features):

- ① SOOT INTO JOINT SURFACE FROM GAS PATHS WITH INTERMITTENT FULL CIRCUMFERENCE LIGHT-MED. CORROSION.
- ② LIGHT TO MED CORROSION INT. FULL CIRCUMFERENCE.



- ③ ALUMINUM OXIDE CORROSION DEPOSITS LOCATED HERE AT 271°, 288°, 298°, 311°, AND 312°.
- ④ INTERMITTENT SOOTING FROM GAS PATHS, HEAT AFFECTED PAINT AT GAS PATH LOCATIONS.
- ⑤ GAS PATHS THROUGH RTV LOCATED AT 132.5° AND 318°. SOOT ENTERED JOINT AND REACHED PRIMARY O-RING AT 108°-150° AND 306°-330°.
- ⑥ EA946 ADHESIVE LOCATED ON THIS SURFACE WAS ERODED AWAY IN LINE WITH GAS PATH AT 132.5° (.025 inch THICKNESS EROSION). EA946 WAS ALSO ERODED TO GLASS CLOTH PHENOLIC AT 318° (.023 inch). GCP EROSION TO .005 DEPTH PRESENT AT 132.5°.
- ⑦ GLASS CLOTH-PHENOLIC EROSION IN THIS AREA 132.5° - 0.005 inch, 318° - 0.003 inch.

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Internal Joint O-rings (Detailed) - Joint 2

Motor No.: RSRM-32	Side: Left (A)	Date: 7-9-93
Assessment Engineer(s)/Inspector(s): <i>W. Sperry, M. Offalter, B. Ferguson</i>		
<b>Primary O-ring:</b>		
Yes	No	Comment #
a. Heat affected or eroded O-ring?	<input checked="" type="checkbox"/>	<input type="checkbox"/>
b. O-ring defects/damage?	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<b>Secondary O-ring:</b>		
Yes	No	Comment #
c. Heat affected or eroded O-ring?	<input checked="" type="checkbox"/>	<input type="checkbox"/>
d. O-ring defects/damage?	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Notes / Comments		
Preliminary PFAR(s)? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		
Preliminary PFAR Number(s): _____		
Clarification Form(s)? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		
Number of Forms Attached: _____		

REVISION \_\_\_\_\_

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Internal Joint RTV - Joint 3

Motor No.: RSRM-32	Side: Left (A)	Date: 9 JULY 25
Assessment Engineer(s)/Inspector(s): R. QUICK, P. MILNER, W. SPERRY		
<b>Joint RTV:</b>		
	Yes	No
a. Gas penetration?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
b. RTV not below char line?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
c. Uncured/reverted RTV?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
d. Voids within RTV?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
e. Grease inhibiting RTV backfill?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
f. Foreign material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
<b>Notes / Comments</b>		
Preliminary PFAR(s)? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		
Preliminary PFAR Number(s): _____		
Clarification Form(s)? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		
Number of Forms Attached: _____		



POSTFLIGHT OBSERVATION RECORD (PFOR)

Nozzle Internal Joint Phenolics - Joint 3

Motor No.: RSRM-32	Side: Left (A)	Date: 9 JUL 93
--------------------	----------------	----------------

Assessment Engineer(s)/Inspector(s): E. QUICK P. MILLER W. SPERRY

Joint Phenolics:	Yes	No	Comment #
a. Heat affected or eroded CCP (below the char line), GCP, or adhesive?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
b. Physical damage?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
c. Edge separations (metal-to-adhesive, within adhesive, adhesive-GCP, within GCP, GCP-to-CCP, or within CCP)?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	1 & 2
d. Phenolics axially displaced from the housing?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

Notes / Comments

- ① ADHESIVE TO HOUSING SEPARATION ON THROAT FULL CIRCUM MAX GAP = .019
- ② ADHESIVE TO HOUSING SEPARATION NOSE INLET HOUSING FROM 835 - 350° MAX GAP .005

Preliminary PFAR(s)?	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	Preliminary PFAR Number(s):	
Clarification Form(s)?	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	Number of Forms Attached:	

REVISION \_\_\_\_\_

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Internal Joint Seals and Metal - Joint 3

Motor No.: RSRM-32	Side: Left (A)	Date: 7-9-93
--------------------	----------------	--------------

Assessment Engineer(s)/Inspector(s): W. Sperry, M. DeFolter

Joint Seals and Metal:

	Yes	No	Comment #
a. Soot to or past O-rings?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
b. Sooted joint surfaces?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
c. Heat affected or eroded O-rings (installed)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
d. O-ring damage (installed)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
e. Heat affected or eroded metal?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
f. RTV to primary O-ring?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
g. RTV past primary O-ring?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
h. Foreign material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
i. Excessive grease? (including in threaded and through bolt holes)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
j. Metal damage? (including index pin and bolt holes (through, threaded/ helical coil inserts))	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
k. Bent or broken bolts?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

Notes / Comments

Preliminary PFAR(s)? ☐ Yes ☒ No Preliminary PFAR Number(s): \_\_\_\_\_  
 Clarification Form(s)? ☐ Yes ☒ No Number of Forms Attached: \_\_\_\_\_

REVISION \_\_\_\_\_

DOC NO. TWR-64240  
SEC \_\_\_\_\_

VOL \_\_\_\_\_

PAGE A-15

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Internal Joint Drawing Worksheet - Joint 3


Motor No.: RSRM-32

Side: Left (A)

Date: 9 JULY 93

Assessment Engineer(s)/Inspector(s): R. Guich W. SPERRY P. MILLER

Sketch Observations Below (include locations and sizes of sketched features):



- ① NO EXCESS GREASE IN HOLES
- ② GREASE COVERAGE NOMINAL
- ③ RTV BELOW CHAR LINE 360°
- ④ RTV FROM 0°-75° & 180°-0°

- ⑤ APPEARS TO BE SALT DEPOSIT FULL CIRCUM

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Internal Joint O-rings (Detailed) - Joint 3

Motor No.: RSRM-32	Side: Left (A)	Date: 7-9-93	
Assessment Engineer(s)/Inspector(s): <i>W. Sperry, M. Offalter, B. Ferguson</i>			
<b>Primary O-ring:</b>			
a. Heat affected or eroded O-ring?	Yes _____	No _____ <input checked="" type="checkbox"/>	Comment # _____
b. O-ring defects/damage?	_____ _____	_____ <input checked="" type="checkbox"/>	_____ _____
<b>Secondary O-ring:</b>			
c. Heat affected or eroded O-ring?	_____ _____	_____ <input checked="" type="checkbox"/>	_____ _____
d. O-ring defects/damage?	_____ _____	_____ <input checked="" type="checkbox"/>	_____ _____
Notes / Comments			
Preliminary PFAR(s)? _____ Yes <input checked="" type="checkbox"/> No _____			
Preliminary PFAR Number(s): _____			
Clarification Form(s)? _____ Yes <input checked="" type="checkbox"/> No _____			
Number of Forms Attached: _____			

REVISION \_\_\_\_\_

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Internal Joint RTV - Joint 4

Motor No.: RSRM-32	Side: Left (A)	Date: 7 JULY 93
Assessment Engineer(s)/Inspector(s): R. QUICK P. MILLER A. CARLISLE		
<u>Joint RTV:</u>		
	Yes	No
a. Gas penetration?	_____	_____/_____ ✓
b. RTV not below char line?	_____	_____/_____ ✓
c. Uncured/reverted RTV?	_____	_____/_____ ✓
d. Voids within RTV?	_____	_____/_____ ✓
e. Grease inhibiting RTV backfill?	_____	_____/_____ ✓
f. Foreign material?	_____	_____/_____ ✓
Comment # _____		
Notes / Comments		
Preliminary PFAR(s)? _____ Yes _____ No <u>✓</u>		
Preliminary PFAR Number(s): _____		
Clarification Form(s)? _____ Yes _____ No <u>✓</u>		
Number of Forms Attached: _____		

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Internal Joint Phenolics - Joint 4

Motor No.: RSRM-32	Side: Left (A)	Date: 7 JULY 93
--------------------	----------------	-----------------

Assessment Engineer(s)/Inspector(s): R. QUICK P. MILLER A. CARLISLE

Joint Phenolics:

	Yes	No	Comment #
a. Heat affected or eroded CCP (below the char line), GCP, or adhesive?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
b. Physical damage?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
c. Edge separations (metal-to-adhesive, within adhesive, adhesive-GCP, within GCP, GCP-to-CCP, or within CCP)?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>1 &amp; 2</u>
d. Phenolics axially displaced from the housing?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

Notes / Comments

- 1- SEPARATION BETWEEN GCP AND FEC HOUSING FULL CIRCUM  
MAX GAP = .015
- 2- SEPARATION BETWEEN GCP AND THROAT HOUSING FULL CIRCUM  
MAX GAP = .021 & ONE SEPARATION WITHIN GCP AT 180° x .70 CIRCUM  
x .002 RADIAL

Preliminary PFAR(s)? ☐ Yes ☒ No

Preliminary PFAR Number(s): \_\_\_\_\_

Clarification Form(s)? ☐ Yes ☒ No

Number of Forms Attached: \_\_\_\_\_

REVISION \_\_\_\_\_

DOC NO. TWR-64240 VOL \_\_\_\_\_  
SEC \_\_\_\_\_ PAGE A-19

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Internal Joint Seals and Metal - Joint 4

Motor No.: RSRM-32	Side: Left (A)	Date: 7 JULY 93
Assessment Engineer(s)/Inspector(s): <i>R. QUICK P. MILLER H. CARLISLE</i>		

<u>Joint Seals and Metal:</u>	Yes	No	Comment #
a. Soot to or past O-rings?	_____	✓	_____
b. Sooted joint surfaces?	_____	✓	_____
c. Heat affected or eroded O-rings (installed)?	_____	✓	_____
d. O-ring damage (installed)?	_____	✓	_____
e. Heat affected or eroded metal?	_____	✓	_____
f. RTV to primary O-ring?	✓	_____	1
g. RTV past primary O-ring?	_____	✓	_____
h. Foreign material?	_____	✓	_____
i. Excessive grease?	_____	✓	_____
(including in threaded and through bolt holes)			
j. Metal damage?	_____	✓	_____
(including index pin and bolt holes (through, threaded/ helical coil inserts))			
k. Bent or broken bolts?	_____	✓	_____

Notes / Comments

Special Issue 3.3.1 *NO CONDITIONS FOUND AT 90° & 270° AND NO APPARENT FUNCTIONAL PROBLEMS*

① *RTV TO PRIMARY O-RING INTERMITTENTLY 360°*

Preliminary PFAR(s)? \_\_\_\_\_ Yes \_\_\_\_\_ ☒ No Preliminary PFAR Number(s): \_\_\_\_\_  
 Clarification Form(s)? \_\_\_\_\_ Yes \_\_\_\_\_ ☒ No Number of Forms Attached: \_\_\_\_\_

REVISION \_\_\_\_\_

DOC NO. TWR-64240	VOL _____
SEC _____	PAGE A-20

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Internal Joint Drawing Worksheet - Joint 4

Motor No.: RSRM-32


Side: Left (A)

Date: 7 JULY 93

Assessment Engineer(s)/Inspector(s): R. QUICK P. MILLER A. CARLISLE

Sketch Observations Below (include locations and sizes of sketched features):

- ① RTV TO PRIMARY O-RING INTERMITTENTLY 360°
- ② LIGHT CORROSION ON FWD EXIT CONE AT 354° & 0°-6°
- ③ SEPARATION INTERMITTENTLY 360° MAX = .015



- ④ SEPARATION 360° MAX GAP = .021
- ⑤ NO EXCESS GREASE IN HOLES AND GREASE COVERAGE WAS NOMINAL
- ⑥ MEDIUM TO HEAVY COVERAGE FULL CIRCUM
- ⑦ RTV DISCOLORED FROM SALT WATER FROM 345° THRU 0° TO 98°



POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Internal Joint O-rings (Detailed) - Joint 4

Motor No.: RSRM-32	Side: Left (A)	Date: 7 July 1993
Assessment Engineer(s)/Inspector(s): A. Carlisle, B. Quick, M. Lyons, J. Richards		
<b>Primary O-ring:</b>		
a. Heat affected or eroded O-ring?	Yes _____ _____	No ✓ _____
b. O-ring defects/damage?	_____ _____	✓ _____
<b>Secondary O-ring:</b>		
c. Heat affected or eroded O-ring?	_____ _____	✓ _____
d. O-ring defects/damage?	_____ _____	✓ _____
Notes / Comments		
Preliminary PFAR(s)?    Yes <input checked="" type="checkbox"/> No    Preliminary PFAR Number(s): _____		
Clarification Form(s)?    Yes <input checked="" type="checkbox"/> No    Number of Forms Attached: _____		

REVISION \_\_\_\_\_

POSTFLIGHT OBSERVATION RECORD (PFOR)

Nozzle Internal Joint RTV - Joint 5

Motor No.: RSRM-32      Side: Left (A)      Date: 8 JULY 93

Assessment Engineer(s)/Inspector(s): *E. QUICK P. MILLER A. CARLISLE*

Joint RTV:

	Yes	No	Comment #
a. Gas penetration?	_____	<input checked="" type="checkbox"/>	_____
b. RTV not below char line?	_____	<input checked="" type="checkbox"/>	_____
c. Uncured/reverted RTV?	_____	<input checked="" type="checkbox"/>	_____
d. Voids within RTV?	<input checked="" type="checkbox"/>	_____	<u>1</u>
e. Foreign material?	_____	<input checked="" type="checkbox"/>	_____

Notes / Comments

*-INTERMITTENT VOIDS 360° LARGEST VOID AT 13°-20° APPROX. 02 DP*

Preliminary PFAR(s)? \_\_\_\_\_ Yes ☒ No

Preliminary PFAR Number(s): \_\_\_\_\_

Classification Form(s)? \_\_\_\_\_ Yes ☒ No

Number of Forms Attached: \_\_\_\_\_

REVISION \_\_\_\_\_

DOC NO. TWR-64240 VOL

SEC PAGE A-23

POSTFLIGHT OBSERVATION RECORD (PFOR)

Nozzle Internal Joint Phenolics - Joint 5

Motor No.: RSRM-32	Side: Left (A)	Date: 8 JULY 93
--------------------	----------------	-----------------

Assessment Engineer(s)/Inspector(s): R. QUICK, P. MILLER, A. CARLISLE

Joint Phenolics:	Yes	No	Comment #
a. Heat affected or eroded CCP (below the char line), GCP, or adhesive?	_____	<u>✓</u>	_____
b. Physical damage?	_____	<u>✓</u>	_____
c. Edge separations (metal-to-adhesive, within adhesive, adhesive-GCP, within GCP, GCP-to-CCP, or within CCP)?	_____	<u>✓</u>	_____
d. Phenolics axially displaced from the housing?	_____	<u>✓</u>	_____

Notes / Comments

Special Issue 3.3.2 *PHENOLIC NOT ACCESSABLE, SPECIAL ISSUE TO BE ADDRESSED DURING WASHOUT ON PFOR A-46*

Preliminary PFAR(s)? \_\_\_\_\_ Yes ✓ No \_\_\_\_\_ Preliminary PFAR Number(s): \_\_\_\_\_

Classification Form(s)? \_\_\_\_\_ Yes ✓ No \_\_\_\_\_ Number of Forms Attached: \_\_\_\_\_

REVISION \_\_\_\_\_

DOC NO.	TWR-64240	VOL
SEC	PAGE	A-24

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Internal Joint Seals and Metal - Joint 5

Motor No.: RSRM-32	Side: Left (A)	Date: 8 JULY 93
Assessment Engineer(s)/Inspector(s): R. QUICK P. MILLER A. CARLISLE		

Joint Seals and Metal:	Yes	No	Comment #
a. Soot to or past O-rings?		<input checked="" type="checkbox"/>	
b. Sooted joint surfaces?		<input checked="" type="checkbox"/>	
c. Heat affected or eroded O-rings (installed)?		<input checked="" type="checkbox"/>	
d. O-ring damage (installed)?		<input checked="" type="checkbox"/>	
e. Heat affected or eroded metal?		<input checked="" type="checkbox"/>	
f. RTV to primary O-ring?	<input checked="" type="checkbox"/>		1
g. RTV past primary O-ring?		<input checked="" type="checkbox"/>	
h. Foreign material?		<input checked="" type="checkbox"/>	
i. Excessive grease?		<input checked="" type="checkbox"/>	
(including in threaded and through bolt holes)			
j. Metal damage?		<input checked="" type="checkbox"/>	
(including index pin and bolt holes (through, threaded/ helical coil inserts))			
k. Bent or broken bolts?		<input checked="" type="checkbox"/>	

Remarks / Comments  
- RTV TO PRIMARY O-RING AT 290° CENTER ABOUT BOLT HOLE FOR 1.0 IN. CIRCUM.

Preliminary PFAR(s)?	Yes	<input checked="" type="checkbox"/> No	Preliminary PFAR Number(s):
Classification Form(s)?	Yes	<input checked="" type="checkbox"/> No	Number of Forms Attached:

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Internal Joint Drawing Worksheet - Joint 5

Motor No.: RSRM-32


Side: Left (A)

Date: 8 JULY 93

Assessment Engineer(s)/Inspector(s): R. QUICK, P. MILLER, A. CARLISLE

Sketch Observations Below (include locations and sizes of sketched features):

- ① NOMINAL GREASE COVERAGE
- ② LIGHT CORROSION ON PACKING RING SEAL SURFACE AT 110°
- ③ MISSING PAINT AND CORROSION AT 260°-265° MEDIUM



- ④ RTV REACHED AER AT LOCATIONS 90°, 100°-105°, 235°-240° 248-295
- ⑤ SNUBBER CONTACT ON AER FROM 175-335 MAX AXIAL DISTANCE 6.2 IN.

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Internal Joint O-rings (Detailed) - Joint 5

Motor No.: RSRM-32

Side: Left (A)

Date: 8 July 1993

Assessment Engineer(s)/Inspector(s): A. Carlisle, M. Lyons, J. Richards

Primary O-ring:

Yes

No

Comment #

a. Heat affected or eroded O-ring?

\_\_\_\_\_

✓  
\_\_\_\_\_

\_\_\_\_\_

b. O-ring defects/damage?

\_\_\_\_\_

✓  
\_\_\_\_\_

\_\_\_\_\_

Secondary O-ring:

c. Heat affected or eroded O-ring?

\_\_\_\_\_

✓  
\_\_\_\_\_

\_\_\_\_\_

d. O-ring defects/damage?

\_\_\_\_\_

✓  
\_\_\_\_\_

\_\_\_\_\_

Notes / Comments

Preliminary PFAR(s)? \_\_\_\_\_ Yes \_\_\_\_\_ No

Preliminary PFAR Number(s): \_\_\_\_\_

Clarification Form(s)? \_\_\_\_\_ Yes \_\_\_\_\_ No

Number of Forms Attached: \_\_\_\_\_

REVISION \_\_\_\_\_

DOC NO. TWR-64240 VOL  
SEC PAGE A-27

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Internal Joint Packings With Retainers (Detailed) - Joint 5

Motor No.: RSRM-32	Side: Left (A)	Date: 8 July 1993
Assessment Engineer(s)/Inspector(s): A. Carlisle, M. Lyons, J. Richards		
<u>Packings With Retainers:</u>	Yes	No
a. Heat affected or eroded seal or retainer?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
b. Seal or retainer defects/damage?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
c. Medium or heavy corrosion?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Notes / Comments

1) Typical disassembly <sup>rubber</sup> damage to 71 of 72 packing with retainers

Preliminary PFAR(s)? ☐ Yes ☒ No Preliminary PFAR Number(s): \_\_\_\_\_

Clarification Form(s)? ☐ Yes ☒ No Number of Forms Attached: \_\_\_\_\_

REVISION \_\_\_\_\_

DOC NO. TWR-64240 VOL  
SEC PAGE A-28

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Cowl Insulation Segments

Motor No.: RSRM-32	Side: Left (A)	Date: 9 July 93
Assessment Engineer(s)/Inspector(s): Jim Passman Bob Quick		

Cowl Insulation Segments:

- a. Abnormal heat effects or erosion?
- b. Soot between the cowl segment and cowl housing/SCP?
- c. Uncured adhesive (silicone)?

Yes	No	Comment #
_____	✓	_____
_____	✓	_____
_____	✓	_____

Bondline Failure Mode Percentage:

	Degree Location								Total
	0-45	45-90	90-135	135-180	180-225	225-270	270-315	315-0	
Metal-to-Adhesive	10	5	25	20	25	20	1	5	
Within Adhesive									
Adhesive-to-SCP	5	2	5	7	5	5	5	2	
Adhesive-to-segment	85	93	70	73	70	75	93	93	
Within segment									

Notes / Comments

Special Issue 3.3.3

THE COWL INSULATION SEGMENTS WERE IN EXCELLENT  
CONDITION NO UNBONDING OR OTHER ANOMALOUS CONDITIONS WERE  
FOUND.

Preliminary PFAR(s)?	Yes	No <input checked="" type="checkbox"/>	Preliminary PFAR Number(s):
Clarification Form(s)?	Yes	No <input checked="" type="checkbox"/>	Number of Forms Attached:



POSTFLIGHT OBSERVATION RECORD (PFOR)  
Flexible Bearing Protector, Flexible Bearing, and Flexible Boot

Motor No.: RSRM-32	Side: Left (A)	Date: 9 July 93
Assessment Engineer(s)/Inspector(s): <u>JIM PASSMAN, BOB QUICK</u>		

<u>Flexible Bearing Protector, Bearing, and Boot:</u>	Yes	No	Comment #
a. Abnormal bearing protector heat effects or erosion? (including burn-through)	_____	____✓____	_____
b. Cracks through the bearing protector?	_____	____✓____	_____
c. Soot between the bearing protector and flexible bearing?	_____	____✓____	_____
d. Heat effects to the flexible bearing?	_____	____✓____	_____
e. Bent or broken bearing protector bolts?	_____	____✓____	_____
f. Flexible boot burn-through?	_____	____✓____	_____
g. Abnormal heat effects or erosion to flexible boot ID?	_____	____✓____	_____
h. Foreign material in the boot cavity?	_____	____✓____	_____

Notes / Comments

Special Issue 3.3.6 NO ABNORMAL CONDITION OBSERVED

Preliminary PFAR(s)? \_\_\_\_\_ Yes \_\_\_\_\_ No ✓ Preliminary PFAR Number(s): \_\_\_\_\_

Clarification Form(s)? \_\_\_\_\_ Yes \_\_\_\_\_ No ✓ Number of Forms Attached: \_\_\_\_\_

REVISION \_\_\_\_\_

DOC NO. TWR-64240	VOL
SEC	PAGE A-30


**POSTFLIGHT OBSERVATION RECORD (PFOR)**  
**Flexible Bearing Protector Measurements (Data Collection Only)**

Motor No.: RSRM-32	Side: Left (A)	Date: 14 JUL 1993
--------------------	----------------	-------------------

Assessment Engineer(s)/Inspector(s): PL / MS / RS

**Flexible Bearing Protector Gas Impingement Area Thickness Measurements (see figure):**

Degree Location	Thickness Measurement A* (inches)	Degree Location	Thickness Measurement A* (inches)	Degree Location	Thickness Measurement A* (inches)
0	.765	120	.738	240	.723
10	.715	130	.746	250	.725
20	.730	140	.735	260	.715
30	.735	150	.730	270	.701
40	.740	160	.720	280	.718
50	.705	170	.715	290	.725
60	.750	180	.721	300	.715
70	.740	190	.715	310	.715
80	.732	200	.710	320	.720
90	.730	210	.728	330	.735
100	.728	220	.730	340	.720
110	.735	230	.720	350	.705



\* "A" is the minimum thickness of the bearing protector belly band in-line with the cowl vent holes. It corresponds to the deepest gas impingement location.

Notes / Comments

262.7

Clarification Form(s)? ☐ Yes ☒ No      Number of Forms Attached:

REVISION

DOC NO. TWR-64240	VOL
SEC	PAGE A-31

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Throat Diameter Measurements (Data Collection Only)

Motor No.: RSRM-32	Side: Left (A)	Date: 07-12-93
Assessment Engineer(s)/Inspector(s): MIGUEL ENRIQUEZ ; RICK GALLEGOS		

Nozzle Throat Diameter Measurements:

Degree Location	Diameter Measurement (inches)
0	<u>55.869"</u>
45	<u>55.857"</u>
90	<u>55.871"</u>
135	<u>55.876"</u>

Notes / Comments

Avg. Throat Diameter = 55.867 inches

Clarification Form(s)? ☐ Yes ☒ No Number of Forms Attached:

REVISION

DOC NO.	TWR-64240	VOL
SEC	PAGE	A-32

**POSTFLIGHT OBSERVATION RECORD (PFOR)**  
**Nozzle Phenolic Bondline - Aft Exit Cone Assembly**

Motor No.: RSRM-32

Side: Left (A)

Date: 13 JULY 93

Assessment Engineer(s)/Inspector(s): T. FRESTON

Metal Housing Bondline Surface:

- a. Soot?
- b. Heat affected or eroded metal?
- c. Voids in adhesive greater than 0.5 inch in any direction?
- d. Corrosion?
- e. Foreign material?

Yes

No

Comment #


Note: Axial cuts may be relocated + or - 10 degrees only. Document if any cuts were relocated.

Primary Bondline/Phenolic Failure Mode Percentage (After Hydrolase and Wedge Removal):

	Degree Location							
	0-45	45-90	90-135	135-180	180-225	225-270	270-315	315-0
Metal-to-Adhesive	10	20	35	10	10	5	8	8
Within Adhesive								
Adhesive-to-GCP								
Within GCP	90	80	65	90	90	95	92	92
GCP-to-CCP								
Within CCP								

Secondary Bondline Failure Mode Percentage (After Removal of Remaining Phenolics):

	Degree Location							
Metal-to-Adhesive								
Within Adhesive								
Adhesive-to-GCP								

Phenolic Removal Method: NYLON WEDGE

**Notes / Comments**

Special Issue 3.3.15 No abnormal bondline separation modes.

Preliminary PFAR(s)? Yes ☐ No ☒

Preliminary PFAR Number(s):

Clarification Form(s)? Yes ☐ No ☒

Number of Forms Attached:

**POSTFLIGHT OBSERVATION RECORD (PFOR)**  
**Nozzle Phenolic Bondline - Forward Exit Cone Assembly**

Motor No.: **RSRM-32** Side: **Left (A)** Date: **19-July 1993**  
Assessment Engineer(s)/Inspector(s): **JIM PASSMAN, TREVOR FRESTON**

<u>Metal Housing Bondline Surface:</u>	Yes	No	Comment #
a. Soot?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
b. Heat affected or eroded metal?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
c. Voids in adhesive greater than 0.5 inch in any direction?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	(1)
d. Corrosion?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	(2)
e. Foreign material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

Note: Axial cuts may be relocated + or - 10 degrees only. Document if any cuts were relocated.

Primary Bondline/Phenolic Failure Mode Percentage (After Hydrolase and Wedge Removal):

	Degree Location								Total
	0-45	45-90	90-135	135-180	180-225	225-270	270-315	315-0	
Metal-to-Adhesive	60	55	50	60	70	60	55	75	61
Within Adhesive									
Adhesive-to-GCP	40	45	50	40	30	40	45	25	39
Within GCP									
GCP-to-CCP									
Within CCP									

Secondary Bondline Failure Mode Percentage (After Removal of Remaining Phenolics):

	Degree Location							
	0-45	45-90	90-135	135-180	180-225	225-270	270-315	315-0
Metal-to-Adhesive								
Within Adhesive								
Adhesive-to-GCP								

Phenolic Removal Method: \_\_\_\_\_

**Notes / Comments**

Special Issue 3.3.16 THE BONDLINE WAS IN NORMAL CONDITION.

DEGREE	SWIM LINATION	THICKNESS	ADJACENT ADH THICK	DEGREE	SWIM LINATION	THICK	ADJ ADH THIC
0	FWD	.063	.063	90	AFT	.062	.063
0	AFT	.065	.060	180	FWD	.062	.061
90	FWD	.062	.061	180	AFT	.065	.062
				270	FWD	.063	.060
				370	AFT	.062	.060
				45	FWD	.064	.060
				45	AFT	.065	.062

(1) SEE CLARIFICATION FORM A-34A.

(2) MED - HEAVY CORROSION IN METAL-ADHESIVE FAILURE AREAS.

Preliminary PFAR(s)? ☐ Yes ☒ No Preliminary PFAR Number(s): \_\_\_\_\_

Clarification Form(s)? ☒ Yes ☐ No Number of Forms Attached: **A-34A**

135	FWD	.064	.075
135	AFT	.063	N/A
225	FWD	.063	.069
225	AFT	.065	.065

Nozzle Subassembly Bondline Adhesive Void Clarification Form

Motor No.: <u>RSRM-32</u>	Side: <input checked="" type="checkbox"/> Left (A) <input type="checkbox"/> Right (B)	Date: <u>19-JUL-93</u>
Assessment Engineer(s)/Inspector(s): <u>TREVR FRESTON</u> <u>JIM PASSMAN</u>		
Nozzle Subassembly: <u>FWD EXIT CONE</u>		

Record Bondline Adhesive Void Measurements and Locations Below:

Degree Location	Void Size		Location on Bonding Surface	
	Axial	Circ.	Distance From Fwd	Distance From Aft
<u>78°</u>	<u>3.00</u>	<u>1.25</u>	<u>—</u>	<u>7.4</u>
<u>77°</u>	<u>0.90</u>	<u>0.40</u>	<u>—</u>	<u>11.2</u>
<u>189°</u>	<u>1.50</u>	<u>0.56</u>	<u>—</u>	<u>5.1</u>
<u>271°</u>	<u>1.10</u>	<u>0.55</u>	<u>—</u>	<u>13.6</u>
<u>274°</u>	<u>1.00</u>	<u>0.40</u>	<u>—</u>	<u>16.4</u>
<u>288</u>	<u>0.50</u>	<u>0.40</u>	<u>—</u>	<u>18.6</u>

Notes / Comments

Corresponding Comment Number(s): (1)

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Phenolic Bondline - Throat Assembly

Motor No.: RSRM-32	Side: Left (A)	Date: 21 July 93
Assessment Engineer(s)/Inspector(s): Jim PASSMAN TREVOE FRESTON		

Metal Housing Bondline Surface:	Yes	No	Comment #
a. Soot?		<input checked="" type="checkbox"/>	
b. Heat affected or eroded metal?		<input checked="" type="checkbox"/>	
c. Voids in adhesive greater than 0.5 inch in any direction?		<input checked="" type="checkbox"/>	(1)
d. Corrosion?	<input checked="" type="checkbox"/>		(2)
e. Foreign material?		<input checked="" type="checkbox"/>	

Note: Axial cuts may be relocated + or - 10 degrees only. Document if any cuts were relocated.

Primary Bondline/Phenolic Failure Mode Percentage (After Hydrolase and Wedge Removal):

	Degree Location							
	0-360°							
Metal-to-Adhesive	100							
Within Adhesive								
Adhesive-to-GCP								
Within GCP								
GCP-to-CCP								
Within CCP								

Secondary Bondline Failure Mode Percentage (After Removal of Remaining Phenolics):

	Degree Location							
Metal-to-Adhesive								
Within Adhesive								
Adhesive-to-GCP								

Phenolic Removal Method: \_\_\_\_\_

Notes / Comments

- (1) FEW VOIDS ~ .20 DIA.  
(2) HEAVY CORROSION ENTIRE SURFACE.

Preliminary PFAR(s)? ☐ Yes ☒ No Preliminary PFAR Number(s): \_\_\_\_\_

Clarification Form(s)? ☐ Yes ☒ No Number of Forms Attached: \_\_\_\_\_

**POSTFLIGHT OBSERVATION RECORD (PFOR)**  
**Nozzle Phenolic Bondline - Forward Nose and Aft Inlet Rings**

Motor No.: **RSRM-32**      Side: **Left (A)**      Date: **7/22/93**

Assessment Engineer(s)/Inspector(s): **R. QUICK T. FRESTON**

**Metal Housing Bondline Surface:**

	Yes	No	Comment #
a. Soot?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
b. Heat affected or eroded metal?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
c. Voids in adhesive greater than 0.5 inch in any direction?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	1
d. Corrosion?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<b>SEE A-36A</b>
e. Foreign material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

Note: Axial cuts may be relocated + or - 10 degrees only. Document if any cuts were relocated.

Primary Bondline/Phenolic Failure Mode Percentage (After Hydrolase and Wedge Removal):

	Degree Location							
	0-45	45-90	90-135	135-180	180-225	225-270	270-315	315-0
Metal-to-Adhesive	100%	100%	60%	60%	100%	100%	100%	100%
Within Adhesive								
Adhesive-to-GCP			40%	40%				
Within GCP								
GCP-to-CCP								
Within CCP								

Secondary Bondline Failure Mode Percentage (After Removal of Remaining Phenolics):

	Degree Location							
	0-45	45-90	90-135	135-180	180-225	225-270	270-315	315-0
Metal-to-Adhesive								
Within Adhesive								
Adhesive-to-GCP								

Phenolic Removal Method: \_\_\_\_\_

Notes / Comments **THE 40% ADHESIVE REMAINING WAS ON THE AFT INLET RING AREA**  
**1- MEDIUM TO HEAVY CORROSION INTERMITTENT FULL CIRCUM**

Special Issue 3.3.7 **Nine voids documented on clarification form A-36A**

Special Issue 3.3.10 **SEE CLARIFICATION FORM A-36A**

Preliminary PFAR(s)? ☐ Yes ☒ No      Preliminary PFAR Number(s): \_\_\_\_\_

Clarification Form(s)? ☒ Yes ☐ No      Number of Forms Attached: **A-36A, A-36B**



Nozzle Subassembly Bondline Adhesive Void Clarification Form

Motor No.: <u>RSRM-32</u>	Side: <input checked="" type="checkbox"/> Left (A) <input type="checkbox"/> Right (B)	Date: <u>7/22/93</u>
Assessment Engineer(s)/Inspector(s): <u>R. QUICK T. FRESTON</u>		
Nozzle Subassembly: <u>FORWARD NOSE AND AFT INLET RING</u>		

Record Bondline Adhesive Void Measurements and Locations Below:

Degree Location	Void Size		Location on Bonding Surface	
	Axial	Circ.	Distance From Fwd FACE OF NOSE RING	Distance From Aft
<u>2°</u>	<u>.52</u>	<u>.27</u>	<u>.95</u>	
<u>110°</u>	<u>.37</u>	<u>.26</u>	<u>1.70</u>	
<u>122°</u>	<u>.48</u>	<u>.30</u>	<u>.90</u>	
<u>127°</u>	<u>.36</u>	<u>.21</u>	<u>1.95</u>	
<u>220°</u>	<u>.60</u>	<u>.32</u>	<u>.34</u>	
<u>222°</u>	<u>.41</u>	<u>.28</u>	<u>1.66</u>	
<u>255°</u>	<u>.42</u>	<u>.25</u>	<u>2.30</u>	
<u>318°</u>	<u>.35</u>	<u>.21</u>	<u>.90</u>	
<u>359°</u>	<u>.37</u>	<u>.25</u>	<u>2.20</u>	

Notes / Comments

Corresponding Comment Number(s): \_\_\_\_\_

PFOR CLARIFICATION FORM  
General

Motor No.: RSRM-32      Side: ☒ Left (A)    ☐ Right (B)    Date: 7-22-93

Assessment Engineer(s)/Inspector(s): R. Quick, M. Clark

Description: LDI Datasheet

Sketch Observations Below (include locations and sizes of sketched features):

NOSE CAP TO HOUSING BONDLINE  
(Left Hand)

Degree	Location	Distance <sup>1</sup>		Void or	Axial	Circ.	Other
Recorded	Actual	Recorded	Actual	Repair	Length	Width	Info.
1	81	11.30	6.70	NON FOUND VOID	.38	.25	
16		10.80					NOT FOUND
33		16.85					NOT FOUND
79		7.60					NOT FOUND
163	163	11.10	6.40	VOID	.80	.45	
177	177	10.84	7.85	VOID	.43	.32	
316	316	9.20	8.40	VOID	.45	.40	

NOSE CAP TO FNR BONDLINE  
(Left Hand)

Degree	Location	Distance <sup>2</sup>		Void or	Axial	Circ.	Other
Recorded	Actual	Recorded	Actual	Repair	Length	Width	Info.
19		1.77					NOT FOUND
20		1.70					NOT FOUND
27		2.08	1.20	VOID	.30	.20	
48		1.98	1.20	VOID	.30	.20	
131		1.95	1.30	VOID	.40	.20	
132		2.32	1.70	VOID	.30	.20	
149		2.78	2.00	VOID	.25	.20	
150		1.90					NOT FOUND
157		3.70	1.30	VOID	.20	.10	
283		1.86	1.10	VOID	.30	.20	
306		2.24	1.40	VOID	.30	.20	
314		1.16					NOT FOUND
299		3.12	2.10	VOID	.15	.10	

FNR TO HOUSING BONDLINE  
(Left Hand)

Degree	Location	Distance <sup>3</sup>		Void or	Axial	Circ.	Other
Recorded	Actual	Recorded	Actual	Repair	Length	Width	Info.
110		0.00					NOT FOUND
290		0.00					NOT FOUND

<sup>1</sup> Distance from fwd tip of nose cap glass  
<sup>2</sup> Distance from flame surface  
<sup>3</sup> Distance from FNR - nose cap - housing interface

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Phenolic Bondline - Nose Cap

Motor No.: RSRM-32	Side: Left (A)	Date: 7/22/93
Assessment Engineer(s)/Inspector(s): R. QUICK T. FRESTON		

**Metal Housing Bondline Surface:**

	Yes	No	Comment #
a. Soot?		<input checked="" type="checkbox"/>	
b. Heat affected or eroded metal?		<input checked="" type="checkbox"/>	
c. Voids in adhesive greater than 0.5 inch in any direction?	<input checked="" type="checkbox"/>		
d. Corrosion?	<input checked="" type="checkbox"/>	1 & 2	
e. Foreign material?		<input checked="" type="checkbox"/>	

Note: Axial cuts may be relocated + or - 10 degrees only. Document if any cuts were relocated.

Primary Bondline/Phenolic Failure Mode Percentage (After Hydrolase and Wedge Removal):

	Degree Location							
	0-45	45-90	90-135	135-180	180-225	225-270	270-315	315-0
Metal-to-Adhesive								
Within Adhesive								
Adhesive-to-GCP								
Within GCP								
GCP-to-CCP	100%	100%	100%	100%	100%	100%	100%	100%
Within CCP								

Secondary Bondline Failure Mode Percentage (After Removal of Remaining Phenolics):

	Degree Location								
	0-45	45-90	90-135	135-180	180-225	225-270	270-315	315-0	total
Metal-to-Adhesive	30%	40%	35%	40%	45%	30%	30%	40%	36
Within Adhesive									
Adhesive-to-GCP	70%	60%	65%	60%	55%	70%	70%	60%	64

Phenolic Removal Method: NYLON WEDGE

Notes / Comments: 1-LIGHT TO MEDIUM CORROSION INTERMITTENT FULL CIRCUM  
2-HYDROLAZE EROSION ON AXIAL CUT FWD TIP AT 10° & 250°

Special Issue 3.3.7 NO REPAIRS FOUND, 5 Voids found see below.

Special Issue 3.3.8 VOID AT 132° 1.25" FROM NOSE CAP FACE .43 AXIAL X .20 CIRCUM  
3 SMALL VOIDS AT 283°

Special Issue 3.3.9 VOID AT 10° 6.7" FROM <sup>FORWARD</sup> FWD END .8 AXIAL X .45 CIRCUM, 177° 7.8" FROM FWD END .43 AXIAL X .32 CIRCUM

Preliminary PFAR(s)? ☐ Yes ☒ No Preliminary PFAR Number(s): 316-8.4 X .45 AXIAL X .4 CIRC

Clarification Form(s)? ☐ Yes ☒ No Number of Forms Attached: \_\_\_\_\_

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Phenolic Bondline - Cowl Assembly

Motor No.: RSRM-32      Side: Left (A)      Date: 7/21/91

Assessment Engineer(s)/Inspector(s): JIM PASSMAN, TREVOR FRESTON

Metal Housing Bondline Surface:	Yes	No	Comment #
a. Soot?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
b. Heat affected or eroded metal?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
c. Voids in adhesive greater than 0.5 inch in any direction?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
d. Corrosion?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
e. Foreign material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

Note: Axial cuts may be relocated + or - 10 degrees only. Document if any cuts were relocated.

Primary Bondline/Phenolic Failure Mode Percentage (After Hydrolase and Wedge Removal):

	Degree Location							
	0-45°	45-90°	90-135°	135-180°	180-225°	225-270°	270-315°	315-360°
Metal-to-Adhesive	15	5	2	2	2	5	0	0
Within Adhesive								
Adhesive-to-SCP	85	95	98	93	98	95	100	100
Within SCP				5				
SCP-to-CCP								
Within CCP								

Secondary Bondline Failure Mode Percentage (After Removal of Remaining Phenolics):

	Degree Location							
Metal-to-Adhesive								
Within Adhesive								
Adhesive-to-SCP								

Phenolic Removal Method: \_\_\_\_\_

Notes / Comments: ADHESIVE TO METAL FAILURES WERE LOCATED AT SHIMS OR HYDROLASE CUTS.

Special Issue 3.3.7 NO VOIDS WERE FOUND.

Special Issue 3.3.13 BONDLINE WAS IN GOOD SHAPE. VERY LOW (~4%) METAL TO ADHESIVE FAILURE MODE. 95% ADHESIVE - TO SCP.

Preliminary PFAR(s)? ☐ Yes ☒ No Preliminary PFAR Number(s): \_\_\_\_\_

Clarification Form(s)? ☐ Yes ☒ No Number of Forms Attached: \_\_\_\_\_

**POSTFLIGHT OBSERVATION RECORD (PFOR)**  
**Nozzle Phenolic Bondline - Fixed Housing Assembly**

Motor No.: RSRM-32      Side: Left (A)      Date: 14 JULY 93  
Assessment Engineer(s)/Inspector(s): R. Quick P. MILLER

<u>Metal Housing Bondline Surface:</u>	Yes	No	Comment #
a. Soot?	_____	<input checked="" type="checkbox"/>	_____
b. Heat affected or eroded metal?	_____	<input checked="" type="checkbox"/>	_____
c. Voids in adhesive greater than 0.5 inch in any direction?	<input checked="" type="checkbox"/>	_____	1
d. Corrosion?	_____	<input checked="" type="checkbox"/>	_____
e. Foreign material?	_____	<input checked="" type="checkbox"/>	_____

Note: Axial cuts may be relocated + or - 10 degrees only. Document if any cuts were relocated.

Primary Bondline/Phenolic Failure Mode Percentage (After Hydrolase and Wedge Removal):

	Degree Location							
	0-45	45-90	90-135	135-180	180-225	225-270	270-315	315-0
Metal-to-Adhesive								
Within Adhesive								
Adhesive-to-GCP								
Within GCP	100%	100%	100%	100%	100%	100%	100%	100%
GCP-to-CCP								
Within CCP								

Secondary Bondline Failure Mode Percentage (After Removal of Remaining Phenolics):

	Degree Location								Total
Metal-to-Adhesive					2%				0.25
Within Adhesive									
Adhesive-to-GCP	100%	100%	100%	100%	98%	100%	100%	100%	99.75

Phenolic Removal Method: NYLON WEDGE

**Notes / Comments**

1.60% .4 FROM AFT END 2.6 AXIAL X .60 CIRCUM

90° 1.6 FROM AFT END 1.0 AXIAL X .30 CIRCUM

Special Issue 3.3.2 There was no sign of growth in the areas of the wetlines

Preliminary PFAR(s)? \_\_\_\_\_ Yes ☒ No \_\_\_\_\_ Preliminary PFAR Number(s): \_\_\_\_\_

Clarification Form(s)? \_\_\_\_\_ Yes ☒ No \_\_\_\_\_ Number of Forms Attached: \_\_\_\_\_

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Phenolic Sections - Aft Exit Cone

Motor No.: RSRM-32 Side: Left (A) Date: 8-27-93

Assessment Engineer(s)/Inspector(s): M. Clark

Phenolic Sections:

	Yes	No	Comment #
a. Cross-ply cracking in virgin material?			
b. Ply lifting?			

Aft Exit Cone Char and Erosion Measurements:

Station Location	0°		90°		180°		270°	
	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
73.77	<del>①</del>							
77.77								
83.77				NA				
89.77								
95.77				NA				
101.77								
107.77								
113.77								
118.77								

Negative Margin of Safety? Yes No Station: Degree:

Notes / Comments

Special Issue 3.3.19 Pieces recovered at KSC have been misplaced and have not been assessed

① None of the CCP remained attached to housing to allow measurements to be taken

Preliminary PFAR(s)? Yes No Preliminary PFAR Number(s):

Clarification Form(s)? Yes No Number of Forms Attached:

**POSTFLIGHT OBSERVATION RECORD (PFOR)**  
**Nozzle Phenolic Sections - Forward Exit Cone**

Motor No.: RSRM-32 Side: Left (A) Date: 8-26-93

Assessment Engineer(s)/Inspector(s): L.E. WILKES

**Phenolic Sections:**

- a. Cross-ply cracking in virgin material?  
b. Ply lifting?

Yes	No	Comment #
<u>      </u>	<u>✓</u>	<u>      </u>
<u>      </u>	<u>✓</u>	<u>      </u>

**Forward Exit Cone Char and Erosion Measurements:**

Station Location	0°		90°		180°		270°	
	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
1.0	<u>.37</u>	<u>.75</u>	<u>.37</u>	<u>.76</u>	<u>.33</u>	<u>.78</u>	<u>.36</u>	<u>.76</u>
4.0	<u>.36</u>	<u>.73</u>	<u>.35</u>	<u>.76</u>	<u>.34</u>	<u>.74</u>	<u>.37</u>	<u>.74</u>
4.6	<u>.37</u>	<u>.71</u>	<u>.37</u>	<u>.72</u>	<u>.36</u>	<u>.75</u>	<u>.36</u>	<u>.77</u>
8.0	<u>.35</u>	<u>.71</u>	<u>.37</u>	<u>.68</u>	<u>.35</u>	<u>.70</u>	<u>.35</u>	<u>.74</u>
12.0	<u>.35</u>	<u>.76</u>	<u>.32</u>	<u>.73</u>	<u>.33</u>	<u>.70</u>	<u>.33</u>	<u>.65</u>
16.0	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>
20.0	<u>↓</u>	<u>↓</u>	<u>↓</u>	<u>↓</u>	<u>↓</u>	<u>↓</u>	<u>↓</u>	<u>↓</u>
24.0	<u>NA</u>	<u>NA</u>	<u>↓</u>	<u>↓</u>	<u>↓</u>	<u>↓</u>	<u>↓</u>	<u>↓</u>
28.0	<u>.30</u>	<u>.70</u>	<u>NA</u>	<u>NA</u>	<u>.28</u>	<u>.70</u>	<u>.28</u>	<u>.71</u>
32.0	<u>.21</u>	<u>.75</u>	<u>.19</u>	<u>.78</u>	<u>.25</u>	<u>.68</u>	<u>.19</u>	<u>.82</u>
32.9	<u>.18</u>	<u>.70</u>	<u>.19</u>	<u>.75</u>	<u>.16</u>	<u>.71</u>	<u>.15</u>	<u>.81</u>
34.0	<u>.15</u>	<u>.67</u>	<u>.15</u>	<u>.75</u>	<u>.15</u>	<u>.74</u>	<u>.14</u>	<u>.82</u>

Negative Margin of Safety?        Yes ✓ No        Station:        Degree:       

**Notes / Comments**

Preliminary PFAR(s)?        Yes ✓ No        Preliminary PFAR Number(s):       

Clarification Form(s)?        Yes ✓ No        Number of Forms Attached:

**POSTFLIGHT OBSERVATION RECORD (PFOR)**  
**Nozzle Phenolic Sections - Throat Assembly**

Motor No.: **RSRM-32**      Side: **Left (A)**      Date: **8-26-97**

Assessment Engineer(s)/Inspector(s): **L.E. WILKES**

**Phenolic Sections:**

	Yes	No	Comment #
a. Cross-ply cracking in virgin material?	<u>          </u>	<u>✓</u>	<u>          </u>
b. Ply lifting?	<u>          </u>	<u>✓</u>	<u>          </u>

**Throat Inlet Ring and Throat Ring Char and Erosion Measurements:**

Station	0°		90°		180°		270°	
Location	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
1.0	<u>1.07</u>	<u>.62</u>	<u>1.06</u>	<u>.62</u>	<u>1.06</u>	<u>.68</u>	<u>1.03</u>	<u>.62</u>
2.0	<u>1.11</u>	<u>.71</u>	<u>1.08</u>	<u>.61</u>	<u>1.09</u>	<u>.66</u>	<u>1.07</u>	<u>.65</u>
4.0	<u>1.17</u>	<u>.68</u>	<u>1.14</u>	<u>.68</u>	<u>1.16</u>	<u>.59</u>	<u>1.12</u>	<u>.68</u>
6.0	<u>1.23</u>	<u>.63</u>	<u>1.20</u>	<u>.64</u>	<u>1.20</u>	<u>.64</u>	<u>1.19</u>	<u>.70</u>
8.0	<u>1.25</u>	<u>.50</u>	<u>1.21</u>	<u>.56</u>	<u>1.25</u>	<u>.50</u>	<u>1.23</u>	<u>.55</u>
10.0	<u>1.18</u>	<u>.56</u>	<u>1.19</u>	<u>.54</u>	<u>1.18</u>	<u>.55</u>	<u>1.15</u>	<u>.55</u>
12.0	<u>1.15</u>	<u>.60</u>	<u>1.16</u>	<u>.57</u>	<u>1.14</u>	<u>.62</u>	<u>1.13</u>	<u>.60</u>
14.0	<u>1.13</u>	<u>.62</u>	<u>1.16</u>	<u>.58</u>	<u>1.15</u>	<u>.59</u>	<u>1.13</u>	<u>.56</u>
16.0	<u>1.08</u>	<u>.69</u>	<u>1.05</u>	<u>.68</u>	<u>1.10</u>	<u>.65</u>	<u>1.14</u>	<u>.73</u>
18.0	<u>.96</u>	<u>.78</u>	<u>.95</u>	<u>.76</u>	<u>.96</u>	<u>.68</u>	<u>.94</u>	<u>.66</u>
20.0	<u>.76</u>	<u>.80</u>	<u>.78</u>	<u>.71</u>	<u>.77</u>	<u>.75</u>	<u>.72</u>	<u>.77</u>
22.0	<u>.50</u>	<u>.80</u>	<u>.51</u>	<u>.81</u>	<u>.51</u>	<u>.81</u>	<u>.47</u>	<u>.84</u>
23.0	<u>.44</u>	<u>.82</u>	<u>.47</u>	<u>.80</u>	<u>.44</u>	<u>.80</u>	<u>.41</u>	<u>.82</u>

Negative Margin of Safety?            Yes ✓ No      Station:            Degree:           

**Notes / Comments**

Preliminary PFAR(s)?            Yes ✓ No      Preliminary PFAR Number(s):           

Clarification Form(s)?            Yes ✓ No      Number of Forms Attached:



**POSTFLIGHT OBSERVATION RECORD (PFOR)**  
**Nozzle Phenolic Sections - Forward Nose and Aft Inlet Rings**

Motor No.: RSRM-32 Side: Left (A) Date: 8/26/93

Assessment Engineer(s)/Inspector(s): CLARK, PASSMAN, QUICK, WILKES

Phenolic Sections:	Yes	No	Comment #
a. Cross-ply cracking in virgin material?	<u>      </u>	<u>  ✓  </u>	<u>      </u>
b. Ply lifting?	<u>      </u>	<u>  ✓  </u>	<u>      </u>

**Forward Nose Ring Char and Erosion Measurements:**

Station	0°		90°		180°		270°	
Location	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
28.0	<u>.122</u>	<u>.66</u>	<u>.110</u>	<u>.58</u>	<u>N/A</u>		<u>.115</u>	<u>.67</u>
30.0	<u>.93</u>	<u>.60</u>	<u>.87</u>	<u>.67</u>	<u>.82</u>	<u>.66</u>	<u>.93</u>	<u>.64</u>
32.0	<u>.93</u>	<u>.64</u>	<u>.90</u>	<u>.59</u>	<u>.92</u>	<u>.55</u>	<u>1.01</u>	<u>.66</u>

Negative Margin of Safety?        Yes   ✓   No Station:        Degree:       

**Aft Inlet Ring Char and Erosion Measurements:**

Station	0°		90°		180°		270°	
Location	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
34.0	<u>.88</u>	<u>.61</u>	<u>.83</u>	<u>.60</u>	<u>.90</u>	<u>.53</u>	<u>.87</u>	<u>.63</u>
36.0	<u>.90</u>	<u>.60</u>	<u>.86</u>	<u>.59</u>	<u>.92</u>	<u>.55</u>	<u>.91</u>	<u>.67</u>
38.0	<u>.96</u>	<u>.53</u>	<u>.94</u>	<u>.64</u>	<u>.98</u>	<u>.56</u>	<u>.98</u>	<u>.72</u>
39.0	<u>.99</u>	<u>.56</u>	<u>.94</u>	<u>.56</u>	<u>1.00</u>	<u>.61</u>	<u>1.01</u>	<u>.70</u>

Negative Margin of Safety?        Yes   ✓   No Station:        Degree:       

**Notes / Comments**

Preliminary PFAR(s)?        Yes   ✓   No Preliminary PFAR Number(s):       

Clarification Form(s)?        Yes   ✓   No Number of Forms Attached:

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Phenolic Sections - Nose Cap

Motor No.: RSRM-32 Side: Left (A) Date: 8/25/93

Assessment Engineer(s)/Inspector(s): CLARK, PASSMAN, QUICK, WILKES

Phenolic Sections:	Yes	No	Comment #
a. Cross-ply cracking in virgin material?	<u>      </u>	<u>  v  </u>	<u>      </u>
b. Ply lifting?	<u>      </u>	<u>  v  </u>	<u>      </u>

Nose Cap Char and Erosion Measurements:

Station	0°		90°		180°		270°	
Location	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
1.5	<u>.29</u>	<u>.50</u>	<u>.74*</u>		<u>.70*</u>		<u>.85*</u>	
4.0	<u>.40</u>	<u>.48</u>	<u>.40</u>	<u>.43</u>	<u>.32</u>	<u>.51</u>	<u>.33</u>	<u>.56</u>
6.0	<u>.41</u>	<u>.53</u>	<u>.42</u>	<u>.48</u>	<u>.33</u>	<u>.53</u>	<u>.37</u>	<u>.47</u>
8.0	<u>.49</u>	<u>.51</u>	<u>.44</u>	<u>.49</u>	<u>.44</u>	<u>.39</u>	<u>.43</u>	<u>.49</u>
10.0	<u>.56</u>	<u>.47</u>	<u>.50</u>	<u>.48</u>	<u>.45</u>	<u>.45</u>	<u>.49</u>	<u>.50</u>
12.0	<u>.58</u>	<u>.51</u>	<u>.48</u>	<u>.49</u>	<u>.45</u>	<u>.49</u>	<u>.49</u>	<u>.50</u>
14.0	<u>.70</u>	<u>.44</u>	<u>.65</u>	<u>.51</u>	<u>.58</u>	<u>.42</u>	<u>.59</u>	<u>.48</u>
16.0	<u>.78</u>	<u>.46</u>	<u>.69</u>	<u>.43</u>	<u>.61</u>	<u>.46</u>	<u>.62</u>	<u>.45</u>
18.0	<u>.94</u>	<u>.44</u>	<u>.81</u>	<u>.38</u>	<u>.76</u>	<u>.41</u>	<u>.71</u>	<u>.47</u>
20.0	<u>1.15</u>	<u>.51</u>	<u>1.05</u>	<u>.39</u>	<u>.93</u>	<u>.47</u>	<u>.95</u>	<u>.47</u>
22.0	<u>1.79</u>	<u>.63</u>	<u>1.69</u>	<u>.55</u>	<u>1.57</u>	<u>.63</u>	<u>1.49</u>	<u>.88</u>
24.0	<u>1.94</u>	<u>.70</u>	<u>1.79</u>	<u>.71</u>	<u>1.76</u>	<u>.78</u>	<u>1.85</u>	<u>.89</u>
26.0	<u>1.40</u>	<u>.70</u>	<u>1.27</u>	<u>.76</u>	<u>1.30</u>	<u>.77</u>	<u>1.45</u>	<u>.79</u>

Negative Margin of Safety?        Yes   v   No Station:        Degree:       

Notes / Comments \*DENOTES MAX AFFECTE DEPTH

Preliminary PFAR(s)?        Yes   v   No Preliminary PFAR Number(s):       

Clarification Form(s)?        Yes   v   No Number of Forms Attached:

POSTFLIGHT OBSERVATION RECORD (PFOR)

Nozzle Phenolic Sections - Cowl

Motor No.: RSRM-32

Side: Left (A)

Date: 5-22-77

Assessment Engineer(s)/Inspector(s): L.E. WILKES

Phenolic Sections:

Yes

No

Comment #

a. Cross-ply cracking in virgin material?

b. Ply lifting?

Cowl Char and Erosion Measurements:

Station	0°		90°		180°		270°	
Location	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
0.3	.30	.80	.31	.72	.30	.71	.28	.78
1.0	.29	.73	.32	.66	.27	.68	.26	.70
2.0	.27	.69	.25	.68	.23	.62	.22	.67
3.0	.26	.65	.22	.69	.20	.66	.21	.71
4.0	.24	.62	.19	.68	.18	.63	.18	.72
5.0	.20	.78	.18	.72	.15	.69	.16	.71
6.0	.16	.70	.15	.67	.14	.76	.14	.70
6.8	.25	.82	.15	.87	.18	.82	.23	.82

Negative Margin of Safety? \_\_\_\_\_

Yes

No

Station: \_\_\_\_\_

Degree: \_\_\_\_\_

Notes / Comments

Special Issue 3.3.17

POST FLIGHT COWL CCR COMPARISON AFTER FLIGHT  
OF THE FLIGHT NO. 112222. NO PLY LIFTING.

Preliminary PFAR(s)? \_\_\_\_\_

Yes

No

Preliminary PFAR Number(s): \_\_\_\_\_

Clarification Form(s)? \_\_\_\_\_

Yes

No

Number of Forms Attached: \_\_\_\_\_

REVISION \_\_\_\_\_

DOC NO. TWR-64240

VOL \_\_\_\_\_

SEC \_\_\_\_\_

PAGE A-45

ORIGINAL PAGE IS  
OF POOR QUALITY

**POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Phenolic Sections - Fixed Housing**

Motor No.: RSRM-32      Side: Left (A)      Date: 8-26-93

Assessment Engineer(s)/Inspector(s): L.E. WILKES

Phenolic Sections:	Yes	No	Comment #
a. Cross-ply cracking in virgin material?	<u>          </u>	<u>✓</u>	<u>          </u>
b. Ply lifting?	<u>          </u>	<u>✓</u>	<u>          </u>

**Fixed Housing Char and Erosion Measurements:**

Station	0°		90°		180°		270°	
Location	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
0.0	<u>.08</u>	<u>1.20</u>	<u>.05</u>	<u>1.12</u>	<u>.04</u>	<u>1.13</u>	<u>.00</u>	<u>1.21</u>
1.0	<u>.04</u>	<u>1.13</u>	<u>.06</u>	<u>1.06</u>	<u>.02</u>	<u>1.03</u>	<u>.01</u>	<u>1.08</u>
2.0	<u>.00</u>	<u>1.07</u>	<u>.01</u>	<u>.96</u>	<u>.02</u>	<u>1.10</u>	<u>.04</u>	<u>1.00</u>
3.0	<u>.03</u>	<u>.97</u>	<u>.01</u>	<u>.97</u>	<u>.00</u>	<u>1.13</u>	<u>.03</u>	<u>1.05</u>
4.0	<u>.03</u>	<u>1.01</u>	<u>.01</u>	<u>.93</u>	<u>.01</u>	<u>1.07</u>	<u>.04</u>	<u>1.02</u>
5.0	<u>.01</u>	<u>1.00</u>	<u>.01</u>	<u>.91</u>	<u>.00</u>	<u>1.04</u>	<u>.03</u>	<u>1.01</u>
6.0	<u>.01</u>	<u>1.04</u>	<u>.00</u>	<u>.95</u>	<u>.00</u>	<u>1.04</u>	<u>.05</u>	<u>1.00</u>
7.0	<u>.01</u>	<u>1.02</u>	<u>.00</u>	<u>.92</u>	<u>.01</u>	<u>.99</u>	<u>.00</u>	<u>.96</u>
8.0	<u>.00</u>	<u>.92</u>	<u>.00</u>	<u>.78</u>	<u>.00</u>	<u>.86</u>	<u>.00</u>	<u>.93</u>
9.0	<u>.00</u>	<u>.93</u>	<u>NA</u>	<u>.73*</u>	<u>.00</u>	<u>.83</u>	<u>.00</u>	<u>.78</u>
10.75	<u>.02</u>	<u>1.84</u>	<u>NA</u>	<u>1.84*</u>	<u>.15</u>	<u>1.45</u>	<u>.00</u>	<u>1.73</u>

Negative Margin of Safety?            Yes ✓ No      Station:            Degree:           

Notes / Comments \* TOTAL HEAT AFFECTED DEPTH (CHAR LINE)

Special Issue 3.3.2 SEE PFOR PAGE A-24.

Preliminary PFAR(s)?            Yes ✓ No      Preliminary PFAR Number(s):           

Verification Form(s)?            Yes ✓ No      Number of Forms Attached:           

REVISION           

DOC NO. TWR-64240 | VOL             
SEC            | PAGE A-46

ORIGINAL PAGE 15  
(5) POOR QUALITY

**POSTFLIGHT OBSERVATION RECORD (PFOR)**  
**Nozzle Phenolic Sections - Outer Boot Ring and Flexible Boot**

Motor No.: RSRM-32 Side: Left (A) Date: 8-24-83

Assessment Engineer(s)/Inspector(s): L.E. WHITE

<u>Phenolic Sections:</u>	Yes	No	Comment #
a. Cross-ply cracking in virgin material?	<u>          </u>	<u>✓</u>	<u>          </u>
b. Ply lifting?	<u>          </u>	<u>✓</u>	<u>          </u>

<u>Flexible Boot/Outer Boot Ring Interface:</u>	Yes	No	Comment #
c. Separations?	<u>✓</u>	<u>          </u>	<u>1</u>
d. Heat effects in separations (if present)?	<u>          </u>	<u>✓</u>	<u>          </u>

**Outer Boot Ring Char and Erosion Measurements:**

Station	0°		90°		180°		270°	
Location	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
8.0	<u>.10</u>	<u>.92</u>	<u>.10</u>	<u>.82</u>	<u>.07</u>	<u>.25</u>	<u>.14</u>	<u>.92</u>
9.0	<u>.09</u>	<u>.91</u>	<u>.10</u>	<u>.80</u>	<u>.03</u>	<u>.94</u>	<u>.05</u>	<u>1.01</u>
10.0	<u>.05</u>	<u>.90</u>	<u>.05</u>	<u>.79</u>	<u>.01</u>	<u>.92</u>	<u>.04</u>	<u>.94</u>
11.3	<u>.07</u>	<u>.92</u>	<u>.07</u>	<u>.81</u>	<u>.00</u>	<u>.25</u>	<u>.05</u>	<u>          </u>

Negative Margin of Safety?            Yes ✓ No Station:            Degree:           

**Number of Plies Remaining on the Flexible Boot:**

Degree	Plies
Location	Remaining
0	<u>3.7</u>
90	<u>3.2</u>
180	<u>3.5</u>
270	<u>3.1</u>

Negative Margin of Safety?            Yes            No Degree:           

Notes / Comments ① SEPARATIONS WERE OBSERVED AT 0° AND 270° SECTIONS. BUT NO HEAT EFFECTS WERE FOUND IN SEPARATIONS.

Preliminary PFAR(s)?            Yes ✓ No Preliminary PFAR Number(s):           

Clarification Form(s)?            Yes ✓ No Number of Forms Attached:

**POSTFLIGHT OBSERVATION RECORD (PFOR)**  
**Barrier-Booster Leak Check Port Plug and Port (At Removal) - 126 Degrees**

Motor No.: RSRM-32	Side: Left (A)	Date: 7-9-93
Assessment Engineer(s)/Inspector(s): S. Eden, M. Lyon, C. Taylor, L. MacCauley		
<b>Leak Check Port Plug and Port:</b> a. Soot to or past O-ring? b. Sooted surfaces? c. Heat affected or eroded O-ring (installed)? d. O-ring damage (installed)? e. Heat affected or eroded metal? f. Foreign material? g. Excessive grease? h. Medium or heavy corrosion? i. Metal damage?	Yes _____ _____ _____ _____ _____ _____ _____ _____ _____	No ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓
		Comment # _____ _____ _____ _____ _____ _____ _____ _____ _____
Notes / Comments		
Preliminary PFAR(s)?    Yes <input checked="" type="checkbox"/> No    Preliminary PFAR Number(s): _____ Clarification Form(s)?    Yes <input checked="" type="checkbox"/> No    Number of Forms Attached: _____		

POSTFLIGHT OBSERVATION RECORD (PFOR)

Barrier-Booster Leak Check Port Plug and O-ring (Detailed) - 126 Degrees

Motor No.: RSRM-32

Side: Left (A)

Date: 7-9-93

Assessment Engineer(s)/Inspector(s): S. Eden, M. Lyon, C. Taylor, L. MacCauley

Leak Check Port Plug:

Yes

No

Comment #

a. Foreign material between the O-ring and plug?

\_\_\_\_\_

☒

\_\_\_\_\_

b. Heat affected or eroded metal?

\_\_\_\_\_

☒

\_\_\_\_\_

c. Seal surface/thread damage?

\_\_\_\_\_

☒

\_\_\_\_\_

Secondary O-ring:

d. Heat affected or eroded O-ring?

\_\_\_\_\_

☒

\_\_\_\_\_

e. O-ring defects/damage?

\_\_\_\_\_

☒

\_\_\_\_\_

Notes / Comments

Preliminary PFAR(s)? \_\_\_\_\_ Yes ☒ No

Preliminary PFAR Number(s): \_\_\_\_\_

Clarification Form(s)? \_\_\_\_\_ Yes ☒ No

Number of Forms Attached: \_\_\_\_\_

REVISION \_\_\_\_\_

DOC NO. TWR-64240  
SEC \_\_\_\_\_

VOL \_\_\_\_\_

PAGE A-49

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Internal Joint Leak Check Port Plug and Port (At Removal) - Joint 2

Motor No.: RSRM-32

Side: Left (A)

Date: 7-9-93

Assessment Engineer(s)/Inspector(s): W Sperry, M. Offelter

Leak Check Port Plug and Port:

- a. Soot to or past O-ring?
- b. Sooted surfaces?
- c. Heat affected or eroded O-ring (installed)?
- d. O-ring damage (installed)?
- e. Heat affected or eroded metal?
- f. Foreign material?
- g. Excessive grease?
- h. Medium or heavy corrosion?
- i. Metal damage?

Yes

No

Comment #

<input type="checkbox"/>	<input checked="" type="checkbox"/>	
<input type="checkbox"/>	<input checked="" type="checkbox"/>	
<input type="checkbox"/>	<input checked="" type="checkbox"/>	
<input type="checkbox"/>	<input checked="" type="checkbox"/>	
<input type="checkbox"/>	<input checked="" type="checkbox"/>	
<input type="checkbox"/>	<input checked="" type="checkbox"/>	
<input type="checkbox"/>	<input checked="" type="checkbox"/>	
<input type="checkbox"/>	<input checked="" type="checkbox"/>	
<input type="checkbox"/>	<input checked="" type="checkbox"/>	

Plug Break-away and Running Torques (inch-lbs):

Break-away:

35

Running:

7

Notes / Comments

Preliminary PFAR(s)? ☐ Yes ☒ No

Preliminary PFAR Number(s): \_\_\_\_\_

Clarification Form(s)? ☐ Yes ☒ No

Number of Forms Attached: \_\_\_\_\_

REVISION \_\_\_\_\_



POSTFLIGHT OBSERVATION RECORD (PFOR)

Nozzle Internal Joint Leak Check Port Plug and O-ring (Detailed) - Joint 2

Motor No.: RSRM-32

Side: Left (A)

Date: 7-9-93

Assessment Engineer(s)/Inspector(s): W. Sperry, M. Offolter

Leak Check Port Plug:

Yes

No

Comment #

a. Foreign material between the O-ring and plug?

\_\_\_\_\_

☒

\_\_\_\_\_

b. Heat affected or eroded metal?

\_\_\_\_\_

☒

\_\_\_\_\_

c. Seal surface/thread damage?

\_\_\_\_\_

☒

\_\_\_\_\_

Secondary O-ring:

d. Heat affected or eroded O-ring?

\_\_\_\_\_

☒

\_\_\_\_\_

e. O-ring defects/damage?

\_\_\_\_\_

☒

\_\_\_\_\_

Notes / Comments

Preliminary PFAR(s)? \_\_\_\_\_ Yes ☒ No

Preliminary PFAR Number(s): \_\_\_\_\_

Clarification Form(s)? \_\_\_\_\_ Yes ☒ No

Number of Forms Attached: \_\_\_\_\_

REVISION \_\_\_\_\_

DOC NO. TWR-64240  
SEC \_\_\_\_\_

VOL \_\_\_\_\_  
PAGE A-51

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Internal Joint Leak Check Port Plug and Port (At Removal) - Joint 3

Motor No.: RSRM-32

Side: Left (A)

Date: 7-9-93

Assessment Engineer(s)/Inspector(s): W. SPERRY, M. OFFELTER

Leak Check Port Plug and Port:

Yes

No

Comment #

- a. Soot to or past O-ring?
- b. Sooted surfaces?
- c. Heat affected or eroded O-ring (installed)?
- d. O-ring damage (installed)?
- e. Heat affected or eroded metal?
- f. Foreign material?
- g. Excessive grease?
- h. Medium or heavy corrosion?
- i. Metal damage?

Yes	No	Comment #
<input type="checkbox"/>	<input checked="" type="checkbox"/>	
<input type="checkbox"/>	<input checked="" type="checkbox"/>	
<input type="checkbox"/>	<input checked="" type="checkbox"/>	
<input type="checkbox"/>	<input checked="" type="checkbox"/>	
<input type="checkbox"/>	<input checked="" type="checkbox"/>	
<input type="checkbox"/>	<input checked="" type="checkbox"/>	
<input type="checkbox"/>	<input checked="" type="checkbox"/>	
<input type="checkbox"/>	<input checked="" type="checkbox"/>	
<input type="checkbox"/>	<input checked="" type="checkbox"/>	

Plug Break-away and Running Torques (inch-lbs):

Break-away: 40 in-lb

Running: 10

Notes / Comments

Preliminary PFAR(s)? ☐ Yes ☒ No

Preliminary PFAR Number(s):

Clarification Form(s)? ☐ Yes ☒ No

Number of Forms Attached:

REVISION

POSTFLIGHT OBSERVATION RECORD (PFOR)

Nozzle Internal Joint Leak Check Port Plug and O-ring (Detailed) - Joint 3

Motor No.: RSRM-32

Side: Left (A)

Date: 7-9-93

Assessment Engineer(s)/Inspector(s): W. Sperry, M. Offalter, B. Ferguson

Leak Check Port Plug:

Yes

No

Comment #

a. Foreign material between the O-ring and plug?

\_\_\_\_\_

☒

\_\_\_\_\_

b. Heat affected or eroded metal?

\_\_\_\_\_

☒

\_\_\_\_\_

c. Seal surface/thread damage?

\_\_\_\_\_

☒

\_\_\_\_\_

Secondary O-ring:

d. Heat affected or eroded O-ring?

\_\_\_\_\_

☒

\_\_\_\_\_

e. O-ring defects/damage?

\_\_\_\_\_

☒

\_\_\_\_\_

Notes / Comments

Preliminary PFAR(s)? \_\_\_\_\_ Yes ☒ No

Preliminary PFAR Number(s): \_\_\_\_\_

Clarification Form(s)? \_\_\_\_\_ Yes ☒ No

Number of Forms Attached: \_\_\_\_\_

REVISION \_\_\_\_\_

DOC NO. TWR-64240

VOL \_\_\_\_\_

SEC \_\_\_\_\_

PAGE A-53

POSTFLIGHT OBSERVATION RECORD (PFOR)

Nozzle Internal Joint Leak Check Port Plug and Port (At Removal) - Joint 4

Motor No.: RSRM-32	Side: Left (A)	Date: 7 July 1993
Assessment Engineer(s)/Inspector(s): A. Carlisle, B. Quick, M. Lyons, J. Richards		
<b>Leak Check Port Plug and Port:</b>		
	Yes	No
a. Soot to or past O-ring?	_____	✓ _____
b. Sooted surfaces?	_____	✓ _____
c. Heat affected or eroded O-ring (installed)?	_____	✓ _____
d. O-ring damage (installed)?	_____	✓ _____
e. Heat affected or eroded metal?	_____	✓ _____
f. Foreign material?	_____	✓ _____
g. Excessive grease?	_____	✓ _____
h. Medium or heavy corrosion?	_____	✓ _____
i. Metal damage?	_____	✓ _____
Plug Break-away and Running Torques (inch-lbs):		Break-away: 42
		Running: 5
Notes / Comments		
Preliminary PFAR(s)? _____ Yes <input checked="" type="checkbox"/> No _____		
Preliminary PFAR Number(s): _____		
Clarification Form(s)? _____ Yes <input checked="" type="checkbox"/> No _____		
Number of Forms Attached: _____		

POSTFLIGHT OBSERVATION RECORD (PFOR)

Nozzle Internal Joint Leak Check Port Plug and O-ring (Detailed) - Joint 4

Motor No.: RSRM-32	Side: Left (A)	Date: 3 July 1993	
Assessment Engineer(s)/Inspector(s): A. Carlisle, B. Quirk, M. Lyons, J. Richards			
<u>Leak Check Port Plug:</u>	Yes	No	Comment #
a. Foreign material between the O-ring and plug?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="text"/>
b. Heat affected or eroded metal?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="text"/>
c. Seal surface/thread damage?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="text"/>
<u>Secondary O-ring:</u>			
d. Heat affected or eroded O-ring?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="text"/>
e. O-ring defects/damage?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="text"/>
Notes / Comments			
Preliminary PFAR(s)? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Preliminary PFAR Number(s): <input type="text"/>			

Clarification Form(s)? ☐ Yes ☒ No Number of Forms Attached:

REVISION

DOC NO. TWR-64240	VOL
SEC	PAGE A-55

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Internal Joint Leak Check Port Plug and Port (At Removal) - Joint 5

Motor No.: RSRM-32	Side: Left (A)	Date: 8 JUL 1993
--------------------	----------------	------------------

Assessment Engineer(s)/Inspector(s): A. Carlyle, M. Lyons, J. Richards

Leak Check Port Plug and Port:

	Yes	No	Comment #
a. Soot to or past O-ring?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
b. Sooted surfaces?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
c. Heat affected or eroded O-ring (installed)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
d. O-ring damage (installed)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
e. Heat affected or eroded metal?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
f. Foreign material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
g. Excessive grease?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
h. Medium or heavy corrosion?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
i. Metal damage?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

Plug Break-away and Running Torques (inch-lbs):

Break-away:

37

Running:

10

Notes / Comments

Preliminary PFAR(s)? ☐ Yes ☒ No

Preliminary PFAR Number(s): \_\_\_\_\_

Clarification Form(s)? ☐ Yes ☒ No

Number of Forms Attached: \_\_\_\_\_

REVISION \_\_\_\_\_

DOC NO. TWR-64240 VOL  
SEC PAGE A-56

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Internal Joint Leak Check Port Plug and O-ring (Detailed) - Joint 5

Motor No.: RSRM-32	Side: Left (A)	Date: 8 JUL 1993																								
Assessment Engineer(s)/Inspector(s): A. Carlisle, M. Lyons, J. Richards																										
<p><b>Leak Check Port Plug:</b></p> <table style="width: 100%;"> <thead> <tr> <th></th> <th style="text-align: center;">Yes</th> <th style="text-align: center;">No</th> <th style="text-align: center;">Comment #</th> </tr> </thead> <tbody> <tr> <td>a. Foreign material between the O-ring and plug?</td> <td style="text-align: center;">_____</td> <td style="text-align: center;">✓ _____</td> <td style="text-align: center;">_____</td> </tr> <tr> <td>b. Heat affected or eroded metal?</td> <td style="text-align: center;">_____</td> <td style="text-align: center;">✓ _____</td> <td style="text-align: center;">_____</td> </tr> <tr> <td>c. Seal surface/thread damage?</td> <td style="text-align: center;">_____</td> <td style="text-align: center;">✓ _____</td> <td style="text-align: center;">_____</td> </tr> </tbody> </table> <p><b>Secondary O-ring:</b></p> <table style="width: 100%;"> <tbody> <tr> <td>d. Heat affected or eroded O-ring?</td> <td style="text-align: center;">_____</td> <td style="text-align: center;">✓ _____</td> <td style="text-align: center;">_____</td> </tr> <tr> <td>e. O-ring defects/damage?</td> <td style="text-align: center;">_____</td> <td style="text-align: center;">✓ _____</td> <td style="text-align: center;">_____</td> </tr> </tbody> </table>				Yes	No	Comment #	a. Foreign material between the O-ring and plug?	_____	✓ _____	_____	b. Heat affected or eroded metal?	_____	✓ _____	_____	c. Seal surface/thread damage?	_____	✓ _____	_____	d. Heat affected or eroded O-ring?	_____	✓ _____	_____	e. O-ring defects/damage?	_____	✓ _____	_____
	Yes	No	Comment #																							
a. Foreign material between the O-ring and plug?	_____	✓ _____	_____																							
b. Heat affected or eroded metal?	_____	✓ _____	_____																							
c. Seal surface/thread damage?	_____	✓ _____	_____																							
d. Heat affected or eroded O-ring?	_____	✓ _____	_____																							
e. O-ring defects/damage?	_____	✓ _____	_____																							
<p>Notes / Comments</p>																										
<p>Preliminary PFAR(s)? _____ Yes    ✓ _____ No    Preliminary PFAR Number(s): _____</p>																										
<p>Clarification Form(s)? _____ Yes    ✓ _____ No    Number of Forms Attached: _____</p>																										

REVISION \_\_\_\_\_

DOC NO. TWR-64240	VOL	
SEC _____	PAGE	A-57





POSTFLIGHT OBSERVATION RECORD (PFOR)  
Case Factory Joint - Forward Cylinder/Cylinder

Motor No.: RSRM-32	Side: Left (A)	Date: 21 SEP 1993
--------------------	----------------	-------------------

Assessment Engineer(s)/Inspector(s): Birch

Joint Seals and Metal:

	Yes	No	Comment #
a. Heat affected or eroded O-ring?	_____	<u>X</u> _____	_____
b. Heavy corrosion (pitting) in joint?	_____	<u>X</u> _____	_____
c. Heavy corrosion (pitting) in leak check port?	_____	<u>X</u> _____	_____

Note: Remove corrosion to determine if pitting has occurred. Care should be taken not to damage the hardware. Solvent and/or green Scotch-Brite® pads may be used to remove the corrosion. Corrosion removal is to be done in a circumferential direction only.

Notes / Comments

Preliminary PFAR(s)? \_\_\_\_\_ Yes X No Preliminary PFAR Number(s): \_\_\_\_\_

Clarification Form(s)? \_\_\_\_\_ Yes X No Number of Forms Attached: \_\_\_\_\_

REVISION \_\_\_\_\_

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Case Factory Joint - Forward Center

Motor No.: RSRM-32

Side: Left (A)

Date: 09-28-93

Assessment Engineer(s)/Inspector(s): A. ZAREMBA

Joint Seals and Metal:

Yes

No

Comment #

a. Heat affected or eroded O-ring?

\_\_\_\_\_

X

\_\_\_\_\_

b. Heavy corrosion (pitting) in joint?

\_\_\_\_\_

X

\_\_\_\_\_

c. Heavy corrosion (pitting) in leak check port?

\_\_\_\_\_

X

\_\_\_\_\_

Note: Remove corrosion to determine if pitting has occurred. Care should be taken not to damage the hardware. Solvent and/or green Scotch-Brite® pads may be used to remove the corrosion. Corrosion removal is to be done in a circumferential direction only.

Notes / Comments

Preliminary PFAR(s)? \_\_\_\_\_ Yes X No

Preliminary PFAR Number(s): \_\_\_\_\_

Clarification Form(s)? \_\_\_\_\_ Yes X No

Number of Forms Attached: \_\_\_\_\_

REVISION \_\_\_\_\_

DOC NO. TWR-64240 VOL  
SEC PAGE A-60

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Case Factory Joint - Aft Center

Motor No.: RSRM-32	Side: Left (A)	Date: 9-22-93
--------------------	----------------	---------------

Assessment Engineer(s)/Inspector(s): G RICH

Joint Seals and Metal:

- a. Heat affected or eroded O-ring?
- b. Heavy corrosion (pitting) in joint?
- c. Heavy corrosion (pitting) in leak check port?

Yes

No

Comment #

\_\_\_\_\_

✓

\_\_\_\_\_

\_\_\_\_\_

✓

\_\_\_\_\_

\_\_\_\_\_

✓

\_\_\_\_\_

Note: Remove corrosion to determine if pitting has occurred. Care should be taken not to damage the hardware. Solvent and/or green Scotch-Brite® pads may be used to remove the corrosion. Corrosion removal is to be done in a circumferential direction only.

Notes / Comments

NONE

Preliminary PFAR(s)? \_\_\_\_\_ Yes \_\_\_\_\_ No Preliminary PFAR Number(s): \_\_\_\_\_

Clarification Form(s)? \_\_\_\_\_ Yes \_\_\_\_\_ No Number of Forms Attached: \_\_\_\_\_

REVISION \_\_\_\_\_

DOC NO. TWR-64240 VOL  
SEC PAGE A-61

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Case Factory Joint - ET Attach/Stiffener

Motor No.: RSRM-32	Side: Left (A)	Date: 9-1-93
--------------------	----------------	--------------

Assessment Engineer(s)/Inspector(s): C. R. R. R.

Joint Seals and Metal:

- a. Heat affected or eroded O-ring?  
b. Heavy corrosion (pitting) in joint?  
c. Heavy corrosion (pitting) in leak check port?

Yes

No

Comment #

\_\_\_\_\_

✓

\_\_\_\_\_

\_\_\_\_\_

✓

\_\_\_\_\_

\_\_\_\_\_

✓

\_\_\_\_\_

Note: Remove corrosion to determine if pitting has occurred. Care should be taken not to damage the hardware. Solvent and/or green Scotch-Brite® pads may be used to remove the corrosion. Corrosion removal is to be done in a circumferential direction only.

Notes / Comments

Preliminary PFAR(s)? \_\_\_\_\_ Yes ✓ No

Preliminary PFAR Number(s): \_\_\_\_\_

Clarification Form(s)? \_\_\_\_\_ Yes ✓ No

Number of Forms Attached: \_\_\_\_\_

REVISION \_\_\_\_\_

DOC NO. TWR-64240 VOL  
SEC PAGE A-62

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Case Factory Joint - Stiffener/Stiffener

Motor No.: RSRM-32	Side: Left (A)	Date: 9-1-93
Assessment Engineer(s)/Inspector(s): G RICH		
<b>Joint Seals and Metal:</b>		
	Yes	No
a. Heat affected or eroded O-ring?	_____	_____✓
b. Heavy corrosion (pitting) in joint?	_____	_____✓
c. Heavy corrosion (pitting) in leak check port?	_____	_____✓
<p>Note: Remove corrosion to determine if pitting has occurred. Care should be taken not to damage the hardware. Solvent and/or green Scotch-Brite® pads may be used to remove the corrosion. Corrosion removal is to be done in a circumferential direction only.</p>		
Notes / Comments		
Preliminary PFAR(s)? _____ Yes _____✓ No Preliminary PFAR Number(s): _____		
Clarification Form(s)? _____ Yes _____✓ No Number of Forms Attached: _____		



POSTFLIGHT OBSERVATION RECORD (PFOR)  
S&A Device (Barrier-Booster and Environmental Seal Regions)

Motor No.: RSRM-32	Side: Right (B)	Date: 7/9/93
--------------------	-----------------	--------------

Assessment Engineer(s)/Inspector(s): Eden / Nolan

Barrier-Booster Bore and Rotor:

	Yes	No	Comment #
a. Soot to or past O-rings?	<input checked="" type="checkbox"/>		①
b. Sooted metal surfaces?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	①
c. Heat affected or eroded O-ring (installed)?		<input checked="" type="checkbox"/>	
d. O-ring damage (installed)?		<input checked="" type="checkbox"/>	
e. Foreign material?		<input checked="" type="checkbox"/>	
f. Heat affected or eroded metal?		<input checked="" type="checkbox"/>	
g. Metal damage?		<input checked="" type="checkbox"/>	
h. Excessive grease?		<input checked="" type="checkbox"/>	
i. Corrosion?		<input checked="" type="checkbox"/>	
j. Teflon retainer damage?		<input checked="" type="checkbox"/>	

Environmental Seal Regions:

k. Environmental O-ring assembly damage (visible without magnification)?		<input checked="" type="checkbox"/>	
l. Foreign material?		<input checked="" type="checkbox"/>	

Notes / Comments

① Typical pressure to primary O-ring #1 with associated sooting.

Preliminary PFAR(s)? ☐ Yes ☒ No Preliminary PFAR Number(s): \_\_\_\_\_

Clarification Form(s)? ☐ Yes ☒ No Number of Forms Attached: \_\_\_\_\_

POSTFLIGHT OBSERVATION RECORD (PFOR)  
S&A Rotor Shaft O-rings (Detailed)

Motor No.: RSRM-32	Side: Right (B)	Date: 7/9/93
Assessment Engineer(s)/Inspector(s): Eden / Nolan		
<u>Forward Primary O-ring:</u>	Yes	No
a. Heat affected or eroded O-ring?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
b. O-ring defects/damage?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
<u>Aft Primary O-ring:</u>		
c. Heat affected or eroded O-ring?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
d. O-ring defects/damage?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
<u>Forward Secondary O-ring:</u>		
e. Heat affected or eroded O-ring?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
f. O-ring defects/damage?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
<u>Aft Secondary O-ring:</u>		
g. Heat affected or eroded O-ring?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
h. O-ring defects/damage?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Notes / Comments		
Preliminary PFAR(s)? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		
Preliminary PFAR Number(s): _____		
Clarification Form(s)? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		
Number of Forms Attached: _____		



POSTFLIGHT OBSERVATION RECORD (PFOR)  
SII and Port (At Removal) - 18 Degrees

Motor No.: RSRM-32	Side: Right (B)	Date: 7/9/93
Assessment Engineer(s)/Inspector(s): Eden/Nolan		
<u>SII and Port:</u>	Yes	No
a. Soot to or past O-ring?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
b. Sooted surfaces?	<input checked="" type="checkbox"/>	<input type="checkbox"/>
c. Heat affected or eroded O-ring (installed)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
d. O-ring damage (installed)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
e. Eroded metal?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
f. Foreign material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
g. Excessive grease?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
h. Medium or heavy corrosion?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
i. Metal damage?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Notes / Comments		
typical soot to the 2 <sup>nd</sup> thread. and tip of SII.		
Preliminary PFAR(s)? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		
Preliminary PFAR Number(s): _____		
Clarification Form(s)? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		
Number of Forms Attached: _____		

POSTFLIGHT OBSERVATION RECORD (PFOR)

SII and O-rings (Detailed) - 18 Degrees

Motor No.: RSRM-32

Side: Right (B)

Date: 7/9/93

Assessment Engineer(s)/Inspector(s): Eden / Nolan

SII:

Yes

No

Comment #

a. Foreign material between the O-ring and SII?

\_\_\_\_\_

☒

\_\_\_\_\_

b. Eroded metal?

\_\_\_\_\_

☒

\_\_\_\_\_

c. Seal surface/thread damage?

\_\_\_\_\_

☒

\_\_\_\_\_

Primary O-ring:

d. Heat affected or eroded O-ring?

\_\_\_\_\_

☒

\_\_\_\_\_

e. O-ring defects/damage?

\_\_\_\_\_

☒

\_\_\_\_\_

Secondary O-ring:

f. Heat affected or eroded O-ring?

\_\_\_\_\_

☒

\_\_\_\_\_

g. O-ring defects/damage?

\_\_\_\_\_

☒

\_\_\_\_\_

Notes / Comments

Preliminary PFAR(s)? \_\_\_\_\_ Yes ☒ No

Preliminary PFAR Number(s): \_\_\_\_\_

Clarification Form(s)? \_\_\_\_\_ Yes ☒ No

Number of Forms Attached: \_\_\_\_\_

REVISION \_\_\_\_\_

DOC NO. TWR-64240

VOL \_\_\_\_\_

SEC \_\_\_\_\_

PAGE A-68

POSTFLIGHT OBSERVATION RECORD (PFOR)  
SII and Port (At Removal) - 198 Degrees

Motor No.: RSRM-32	Side: Right (B)	Date: 7/9/93
--------------------	-----------------	--------------

Assessment Engineer(s)/Inspector(s): Eden / Nolan

SII and Port:

- a. Soot to or past O-ring?
- b. Sooted surfaces?
- c. Heat affected or eroded O-ring (installed)?
- d. O-ring damage (installed)?
- e. Eroded metal?
- f. Foreign material?
- g. Excessive grease?
- h. Medium or heavy corrosion?
- i. Metal damage?

Yes

No

Comment #

✓	✓	/
✓	✓	/
✓	✓	/
✓	✓	/
✓	✓	/
✓	✓	/
✓	✓	/
✓	✓	/
✓	✓	/

Notes / Comments

1- Typical soot to tip of SII.

Preliminary PFAR(s)? Yes ☒ No

Preliminary PFAR Number(s): \_\_\_\_\_

Clarification Form(s)? Yes ☒ No

Number of Forms Attached: \_\_\_\_\_

POSTFLIGHT OBSERVATION RECORD (PFOR)  
SII and O-rings (Detailed) - 198 Degrees

Motor No.: RSRM-32	Side: Right (B)	Date: 7/9/93
Assessment Engineer(s)/Inspector(s): Eden/Nolan		
<b>SII:</b>		
Yes	No	Comment #
a. Foreign material between the O-ring and SII?	<input checked="" type="checkbox"/>	
b. Eroded metal?	<input checked="" type="checkbox"/>	
c. Seal surface/thread damage?	<input checked="" type="checkbox"/>	
<b>Primary O-ring:</b>		
d. Heat affected or eroded O-ring?	<input checked="" type="checkbox"/>	
e. O-ring defects/damage?	<input checked="" type="checkbox"/>	
<b>Secondary O-ring:</b>		
f. Heat affected or eroded O-ring?	<input checked="" type="checkbox"/>	
g. O-ring defects/damage?	<input checked="" type="checkbox"/>	
Notes / Comments		
Preliminary PFAR(s)? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		
Preliminary PFAR Number(s): _____		
Clarification Form(s)? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		
Number of Forms Attached: _____		

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Metal Components - Excluding Joints

Motor No.: RSRM-32	Side: Right (B)	Date: 9 July 93	
Assessment Engineer(s)/Inspector(s): J. Passman, R. Quick, M. Clark			
Metal Component (check appropriate space when evaluation is completed):			
<input checked="" type="checkbox"/>	Forward Exit Cone Housing	<input checked="" type="checkbox"/>	Flexible Bearing
<input checked="" type="checkbox"/>	Fixed Housing	<input checked="" type="checkbox"/>	Throat Housing
<input checked="" type="checkbox"/>	Cowl Housing	<input checked="" type="checkbox"/>	Nose Inlet Housing
<b><u>Metal Components:</u></b>			
	Yes	No	Comment #
a. Metal damage?	_____	<input checked="" type="checkbox"/>	_____
b. Loose or missing fasteners? (including forward exit cone forward shear pins)	_____	<input checked="" type="checkbox"/>	_____
c. Heat affected paint (discolored and blistered)?	_____	<input checked="" type="checkbox"/>	_____
d. Bubbled paint?	_____	<input checked="" type="checkbox"/>	_____
e. Missing primer or paint not due to impact or handling?	_____	<input checked="" type="checkbox"/>	_____
f. Heavy corrosion?	_____	<input checked="" type="checkbox"/>	_____
Notes / Comments			
Preliminary PFAR(s)? _____ Yes <input checked="" type="checkbox"/> No _____ Preliminary PFAR Number(s): _____			

Clarification Form(s)? \_\_\_\_\_ Yes ☒ No \_\_\_\_\_ Number of Forms Attached: \_\_\_\_\_

REVISION \_\_\_\_\_

DOC NO. TWR-64240	VOL. _____
SEC _____	PAGE A-71



**POSTFLIGHT OBSERVATION RECORD (PFOR)**  
**Nozzle Internal Joint Phenolics - Joint 2**

<b>Motor No.:</b> RSRM-32	<b>Side:</b> Right (B)	<b>Date:</b>																				
<b>Assessment Engineer(s)/Inspector(s):</b>																						
<table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th style="width:60%;"><u>Joint Phenolics:</u></th> <th style="width:10%;">Yes</th> <th style="width:10%;">No</th> <th style="width:20%;">Comment #</th> </tr> </thead> <tbody> <tr> <td>a. Heat affected or eroded CCP (below the char line), GCP/SCP, or adhesive?</td> <td align="center">_____</td> <td align="center">_____<input checked="" type="checkbox"/></td> <td>_____</td> </tr> <tr> <td>b. Physical damage?</td> <td align="center">_____</td> <td align="center">_____<input checked="" type="checkbox"/></td> <td>_____</td> </tr> <tr> <td>c. Edge separations (metal-to-adhesive, within adhesive, adhesive-GCP/SCP, within GCP/SCP, GCP/SCP-to-CCP, or within CCP)?</td> <td align="center">_____</td> <td align="center">_____<input checked="" type="checkbox"/></td> <td>_____</td> </tr> <tr> <td>d. Phenolics axially displaced from the housing?</td> <td align="center">_____</td> <td align="center">_____<input checked="" type="checkbox"/></td> <td>_____</td> </tr> </tbody> </table>			<u>Joint Phenolics:</u>	Yes	No	Comment #	a. Heat affected or eroded CCP (below the char line), GCP/SCP, or adhesive?	_____	_____ <input checked="" type="checkbox"/>	_____	b. Physical damage?	_____	_____ <input checked="" type="checkbox"/>	_____	c. Edge separations (metal-to-adhesive, within adhesive, adhesive-GCP/SCP, within GCP/SCP, GCP/SCP-to-CCP, or within CCP)?	_____	_____ <input checked="" type="checkbox"/>	_____	d. Phenolics axially displaced from the housing?	_____	_____ <input checked="" type="checkbox"/>	_____
<u>Joint Phenolics:</u>	Yes	No	Comment #																			
a. Heat affected or eroded CCP (below the char line), GCP/SCP, or adhesive?	_____	_____ <input checked="" type="checkbox"/>	_____																			
b. Physical damage?	_____	_____ <input checked="" type="checkbox"/>	_____																			
c. Edge separations (metal-to-adhesive, within adhesive, adhesive-GCP/SCP, within GCP/SCP, GCP/SCP-to-CCP, or within CCP)?	_____	_____ <input checked="" type="checkbox"/>	_____																			
d. Phenolics axially displaced from the housing?	_____	_____ <input checked="" type="checkbox"/>	_____																			
<b>Notes / Comments</b>																						

**Preliminary PFAR(s)?** \_\_\_\_\_ Yes \_\_\_\_\_☒ No      **Preliminary PFAR Number(s):** \_\_\_\_\_  
**Clarification Form(s)?** \_\_\_\_\_ Yes \_\_\_\_\_☒ No      **Number of Forms Attached:** \_\_\_\_\_

REVISION \_\_\_\_\_

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Internal Joint Seals and Metal - Joint 2

Motor No.: RSRM-32	Side: Right (B)	Date: 7-9-93
--------------------	-----------------	--------------

Assessment Engineer(s)/Inspector(s): W. Sperry, M. Offolter

<u>Joint Seals and Metal:</u>	Yes	No	Comment #
a. Soot to or past O-rings?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
b. Sooted joint surfaces?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
c. Heat affected or eroded O-rings (installed)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
d. O-ring damage (installed)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
e. Heat affected or eroded metal?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
f. RTV to primary O-ring?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
g. RTV past primary O-ring?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
h. Foreign material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
i. Excessive grease?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
(including in threaded and through bolt holes)			
j. Metal damage?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
(including Index pin and bolt holes (through, threaded/ helical coil inserts))			
k. Bent or broken bolts?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

Notes / Comments

1- light to medium corrosion upstream of primary O-ring between bolt holes full circumference.

Preliminary PFAR(s)? ☐ Yes ☒ No

Preliminary PFAR Number(s): \_\_\_\_\_

Clarification Form(s)? ☐ Yes ☒ No

Number of Forms Attached: \_\_\_\_\_

REVISION \_\_\_\_\_

DOC NO. TWR-64240  
SEC \_\_\_\_\_

VOL \_\_\_\_\_  
PAGE A-74




POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Internal Joint Drawing Worksheet - Joint 2

Motor No.: RSRM-32	Side: Right (B)	Date: 9 JULY 93
Assessment Engineer(s)/Inspector(s): J. PASSMAN R. QUICK		

Sketch Observations Below (include locations and sizes of sketched features):

- ① INTERMITTENT LIGHT-MED CORROSION IN THIS AREA
- ② NO EXCESS GREASE IN BOLT HOLES
- ③ RTV TO INLET HSG FULL CIRCUM



POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Internal Joint O-rings (Detailed) - Joint 2

Motor No.: RSRM-32	Side: Right (B)	Date: 7-9-93
Assessment Engineer(s)/Inspector(s): <i>W. Sperry, M. Offeller, B. Ferguson</i>		
<u>Primary O-ring:</u>	Yes	No
a. Heat affected or eroded O-ring?	_____	_____/_____ ✓
b. O-ring defects/damage?	_____	_____/_____ ✓
<u>Secondary O-ring:</u>		
c. Heat affected or eroded O-ring?	_____	_____/_____ ✓
d. O-ring defects/damage?	_____	_____/_____ ✓
Notes / Comments		
Preliminary PFAR(s)? _____ Yes _____ No _____		
Preliminary PFAR Number(s): _____		
Clarification Form(s)? _____ Yes _____ No _____		
Number of Forms Attached: _____		

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Internal Joint RTV - Joint 3

Motor No.: RSRM-32	Side: Right (B)	Date: 9 July 93																												
Assessment Engineer(s)/Inspector(s): K. Guick W. SPERRY P. MILLER																														
<table border="1" style="width:100%"><thead><tr><th style="width:60%">Joint RTV:</th><th style="width:10%">Yes</th><th style="width:10%">No</th><th style="width:20%">Comment #</th></tr></thead><tbody><tr><td>a. Gas penetration?</td><td>_____</td><td>_____✓</td><td>_____</td></tr><tr><td>b. RTV not below char line?</td><td>_____</td><td>_____✓</td><td>_____</td></tr><tr><td>c. Uncured/reverted RTV?</td><td>_____</td><td>_____✓</td><td>_____</td></tr><tr><td>d. Voids within RTV?</td><td>_____</td><td>_____✓</td><td>_____</td></tr><tr><td>e. Grease inhibiting RTV backfill?</td><td>_____</td><td>_____✓</td><td>_____</td></tr><tr><td>f. Foreign material?</td><td>_____</td><td>_____✓</td><td>_____</td></tr></tbody></table>			Joint RTV:	Yes	No	Comment #	a. Gas penetration?	_____	_____✓	_____	b. RTV not below char line?	_____	_____✓	_____	c. Uncured/reverted RTV?	_____	_____✓	_____	d. Voids within RTV?	_____	_____✓	_____	e. Grease inhibiting RTV backfill?	_____	_____✓	_____	f. Foreign material?	_____	_____✓	_____
Joint RTV:	Yes	No	Comment #																											
a. Gas penetration?	_____	_____✓	_____																											
b. RTV not below char line?	_____	_____✓	_____																											
c. Uncured/reverted RTV?	_____	_____✓	_____																											
d. Voids within RTV?	_____	_____✓	_____																											
e. Grease inhibiting RTV backfill?	_____	_____✓	_____																											
f. Foreign material?	_____	_____✓	_____																											
Notes / Comments																														

Preliminary PFAR(s)? \_\_\_\_\_ Yes \_\_\_\_\_ No

Preliminary PFAR Number(s): \_\_\_\_\_

Clarification Form(s)? \_\_\_\_\_ Yes \_\_\_\_\_ No

Number of Forms Attached: \_\_\_\_\_

REVISION \_\_\_\_\_

DOC NO. TWR-64240  
SEC \_\_\_\_\_

VOL \_\_\_\_\_  
PAGE A-77

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Internal Joint Phenolics - Joint 3

Motor No.: RSRM-32	Side: Right (B)	Date: 9 JULY 93
Assessment Engineer(s)/Inspector(s): R. QUICK W. SPERRY P. MILLER		
<b>Joint Phenolics:</b>		
	Yes	No
a. Heat affected or eroded CCP (below the char line), GCP, or adhesive?	_____	_____✓_____
b. Physical damage?	_____	_____✓_____
c. Edge separations (metal-to-adhesive, within adhesive, adhesive-GCP, within GCP, GCP-to-CCP, or within CCP)?	_____✓_____	_____
d. Phenolics axially displaced from the housing?	_____	_____✓_____
Comment #		
SEE Pg A-86		
Notes / Comments		

Preliminary PFAR(s)? \_\_\_\_\_ Yes \_\_\_\_\_✓\_\_\_\_\_ No Preliminary PFAR Number(s): \_\_\_\_\_  
Clarification Form(s)? \_\_\_\_\_ Yes \_\_\_\_\_✓\_\_\_\_\_ No Number of Forms Attached: \_\_\_\_\_

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Internal Joint Seals and Metal - Joint 3

Motor No.: RSRM-32	Side: Right (B)	Date: 7-9-93
--------------------	-----------------	--------------

Assessment Engineer(s)/Inspector(s): W. Sperry, M. Offalter

<u>Joint Seals and Metal:</u>	Yes	No	Comment #
a. Soot to or past O-rings?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
b. Sooted joint surfaces?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
c. Heat affected or eroded O-rings (installed)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
d. O-ring damage (installed)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
e. Heat affected or eroded metal?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
f. RTV to primary O-ring?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
g. RTV past primary O-ring?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
h. Foreign material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
i. Excessive grease?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
(including in threaded and through bolt holes)			
j. Metal damage?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
(including index pin and bolt holes (through, threaded/ helical coil inserts))			
k. Bent or broken bolts?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

Notes / Comments

Preliminary PFAR(s)? ☐ Yes ☒ No

Preliminary PFAR Number(s): \_\_\_\_\_

Clarification Form(s)? ☐ Yes ☒ No

Number of Forms Attached: \_\_\_\_\_

REVISION \_\_\_\_\_

DOC NO. TWR-64240  
SEC \_\_\_\_\_

VO. \_\_\_\_\_  
PAGE A-79

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Internal Joint Drawing Worksheet - Joint 3

Motor No.: RSRM-32


Side: Right (B)

Date: 9 JULY 93

Assessment Engineer(s)/Inspector(s): R. QUICK W. SPERRY P. MILLER

Sketch Observations Below (include locations and sizes of sketched features):

- ① RTV BELOW CHAR LINE FULL CIRCUM
- ② GREASE COVERAGE WAS NOMINAL
- ③ NO EXCESS GREASE IN BOLT HOLES
- ④ NO SEPARATIONS ON FWD END OF THROAT



- ⑤ SEPARATIONS BETWEEN INLET HSG AND AFT INLET RING  
AT 110°-157°=.005, 162°-187°=.005, 232°-245°=.005 AND  
300°-340°=.005

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Internal Joint O-rings (Detailed) - Joint 3

Motor No.: RSRM-32	Side: Right (B)	Date: 7-9-93
Assessment Engineer(s)/Inspector(s): <u>W. Sperry, M. Offalter, B. Ferguson</u>		
<u>Primary O-ring:</u>	Yes	No
a. Heat affected or eroded O-ring?	_____	_____/_____ ✓
b. O-ring defects/damage?	_____	_____/_____ ✓
<u>Secondary O-ring:</u>		
c. Heat affected or eroded O-ring?	_____	_____/_____ ✓
d. O-ring defects/damage?	_____	_____/_____ ✓
Notes / Comments		
Preliminary PFAR(s)? _____ Yes _____ No <u>✓</u>		
Preliminary PFAR Number(s): _____		
Clarification Form(s)? _____ Yes _____ No <u>✓</u>		
Number of Forms Attached: _____		

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Internal Joint RTV - Joint 4

Motor No.: RSRM-32

Side: Right (B)

Date: 7 JULY 93

Assessment Engineer(s)/Inspector(s): R. QUICK A. CARLISLE P. MILLER

Joint RTV:

	Yes	No	Comment #
a. Gas penetration?	_____	_____/_____ ✓	_____
b. RTV not below char line?	_____	_____/_____ ✓	_____
c. Uncured/reverted RTV?	_____	_____/_____ ✓	_____
d. Voids within RTV?	_____	_____/_____ ✓	_____
e. Grease inhibiting RTV backfill?	_____	_____/_____ ✓	_____
f. Foreign material?	_____	_____/_____ ✓	_____

Notes / Comments

Preliminary PFAR(s)? \_\_\_\_\_ Yes \_\_\_\_\_/\_\_\_\_\_  
✓ No

Preliminary PFAR Number(s): \_\_\_\_\_

Clarification Form(s)? \_\_\_\_\_ Yes \_\_\_\_\_/\_\_\_\_\_  
✓ No

Number of Forms Attached: \_\_\_\_\_

REVISION \_\_\_\_\_

DOC NO. TWR-64240  
SEC \_\_\_\_\_

VOL  
PAGE A-81a



POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Internal Joint Phenolics - Joint 4

Motor No.: RSRM-32	Side: Right (B)	Date: 9 JULY 93
--------------------	-----------------	-----------------

Assessment Engineer(s)/Inspector(s): *R. QUICK A. CARLISLE P. MILLER*

Joint Phenolics:

	Yes	No	Comment #
a. Heat affected or eroded CCP (below the char line), GCP, or adhesive?	_____	<input checked="" type="checkbox"/>	_____
b. Physical damage?	<input checked="" type="checkbox"/>	_____	<u>1</u>
c. Edge separations (metal-to-adhesive, within adhesive, adhesive-GCP, within GCP, GCP-to-CCP, or within CCP)?	<input checked="" type="checkbox"/>	_____	<u>2</u>
d. Phenolics axially displaced from the housing?	_____	_____	_____

Notes / Comments

*1-GCP BROKE DURING DISASSEMBLY FROM 90°-135°*  
*2- SEPARATION ON AFT END OF THROAT FULL CIRCUM MAX GAP = .021*

Preliminary PFAR(s)? \_\_\_\_\_ Yes ☒ No \_\_\_\_\_ Preliminary PFAR Number(s): \_\_\_\_\_

Clarification Form(s)? \_\_\_\_\_ Yes ☒ No \_\_\_\_\_ Number of Forms Attached: \_\_\_\_\_

REVISION \_\_\_\_\_

DOC NO. TWR-64240	VOL _____
SEC _____	PAGE A-82

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Internal Joint Seals and Metal - Joint 4

Motor No.: RSRM-32	Side: Right (B)	Date: 7 JULY 93
Assessment Engineer(s)/Inspector(s): R. QUICK A. CARLISLE P. MILLER		

Joint Seals and Metal:

	Yes	No	Comment #
a. Soot to or past O-rings?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
b. Sooted joint surfaces?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
c. Heat affected or eroded O-rings (installed)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
d. O-ring damage (installed)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
e. Heat affected or eroded metal?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
f. RTV to primary O-ring?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	1
g. RTV past primary O-ring?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
h. Foreign material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
i. Excessive grease?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
(including in threaded and through bolt holes)			
j. Metal damage?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
(including index pin and bolt holes (through, threaded/ helical coil inserts))			
k. Bent or broken bolts?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

Notes / Comments

1-RTV TO PRIMARY O-RING FROM 45°-86° & 240°-270°

Preliminary PFAR(s)? ☐ Yes ☒ No Preliminary PFAR Number(s): \_\_\_\_\_  
 Clarification Form(s)? ☐ Yes ☒ No Number of Forms Attached: \_\_\_\_\_

REVISION \_\_\_\_\_

DOC NO. TWR-64240  
SEC \_\_\_\_\_

VOL \_\_\_\_\_  
PAGE A-83

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Internal Joint Drawing Worksheet - Joint 4

Motor No.: RSRM-32


Side: Right (B)

Date: 7 JULY 93

Assessment Engineer(s)/Inspector(s): R. QUICK A. CARLISLE P. MILLER

Sketch Observations Below (include locations and sizes of sketched features):

- ① ALL CARBON MISSING EXCEPT FROM 198°-265°
- ② RTV BELOW CHAR LINE FULL CIRCUM



- ③ NO CORROSION ON MOUNTING FLANGE
- ④ SEPARATION BETWEEN GCP & HOUSING FULL CIRCUM
- ⑤ RTV DISCOLORED FROM SEA WATER FROM 198°-265°
- ⑥ NO EXCESS GREASE IN HOLES

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Internal Joint O-rings (Detailed) - Joint 4

Motor No.: RSRM-32	Side: Right (B)	Date: 1 July 1993
Assessment Engineer(s)/Inspector(s): A. Carlisle, B. Quick, M. Lyons, J. Richards		
<u>Primary O-ring:</u>	Yes	No
a. Heat affected or eroded O-ring?	_____	✓ _____
b. O-ring defects/damage?	_____	✓ _____
<u>Secondary O-ring:</u>	Yes	No
c. Heat affected or eroded O-ring?	_____	✓ _____
d. O-ring defects/damage?	_____	✓ _____
Notes / Comments		

Preliminary PFAR(s)? \_\_\_\_\_ Yes \_\_\_\_\_ No ✓ Preliminary PFAR Number(s): \_\_\_\_\_

Clarification Form(s)? \_\_\_\_\_ Yes \_\_\_\_\_ No ✓ Number of Forms Attached: \_\_\_\_\_

REVISION \_\_\_\_\_

POSTFLIGHT OBSERVATION RECORD (PFOR)

Nozzle Internal Joint RTV - Joint 5

Motor No.: RSRM-32	Side: Right (B)	Date: 8 JULY 93
--------------------	-----------------	-----------------

Assessment Engineer(s)/Inspector(s): R. QUICK A. CARLISLE P. MILLER

Joint RTV:

	Yes	No	Comment #
a. Gas penetration?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
b. RTV not below char line?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
c. Uncured/reverted RTV?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
d. Voids within RTV?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	1
e. Foreign material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

Notes / Comments

① TWO SMALL VOIDS AT LOCATION 140° AND 320°

Preliminary PFAR(s)? ☐ Yes ☒ No

Preliminary PFAR Number(s): \_\_\_\_\_

Verification Form(s)? ☐ Yes ☒ No

Number of Forms Attached: \_\_\_\_\_

REVISION \_\_\_\_\_

DOC NO. TWR-64240	VOL _____
SEC _____	PAGE A-86

POSTFLIGHT OBSERVATION RECORD (PFOR)

Nozzle Internal Joint Phenolics - Joint 5

Motor No.: RSRM-32

Side: Right (B)

Date: 8 JULY 93

Assessment Engineer(s)/Inspector(s): R. QUICK A. CARLISLE D. MILLER

Joint Phenolics:

	Yes	No	Comment #
a. Heat affected or eroded CCP (below the char line), GCP, or adhesive?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
b. Physical damage?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
c. Edge separations (metal-to-adhesive, within adhesive, adhesive-GCP, within GCP, GCP-to-CCP, or within CCP)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
d. Phenolics axially displaced from the housing?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

Notes / Comments

Preliminary PFAR(s)? ☐ Yes ☒ No

Preliminary PFAR Number(s):

Verification Form(s)? ☐ Yes ☒ No

Number of Forms Attached:

REVISION

DOC NO. TWR-64240 VOL  
SEC PAGE A-87

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Internal Joint Seals and Metal - Joint 5

Motor No.: RSRM-32	Side: Right (B)	Date: 8 JULY
Assessment Engineer(s)/Inspector(s): R. QUICK P. MILLER A. CARLISLE		

Joint Seals and Metal:	Yes	No	Comment #
a. Soot to or past O-rings?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
b. Sooted joint surfaces?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
c. Heat affected or eroded O-rings (installed)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
d. O-ring damage (installed)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
e. Heat affected or eroded metal?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
f. RTV to primary O-ring?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	1
g. RTV past primary O-ring?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
h. Foreign material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
i. Excessive grease?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
(including in threaded and through bolt holes)			
j. Metal damage?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
(including index pin and bolt holes (through, threaded/ helical coil inserts))			
k. Bent or broken bolts?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

as / Comments  
NO RTV TO PRIMARY O-RING FROM ~~185°-255°~~ 0°-70°, 185°-255°

Preliminary PFAR(s)?	Yes	<input checked="" type="checkbox"/>	No	Preliminary PFAR Number(s):
Clarification Form(s)?	Yes	<input checked="" type="checkbox"/>	No	Number of Forms Attached:


REVISION \_\_\_\_\_

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Internal Joint Drawing Worksheet - Joint 5

Motor No.: RSRM-32	Side: Right (B)	Date: 8 JULY 93
Assessment Engineer(s)/Inspector(s): R. QUICK A. CARLISLE F. MILLER		

Sketch Observations Below (include locations and sizes of sketched features):

- ① NOMINAL GREASE COVERAGE
- ② NO EXCESS GREASE IN BOLT HOLES
- ③ LIGHT INTERMITTENT SCARFE MARKS FROM SANDERS 360°



- ④ MEDIUM TO HEAVY CORROSION INTERMITTENTLY FULL CIRCUM



POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Internal Joint O-rings (Detailed) - Joint 5

Motor No.: RSRM-32

Side: Right (B)

Date: 8 July 1993

Assessment Engineer(s)/Inspector(s): A. Carlisle, W. Ferguson

Primary O-ring:

- a. Heat affected or eroded O-ring?  
b. O-ring defects/damage?

Yes

No

Comment #

\_\_\_\_\_  
\_\_\_\_\_

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

\_\_\_\_\_  
\_\_\_\_\_

Secondary O-ring:

- c. Heat affected or eroded O-ring?  
d. O-ring defects/damage?

\_\_\_\_\_  
\_\_\_\_\_

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

\_\_\_\_\_  
\_\_\_\_\_

Notes / Comments

Preliminary PFAR(s)? \_\_\_\_\_ Yes ✓ No

Preliminary PFAR Number(s): \_\_\_\_\_

Clarification Form(s)? \_\_\_\_\_ Yes ✓ No

Number of Forms Attached: \_\_\_\_\_

REVISION \_\_\_\_\_

DOC NO. TWR-64240  
SEC \_\_\_\_\_

VOL \_\_\_\_\_

PAGE A-90

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Internal Joint Packings With Retainers (Detailed) - Joint 5

Motor No.: RSRM-32	Side: Right (B)	Date: 8 July 1993
--------------------	-----------------	-------------------

Assessment Engineer(s)/Inspector(s): A. Carlisle, M. Lyons, J. Richards
---

Packings With Retainers:	Yes	No	Comment #
a. Heat affected or eroded seal or retainer?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
b. Seal or retainer defects/damage?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	1
c. Medium or heavy corrosion?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Notes / Comments

1) Typical disassembly rubber damage to 12 of 12 Packing with Retainers

Preliminary PFAR(s)? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Preliminary PFAR Number(s): _____
Clarification Form(s)? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Number of Forms Attached: _____

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Cowl Insulation Segments

Motor No.: RSRM-32	Side: Right (B)	Date: 9 JUL 93
Assessment Engineer(s)/Inspector(s): Jim PASSMAN Bob Quick		

Cowl Insulation Segments:

	Yes	No	Comment #
a. Abnormal heat effects or erosion?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
b. Soot between the cowl segment and cowl housing/SCP?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
c. Uncured adhesive (silicone)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

Bondline Failure Mode Percentage:

	Degree Location							
	0-45	45-90	90-135	135-180	180-225	225-270	270-315	315-0
Metal-to-Adhesive	25	30	40	50	60	30	40	60
Within Adhesive	2	5	2	2	3	3	2	5
Adhesive-to-SCP	2	2	5	2	7	2	2	2
Adhesive-to-segment	71	63	53	46	30	65	56	33
Within segment								

Notes / Comments

Special Issue 3.3.3

THE COWL INSULATION SEGMENTS WERE IN EXCELLENT  
CONDITION, NO UNBONDING OR OTHER ANOMALOUS CONDITIONS  
WERE FOUND.

Preliminary PFAR(s)? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Preliminary PFAR Number(s): _____
Clarification Form(s)? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Number of Forms Attached: _____

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Flexible Bearing Protector, Flexible Bearing, and Flexible Boot

Motor No.: RSRM-32

Side: Right (B)

Date: 9 JUN 93

Assessment Engineer(s)/Inspector(s): JIM PASSMAN BOB QUICK

Flexible Bearing Protector, Bearing, and Boot:

- |  | Yes   | No     | Comment # |
|--|-------|--------|-----------|
| a. Abnormal bearing protector heat effects or erosion?<br>(including burn-through) | _____ | _____✓ | _____     |
| b. Cracks through the bearing protector?   | _____ | _____✓ | _____     |
| c. Soot between the bearing protector and flexible bearing?                        | _____ | _____✓ | _____     |
| d. Heat effects to the flexible bearing?   | _____ | _____✓ | _____     |
| e. Bent or broken bearing protector bolts?   | _____ | _____✓ | _____     |
| f. Flexible boot burn-through?   | _____ | _____✓ | _____     |
| g. Abnormal heat effects or erosion to flexible boot ID?                           | _____ | _____✓ | _____     |
| h. Foreign material in the boot cavity?  | _____ | _____✓ | _____     |

Notes / Comments

Preliminary PFAR(s)? \_\_\_\_\_ Yes \_\_\_\_\_✓ No

Preliminary PFAR Number(s): \_\_\_\_\_

Clarification Form(s)? \_\_\_\_\_ Yes \_\_\_\_\_✓ No

Number of Forms Attached: \_\_\_\_\_

REVISION \_\_\_\_\_

DOC NO. TWR-64240 VOL  
SEC PAGE A-93


**POSTFLIGHT OBSERVATION RECORD (PFOR)**  
**Flexible Bearing Protector Measurements (Data Collection Only)**

Motor No.: RSRM-32	Side: Right (B)	Date: 14 JUL 1993
--------------------	-----------------	-------------------

Assessment Engineer(s)/Inspector(s): R L MASTERSON

Flexible Bearing Protector Gas Impingement Area Thickness Measurements (see figure):

Degree Location	Thickness Measurement A* (inches)	Degree Location	Thickness Measurement A* (inches)	Degree Location	Thickness Measurement A* (inches)
0	.718	120	.728	240	.731
10	.722	130	.715	250	.654
20	.727	140	.718	260	.733
30	.730	150	.725	270	.725
40	.732	160	.721	280	.736
50	.733	170	.723	290	.725
60	.735	180	.726	300	.715
70	.733	190	.728	310	.69
80	.735	200	.736	320	.71
90	.725	210	.675	330	.72
100	.695	220	.736	340	.715
110	.763	230	.734	350	.722



\* "A" is the minimum thickness of the bearing protector belly band in-line with the cowl vent holes. It corresponds to the deepest gas impingement location.

Notes / Comments

Clarification Form(s)? ☐ Yes ☐ No      Number of Forms Attached:

REVISION

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Throat Diameter Measurements (Data Collection Only)

Motor No.: RSRM-32	Side: Right (B)	Date: 07-12-93
Assessment Engineer(s)/Inspector(s): MIGUEL ENRIQUEZ, RICK GALLEGOS		

Nozzle Throat Diameter Measurements:

Degree Location	Diameter Measurement (inches)
0	<u>55.940"</u>
45	<u>55.925"</u>
90	<u>55.894"</u>
135	<u>55.940"</u>

Notes / Comments

Avg. Throat Diameter = 55.925"

Clarification Form(s)? ☐ Yes ☒ No Number of Forms Attached:

REVISION

DOC NO.	TWR-64240	VOL
SEC	PAGE	A-95

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Phenolic Bondline - Aft Exit Cone Assembly

Motor No.: RSRM-32	Side: Right (B)	Date: 8 July 93
Assessment Engineer(s)/Inspector(s): E. QUICK F. MILLER		

Metal Housing Bondline Surface:	Yes	No	Comment #
a. Soot?		<input checked="" type="checkbox"/>	
b. Heat affected or eroded metal?		<input checked="" type="checkbox"/>	
c. Voids in adhesive greater than 0.5 inch in any direction?	<input checked="" type="checkbox"/>		1
d. Corrosion?		<input checked="" type="checkbox"/>	
e. Foreign material?		<input checked="" type="checkbox"/>	

Note: Axial cuts may be relocated + or - 10 degrees only. Document if any cuts were relocated.

Primary Bondline/Phenolic Failure Mode Percentage (After Hydrolase and Wedge Removal):

	Degree Location							
	0-45	45-90	90-135	135-180	180-225	225-270	270-315	315-0
Metal-to-Adhesive		2%	5%					
Within Adhesive								
Adhesive-to-GCP								
Within GCP	100%	98%	95%	100%	100%	100%	100%	100%
GCP-to-CCP								
Within CCP								

Secondary Bondline Failure Mode Percentage (After Removal of Remaining Phenolics):

	Degree Location							
	0-45	45-90	90-135	135-180	180-225	225-270	270-315	315-0
Metal-to-Adhesive								
Within Adhesive								
Adhesive-to-GCP								

Phenolic Removal Method: \_\_\_\_\_

Notes / Comments 1- VOID 22.1 FROM FWD END 1.1 AXIAL & 6 CIRCUM @ LOC 198°  
2- SMALL VOIDS IN POLY SULFIDE FULL CIRCUM

Preliminary PFAR(s)? ☐ Yes ☒ No Preliminary PFAR Number(s): \_\_\_\_\_  
Clarification Form(s)? ☐ Yes ☒ No Number of Forms Attached: \_\_\_\_\_

**POSTFLIGHT OBSERVATION RECORD (PFOR)**  
**Nozzle Phenolic Bondline - Forward Exit Cone Assembly**

Motor No.: RSRM-32	Side: Right (B)	Date: 7-19-75
--------------------	-----------------	---------------

Assessment Engineer(s)/Inspector(s): M. Clark, P. Miller

Metal Housing Bondline Surface:	Yes	No	Comment #
a. Soot?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
b. Heat affected or eroded metal?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
c. Voids in adhesive greater than 0.5 inch in any direction?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>1</u>
d. Corrosion?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>2</u>
e. Foreign material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

Note: Axial cuts may be relocated + or - 10 degrees only. Document if any cuts were relocated.

Primary Bondline/Phenolic Failure Mode Percentage (After Hydrolase and Wedge Removal):

	Degree Location								
	22.5	47.5	67.5-112.5	112.5-157.5	157.5-202.5	202.5-247.5	247.5-292.5	292.5-337.5	337.5-382.5
Metal-to-Adhesive	<u>20</u>	<u>25</u>	<u>40</u>	<u>30</u>	<u>65</u>	<u>20</u>	<u>15</u>	<u>45</u>	<u>55</u>
Within Adhesive									
Adhesive-to-GCP	<u>70</u>	<u>75</u>	<u>60</u>	<u>70</u>	<u>35</u>	<u>80</u>	<u>85</u>	<u>55</u>	<u>57</u>
Within GCP									
GCP-to-CCP									
Within CCP									

Secondary Bondline Failure Mode Percentage (After Removal of Remaining Phenolics):

	Degree Location							
Metal-to-Adhesive	<u>NA</u>							
Within Adhesive								
Adhesive-to-GCP								

Phenolic Removal Method: \_\_\_\_\_

Notes / Comments  
1) Voids documented on page A-104A and A-104B

Preliminary PFAR(s)? ☐ Yes ☒ No Preliminary PFAR Number(s): \_\_\_\_\_

Clarification Form(s)? ☒ Yes ☐ No Number of Forms Attached: A-104A, A-104B



Nozzle Subassembly Bondline Adhesive Void Clarification Form

Motor No.: RSRM-32 | Side: ☐ Left (A) ☒ Right (B) | Date: 7-19-93  
Assessment Engineer(s)/Inspector(s): M. Clark, P. Miller  
Nozzle Subassembly: Fwd Exit Cone

Record Bondline Adhesive Void Measurements and Locations Below:

Degree Location	Void Size		Location on Bonding Surface	
	Axial	Circ.	Distance From Fwd	Distance From Aft
<u>18.75</u>	<u>.7</u>	<u>.4</u>	<u>          </u>	<u>8.9</u>
<u>26.25</u>	<u>.7</u>	<u>.4</u>	<u>          </u>	<u>10.7</u>
<u>30</u>	<u>2.3</u>	<u>.6</u>	<u>          </u>	<u>6.9</u>
<u>31.9</u>	<u>1.4</u>	<u>.4</u>	<u>          </u>	<u>11.8</u>
<u>32.75</u>	<u>2.7</u>	<u>.8</u>	<u>          </u>	<u>7.7</u>
<u>34.6</u>	<u>.7</u>	<u>.3</u>	<u>          </u>	<u>16.2</u>
<u>34.5</u>	<u>.8</u>	<u>.3</u>	<u>          </u>	<u>17.0</u>
<u>32.5</u>	<u>1.9</u>	<u>.9</u>	<u>          </u>	<u>21.5</u>
<u>34.3</u>	<u>.9</u>	<u>.4</u>	<u>          </u>	<u>20.3</u>
<u>65.6</u>	<u>.7</u>	<u>.6</u>	<u>          </u>	<u>30.7</u>
<u>69.4</u>	<u>.7</u>	<u>.4</u>	<u>          </u>	<u>5.4</u>
<u>76.9</u>	<u>.6</u>	<u>.2</u>	<u>          </u>	<u>18.4</u>
<u>11.9</u>	<u>.7</u>	<u>.4</u>	<u>          </u>	<u>22.9</u>

Notes / Comments

ORIGINAL PAGE IS  
OF POOR QUALITY

Corresponding Comment Number(s):

Nozzle Subassembly Bondline Adhesive Void Clarification Form

Motor No.: <u>RSRM-32</u>	Side: <input type="checkbox"/> Left (A) <input checked="" type="checkbox"/> Right (B)	Date: <u>7-19-93</u>
Assessment Engineer(s)/Inspector(s): <u>M. Clark, P. Miller</u>		
Nozzle Subassembly: <u>Fwd Exit Cone</u>		

Record Bondline Adhesive Void Measurements and Locations Below:

Degree Location	Void Size		Location on Bonding Surface	
	Axial	Circ.	Distance From Fwd	Distance From Aft
<u>123.8</u>	<u>3.6</u>	<u>.4</u>	<u>          </u>	<u>14.9</u>
<u>127.5</u>	<u>.6</u>	<u>.4</u>	<u>          </u>	<u>9.7</u>
<u>127.5</u>	<u>5.4</u>	<u>2.2</u>	<u>          </u>	<u>22.9</u>
<u>129.4</u>	<u>1.7</u>	<u>.9</u>	<u>          </u>	<u>21.6</u>
<u>221.3</u>	<u>.9</u>	<u>.5</u>	<u>          </u>	<u>21.1</u>
<u>155.8</u>	<u>.5</u>	<u>.5</u>	<u>          </u>	<u>33.0</u>
<u>214.4</u>	<u>1.5</u>	<u>.4</u>	<u>          </u>	<u>15.1</u>
<u>246.3</u>	<u>.6</u>	<u>.4</u>	<u>          </u>	<u>31.6</u>
<u>277.5</u>	<u>1.1</u>	<u>.4</u>	<u>          </u>	<u>30.4</u>
<u>279.4</u>	<u>.6</u>	<u>.5</u>	<u>          </u>	<u>27.4</u>
<u>281.3</u>	<u>.8</u>	<u>.6</u>	<u>          </u>	<u>35.7</u>
<u>          </u>	<u>          </u>	<u>          </u>	<u>          </u>	<u>          </u>
<u>          </u>	<u>          </u>	<u>          </u>	<u>          </u>	<u>          </u>

Notes / Comments

ORIGINAL PAGE IS  
OF POOR QUALITY

Corresponding Comment Number(s):

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Phenolic Bondline - Throat Assembly

Motor No.: RSRM-32	Side: Right (B)	Date: 21 July 73
Assessment Engineer(s)/Inspector(s): JIM PASSMAN TREVOR FLESTON		

Metal Housing Bondline Surface:	Yes	No	Comment #
a. Soot?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
b. Heat affected or eroded metal?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
c. Voids in adhesive greater than 0.5 inch in any direction?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	(1)
d. Corrosion?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	(2)
e. Foreign material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

Note: Axial cuts may be relocated + or - 10 degrees only. Document if any cuts were relocated.

Primary Bondline/Phenolic Failure Mode Percentage (After Hydrolase and Wedge Removal):

	Degree Location								Total
	0-45	45-90	90-135	135-180	180-225	225-270	270-315	315-360	
Metal-to-Adhesive	100	99	100	100	98	100	100	100	99.6
Within Adhesive									
Adhesive-to-GCP		1			2				.4
Within GCP									
GCP-to-CCP									
Within CCP									

Secondary Bondline Failure Mode Percentage (After Removal of Remaining Phenolics):

	Degree Location							
Metal-to-Adhesive								
Within Adhesive								
Adhesive-to-GCP								

Phenolic Removal Method: \_\_\_\_\_

Notes / Comments

(1) NUMEROUS SMALL VOIDS ~ .02 DIA INTERMITTENTLY THROUGHOUT BONDLINE.

(2) MEDIUM-LIGHT CORROSION ON FIRST 9" FROM FWD END, MED-HEAVY CORROSION NEXT 12" TO AFT END.

Preliminary PFAR(s)? ☐ Yes ☒ No Preliminary PFAR Number(s): \_\_\_\_\_

Clarification Form(s)? ☐ Yes ☒ No Number of Forms Attached: \_\_\_\_\_

REVISION \_\_\_\_\_

**POSTFLIGHT OBSERVATION RECORD (PFOR)**  
**Nozzle Phenolic Bondline - Forward Nose and Aft Inlet Rings**

Motor No.: RSRM-32	Side: Right (B)	Date: 7-22-93
--------------------	-----------------	---------------

Assessment Engineer(s)/Inspector(s): R. QUICK T. FRESTON

<u>Metal Housing Bondline Surface:</u>	Yes	No	Comment #
a. Soot?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
b. Heat affected or eroded metal?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
c. Voids in adhesive greater than 0.5 inch in any direction?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	1
d. Corrosion?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	2
e. Foreign material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

Note: Axial cuts may be relocated + or - 10 degrees only. Document if any cuts were relocated.

Primary Bondline/Phenolic Failure Mode Percentage (After Hydrolase and Wedge Removal):

	Degree Location							
	0-45	45-90	90-135	135-180	180-225	225-270	270-315	315-0
Metal-to-Adhesive	70%	100%	100%	100%	100%	100%	100%	100%
Within Adhesive								
Adhesive-to-GCP	30%							
Within GCP								
GCP-to-CCP								
Within CCP								

Secondary Bondline Failure Mode Percentage (After Removal of Remaining Phenolics):

	Degree Location							
Metal-to-Adhesive								
Within Adhesive								
Adhesive-to-GCP								

Phenolic Removal Method: \_\_\_\_\_

Notes / Comments *THE 30% REMAINING ADHESIVE WAS ON THE AFT INLET RING AREA  
NO VOIDS GREATER THAN .25Ø*

Special Issue 3.3.7

1. SEE PG A-106A

2. MEDIUM TO HEAVY CORROSION INTERMITTENT FULL CIRCUM

Preliminary PFAR(s)? ☐ Yes ☒ No Preliminary PFAR Number(s): \_\_\_\_\_

Clarification Form(s)? ☒ Yes ☐ No Number of Forms Attached: A-106A



POSTFLIGHT OBSERVATION RECORD (PFOR)

Nozzle Phenolic Bondline - Nose Cap

Motor No.: RSRM-32	Side: Right (B)	Date: 7/22/93
--------------------	-----------------	---------------

Assessment Engineer(s)/Inspector(s): R. Quick T. FRESTON

Metal Housing Bondline Surface:

	Yes	No	Comment #
a. Soot?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
b. Heat affected or eroded metal?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
c. Voids in adhesive greater than 0.5 inch in any direction?	<u>2</u>	<input type="checkbox"/>	
d. Corrosion?	<u>1</u>	<input type="checkbox"/>	
e. Foreign material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

Note: Axial cuts may be relocated + or - 10 degrees only. Document if any cuts were relocated.

Primary Bondline/Phenolic Failure Mode Percentage (After Hydrolase and Wedge Removal):

	Degree Location							
	0-45	45-90	90-135	135-180	180-225	225-270	270-315	315-0
Metal-to-Adhesive								
Within Adhesive								
Adhesive-to-GCP								
Within GCP								
GCP-to-CCP	100%	100%	100%	100%	100%	100%	100%	100%
Within CCP								

Secondary Bondline Failure Mode Percentage (After Removal of Remaining Phenolics):

	Degree Location								Total
	0-45	45-90	90-135	135-180	180-225	225-270	270-315	315-0	
Metal-to-Adhesive	40%	35%	50%	40%	35%	35%	40%	35%	39
Within Adhesive									
Adhesive-to-GCP	60%	65%	50%	60%	65%	65%	60%	65%	61

Phenolic Removal Method: NYLON WEDGE

Notes / Comments

1. MEDIUM TO HEAVY CORROSION INTERMITTENT FULL CIRCUM  
Special Issue 3.3.7

② Special Issue 3.3.11 32° 6.5 FROM AFT 1.0 AXIAL x .18 CIRCUM. 128° 8.3 FROM AFT .70 AXIAL x .45 CIRCUM  
145° 14.55 FROM AFT x .45 AXIAL x .25 CIRCUM, 208° 10.7 FROM AFT x .45 AXIAL x .28 CIRCUM, 245° NO IND.  
Special Issue 3.3.12 NO INDICATION AT 182°

Preliminary PFAR(s)? ☐ Yes ☒ No Preliminary PFAR Number(s): \_\_\_\_\_

Clarification Form(s)? ☒ Yes ☐ No Number of Forms Attached: 1 (A-107A)

PFOR CLARIFICATION FORM  
General

Motor No.: RSRM-32	Side: <input type="checkbox"/> Left (A) <input checked="" type="checkbox"/> Right (B)	Date: 7-22-93
Assessment Engineer(s)/Inspector(s): R. Quick, M. Clark		
Description: LDI Datasheet		

Sketch Observations Below (include locations and sizes of sketched features):

NOSE CAP TO HOUSING BONDLINE  
(Right Hand)

Degree Recorded	Location Actual	Distance <sup>1</sup> Recorded	Distance <sup>1</sup> Actual	Void or Repair	Axial Length	Circ. Width	Other Info.
32	_____	11.52	6.5*	Void	1.00	1.80	_____
128	_____	8.10	8.3*	Void	.70	.45	_____
145	_____	4.50	14.55*	Void	.45	.25	_____
212	208	15.50	10.70*	Void	.45	.28	_____
245	_____	12.80	_____	_____	_____	_____	Nothing Found

NOSE CAP TO FNR BONDLINE  
(Right Hand)

Degree Recorded	Location Actual	Distance <sup>2</sup> Recorded	Distance <sup>2</sup> Actual	Void or Repair	Axial Length	Circ. Width	Other Info.
182	_____	1.14	_____	_____	_____	_____	NOTHING FOUND

<sup>1</sup> Distance from fwd tip of nose cap glass

<sup>2</sup> Distance from flame surface

<sup>3</sup> Distance from FNR - nose cap - housing interface

\* MEASURED FROM AFT END OF NOSE CAP

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Phenolic Bondline - Cowl Assembly

Motor No.: RSRM-32	Side: Right (B)	Date: 7/21/93
Assessment Engineer(s)/Inspector(s): JIM PASSMAN, TREVOR PRESTON		

Metal Housing Bondline Surface:

	Yes	No	Comment #
a. Soot?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
b. Heat affected or eroded metal?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
c. Voids in adhesive greater than 0.5 inch in any direction?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
d. Corrosion?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
e. Foreign material?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

Note: Axial cuts may be relocated + or - 10 degrees only. Document if any cuts were relocated.

Primary Bondline/Phenolic Failure Mode Percentage (After Hydrolase and Wedge Removal):

	Degree Location								Total
	0-45	45-90	90-135	135-180	180-225	225-270	270-315	315-360	
Metal-to-Adhesive		1	25	30	3	2	50	2	14
Within Adhesive									
Adhesive-to-SCP	98	99	75	70	95	98	50	98	85.5
Within SCP	2				2				0.5
SCP-to-CCP									
Within CCP									

Secondary Bondline Failure Mode Percentage (After Removal of Remaining Phenolics):

	Degree Location							
	0-45	45-90	90-135	135-180	180-225	225-270	270-315	315-360
Metal-to-Adhesive								
Within Adhesive								
Adhesive-to-SCP								

Phenolic Removal Method: \_\_\_\_\_

Notes / Comments ADHESIVE TO METAL FAILURES WERE LOCATED AT SHIMS OR HYDROLASE CUTS.

Special Issue 3.3.7 NO VOIDS WERE FOUND.

Special Issue 3.3.13 BONDLINE WAS IN GOOD SHAPE. VERY LOW ADHESIVE TO METAL FAILURE (14%); 85.5% ADHESIVE TO SCP.

Preliminary PFAR(s)? ☐ Yes ☒ No Preliminary PFAR Number(s): \_\_\_\_\_

Clarification Form(s)? ☐ Yes ☒ No Number of Forms Attached: \_\_\_\_\_



POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Phenolic Bondline - Fixed Housing Assembly

Motor No.: RSRM-32	Side: Right (B)	Date: 7-15-93
Assessment Engineer(s)/Inspector(s): M. Clark, P. Miller		

Metal Housing Bondline Surface:	Yes	No	Comment #
a. Soot?		<input checked="" type="checkbox"/>	
b. Heat affected or eroded metal?		<input checked="" type="checkbox"/>	1
c. Voids in adhesive greater than 0.5 inch in any direction?		<input checked="" type="checkbox"/>	
d. Corrosion?		<input checked="" type="checkbox"/>	
e. Foreign material?		<input checked="" type="checkbox"/>	

Note: Axial cuts may be relocated + or - 10 degrees only. Document if any cuts were relocated.

Primary Bondline/Phenolic Failure Mode Percentage (After Hydrolase and Wedge Removal):

	Degree Location							
	0-45	45-90	90-125	125-170	170-225	225-270	270-315	315-360
Metal-to-Adhesive								
Within Adhesive								
Adhesive-to-GCP								
Within GCP	100	100	100	100	100	100	100	100
GCP-to-CCP								
Within CCP								

Secondary Bondline Failure Mode Percentage (After Removal of Remaining Phenolics):

	Degree Location								Total
Metal-to-Adhesive	2	2							1
Within Adhesive									
Adhesive-to-GCP	98	98	100	100	100	100	100	100	99

Phenolic Removal Method: Wedges & hammers

Notes / Comments

1) Intermittent voids, 0.30" or smaller

Preliminary PFAR(s)?	Yes	<input checked="" type="checkbox"/> No	Preliminary PFAR Number(s):
Clarification Form(s)?	Yes	<input checked="" type="checkbox"/> No	Number of Forms Attached:

POSTFLIGHT OBSERVATION RECORD (PFOR)

Nozzle Phenolic Sections - Aft Exit Cone

Motor No.: RSRM-32

Side: Right (B)

Date: 7-9-93

Assessment Engineer(s)/Inspector(s): M. Clark

Phenolic Sections:

Yes

No

Comment #

a. Cross-ply cracking in virgin material?

☐

☒

☐

b. Ply lifting?

☒

☐

☐

Aft Exit Cone Char and Erosion Measurements:

Station	0°		90°		180°		270°	
Location	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
73.77	NA	NA	NA	NA	NA	NA	NA	NA
77.77	↓	↓	↓	↓	↓	↓	↓	↓
83.77	↓	↓	↓	↓	↓	↓	↓	↓
89.77	↓	↓	↓	↓	↓	↓	↓	↓
95.77	↓	↓	↓	↓	↓	↓	↓	↓
101.77	0.17	0.61	0.19	0.55	↓	↓	↓	↓
107.77	NA	NA	0.17	0.58	↓	↓	0.21	0.58
113.77	↓	↓	NA	NA	↓	↓	NA	NA
118.77	↓	↓	↓	↓	↓	↓	↓	↓

Negative Margin of Safety? ☐ Yes ☒ No

Station: ☐ Degree: ☐

Notes / Comments

2) An increase in the erosion depth was observed at approx. 12" from the fwd end (station 107.77)

1) Special Issue 3.3.18 All margins of safety calculations were positive. Ply lifting was observed around the full circ. and axial length on the portion that remained attached to the housing (forward 22"-28"). None of the CCP was recovered from the aft segment. The ply lifting is summarized on page A-110D

Preliminary PFAR(s)? ☒ Yes ☐ No

Preliminary PFAR Number(s): 57C-02

Clarification Form(s)? ☒ Yes ☐ No

Number of Forms Attached: A-110A, A-110B, A-110C, A-110D

REVISION ☐

DOC NO. TWR-64240 | VOL  
SEC | PAGE A-103

**POSTFLIGHT OBSERVATION RECORD (PFOR)**  
**Nozzle Phenolic Sections - Aft Exit Cone**

Motor No.: RSRM-32	Side: Right (B)	Date: 7-9-93
--------------------	-----------------	--------------

Assessment Engineer(s)/Inspector(s): M. Clark, T. Freston

**Phenolic Sections:**

- a. Cross-ply cracking in virgin material?  
b. Ply lifting?

Yes	No	Comment #
<u>      </u>	<u>  ✓  </u>	<u>      </u>
<u>  ✓  </u>	<u>      </u>	<u>      </u>

**Aft Exit Cone Char and Erosion Measurements:**

Station Location	15°		30°		60°		165°	
	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
73.77	NA	NA	NA	NA	NA	NA	NA	NA
77.77								
83.77								
89.77								
95.77								
101.77	↓	↓	0.19	0.56	N	↓	0.16	0.54
107.77	0.27	0.54	NA	NA	0.11	0.59	0.12	0.60
113.77	NA	NA	0.19	0.51	NA	NA	NA	NA
118.77	↓	↓	NA	NA	↓	↓	↓	↓

Negative Margin of Safety?        Yes   ✓   No Station:        Degree:       

**Notes / Comments**

Preliminary PFAR(s)?   ✓   Yes        No Preliminary PFAR Number(s):       

Clarification Form(s)?        Yes   ✓   No Number of Forms Attached:       

REVISION       

DOC NO. TWR-64240	VOL	
SEC	PAGE A- 103 A	

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Phenolic Sections - Aft Exit Cone

Motor No.: RSRM-32 Side: Right (B) Date: 7-9-93

Assessment Engineer(s)/Inspector(s): M. Clark, T. Freston

Phenolic Sections:	Yes	No	Comment #
a. Cross-ply cracking in virgin material?		✓	
b. Ply lifting?	✓		

Aft Exit Cone Char and Erosion Measurements:

Station	195°		210°		255°		285°	
Location	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
73.77	NA	NA	NA	NA	NA	NA	NA	NA
77.77								
83.77								
89.77								
95.77								
101.77	↓	↓	↓	↓	↓	↓	0.19	0.59
107.77	0.17	0.63	0.18	0.56	0.34	0.49	NA	NA
113.77	NA	NA	NA	NA	0.16	0.55	0.18	0.57
118.77	↓	↓	↓	↓	NA	NA	NA	NA

Negative Margin of Safety? Yes ☒ No ☐ Station: Degree:

Notes / Comments

Preliminary PFAR(s)? Yes ☒ No ☐ Preliminary PFAR Number(s):

Clarification Form(s)? Yes ☒ No ☐ Number of Forms Attached:

**POSTFLIGHT OBSERVATION RECORD (PFOR)**  
**Nozzle Phenolic Sections - Aft Exit Cone**

Motor No.: RSRM-32	Side: Right (B)	Date: 7-9-93
Assessment Engineer(s)/Inspector(s): M. Clark, T. Freston		

**Phenolic Sections:**

- a. Cross-ply cracking in virgin material?  
b. Ply lifting?

Yes	No	Comment #
<u>✓</u>	<u>✓</u>	

**Aft Exit Cone Char and Erosion Measurements:**

Station Location	300°		330°		345°		°	
	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
73.77	NA	NA	NA	NA	NA	NA		
77.77								
83.77								
89.77								
95.77	↓	↓	↓	↓	↓	↓		
101.77	0.18	0.57	0.20	0.57	↓	↓		
107.77	0.20	0.51	NA	NA	0.07	0.62		
113.77	0.21	0.53			NA	NA		
118.77	NA	NA	↓	↓	↓	↓		

Negative Margin of Safety?        Yes ✓ No      Station:        Degree:       

**Notes / Comments**

Preliminary PFAR(s)? ✓ Yes        No      Preliminary PFAR Number(s):       

Clarification Form(s)?        Yes ✓ No      Number of Forms Attached:       

REVISION       

DOC NO. TWR-64240	VOL	
SEC	PAGE A-103C	

PFOR CLARIFICATION FORM  
General


Motor No.: RSRM-32	Side: <input type="checkbox"/> Left (A) <input checked="" type="checkbox"/> Right (B)	Date: 7-9-93
Assessment Engineer(s)/Inspector(s): M. Clark		
Description: AEC Ply Lifting		

Sketch Observations Below (include locations and sizes of sketched features):

RSRM-32B Aft Exit Cone Ply Lifting

DEGREE	DISTANCE FROM FWD END	CHAR CAP	PLY LIFT	CHAR	VIRGIN CCP
0	7	0.40	0.18	0.10	0.46
	10	0.39	0.17	0.09	0.43
	15	0.34	0.18	0.08	0.41
	18	0.33	0.19	0.06	0.41
30	6	0.42	0.19	0.04	0.50
	10	0.40	0.20	0.00	0.55
	18	0.34	0.19	0.01	0.49
60	7	0.40	0.13	0.00	0.57
	10	0.41	0.15	0.00	0.55
90	15	0.43	0.16	0.00	0.48
	18	0.38	0.19	0.00	0.50
165	6	0.37	0.16	0.00	0.54
	10	0.42	0.18	0.00	0.52
	15	0.40	0.18	0.00	0.50
180	7	0.45	0.15	0.05	0.50
	10	0.38	0.15	0.03	0.50
	15	0.37	0.15	0.05	0.50
195	7	0.40	0.14	0.00	0.55
	10	0.40	0.15	0.00	0.55
	15	0.39	0.18	0.00	0.53
210	7	0.45	0.10	0.00	0.55
	10	0.42	0.15	0.00	0.55
255	6	0.37	0.2	0	0.54
	10	0.39	0.18	0	0.52
270	10	0.37	0.16	0	0.52
	15	0.37	0.2	0	0.5
	18	0.37	0.18	0	0.5
285	6	0.42	0.15	0.00	0.52
	10	0.42	0.15	0.00	0.53
	15	0.40	0.15	0.00	0.54
	18	0.40	0.17	0.00	0.50
300	6	0.40	0.08	0.03	0.52
	10	0.43	0.10	0.04	0.49
	15	0.44	0.11	0.00	0.50
	18	0.45	0.10	0.06	0.42
330	10	0.37	0.16	0.00	0.53
345	6	0.37	0.18	0.00	0.53
	10	0.39	0.22	0.00	0.51
	15	0.37	0.23	0.00	0.51

\* An increase in the amount of erosion was observed at approx. station 107.77 possible wash area intermittent around the circumference.



AEC PHENOLIC  
CROSS-SECTION

Max. and Min.  
Values

No surface ply lifting  
was observed

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Phenolic Sections - Forward Exit Cone

Motor No.: RSRM-32

Side: Right (B)

Date: 8-27-93

Assessment Engineer(s)/Inspector(s): M. Clark

Phenolic Sections:

Yes No Comment #

a. Cross-ply cracking in virgin material?

\_\_\_\_\_

b. Ply lifting?

\_\_\_\_\_

Forward Exit Cone Char and Erosion Measurements:

Station Location	0°		90°		180°		270°	
	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
1.0	_____	_____	_____	_____	_____	_____	_____	_____
4.0	_____	_____	_____	_____	_____	_____	_____	_____
4.6	_____	_____	_____	_____	_____	_____	_____	_____
8.0	_____	_____	_____	_____	_____	_____	_____	_____
12.0	_____	_____	_____	_____	_____	_____	_____	_____
16.0	_____	_____	_____	_____	_____	_____	_____	_____
20.0	_____	_____	_____	_____	_____	_____	_____	_____
24.0	_____	_____	_____	_____	_____	_____	_____	_____
28.0	_____	_____	_____	_____	_____	_____	_____	_____
32.0	_____	_____	_____	_____	_____	_____	_____	_____
32.9	_____	_____	_____	_____	_____	_____	_____	_____
34.0	_____	_____	_____	_____	_____	_____	_____	_____

Negative Margin of Safety? \_\_\_\_\_ Yes \_\_\_\_\_ No Station: \_\_\_\_\_ Degree: \_\_\_\_\_

Notes / Comments

Very small section left attached on fwd end  
was not recovered at wash. No measurements  
made.

Preliminary PFAR(s)? \_\_\_\_\_ Yes \_\_\_\_\_ No Preliminary PFAR Number(s): \_\_\_\_\_

Clarification Form(s)? \_\_\_\_\_ Yes \_\_\_\_\_ No Number of Forms Attached: \_\_\_\_\_

REVISION \_\_\_\_\_

DOC NO. TWR-64240 VOL  
SEC PAGE A-104

**POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Phenolic Sections - Throat Assembly**

Motor No.: **RSRM-32**      Side: **Right (B)**      Date: **8-26-93**

Assessment Engineer(s)/Inspector(s): **L.E. WILKES**

**Phenolic Sections:**

Yes      No      Comment #

a. Cross-ply cracking in virgin material?                      ✓                

b. Ply lifting?                      ✓                

**Throat Inlet Ring and Throat Ring Char and Erosion Measurements:**

Station	0°		90°		180°		270°	
Location	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
1.0	<u>1.10</u>	<u>.64</u>	<u>1.11</u>	<u>.62</u>	<u>1.05</u>	<u>.64</u>	<u>1.07</u>	<u>.68</u>
2.0	<u>1.10</u>	<u>.66</u>	<u>1.15</u>	<u>.66</u>	<u>1.07</u>	<u>.70</u>	<u>1.11</u>	<u>.65</u>
4.0	<u>1.16</u>	<u>.57</u>	<u>1.18</u>	<u>.67</u>	<u>1.14</u>	<u>.59</u>	<u>1.16</u>	<u>.68</u>
6.0	<u>1.21</u>	<u>.55</u>	<u>1.23</u>	<u>.66</u>	<u>1.20</u>	<u>.63</u>	<u>1.21</u>	<u>.67</u>
8.0	<u>1.19</u>	<u>.58</u>	<u>1.25</u>	<u>.61</u>	<u>1.23</u>	<u>.63</u>	<u>1.21</u>	<u>.57</u>
10.0	<u>1.16</u>	<u>.54</u>	<u>1.23</u>	<u>.65</u>	<u>1.16</u>	<u>.58</u>	<u>1.22</u>	<u>.56</u>
12.0	<u>1.13</u>	<u>.55</u>	<u>1.19</u>	<u>.58</u>	<u>1.15</u>	<u>.58</u>	<u>1.18</u>	<u>.58</u>
14.0	<u>1.12</u>	<u>.56</u>	<u>1.17</u>	<u>.63</u>	<u>1.12</u>	<u>.59</u>	<u>1.17</u>	<u>.59</u>
16.0	<u>1.04</u>	<u>.63</u>	<u>1.10</u>	<u>.58</u>	<u>1.15</u>	<u>.63</u>	<u>1.09</u>	<u>.65</u>
18.0	<u>.93</u>	<u>.64</u>	<u>.95</u>	<u>.71</u>	<u>.93</u>	<u>.71</u>	<u>.93</u>	<u>.75</u>
20.0	<u>.73</u>	<u>.76</u>	<u>.74</u>	<u>.80</u>	<u>.75</u>	<u>.78</u>	<u>.73</u>	<u>.81</u>
22.0	<u>.52</u>	<u>.75</u>	<u>.50</u>	<u>.83</u>	<u>.49</u>	<u>.81</u>	<u>.55</u>	<u>.77</u>
23.0	<u>.41</u>	<u>.78</u>	<u>.40</u>	<u>.85</u>	<u>.41</u>	<u>.79</u>	<u>.46</u>	<u>.81</u>

Negative Margin of Safety?                 Yes      ✓ No      Station:      Degree:                

**Notes / Comments**

Preliminary PFAR(s)?                 Yes      ✓ No      Preliminary PFAR Number(s):                

Clarification Form(s)?                 Yes      ✓ No      Number of Forms Attached:



**POSTFLIGHT OBSERVATION RECORD (PFOR)**  
**Nozzle Phenolic Sections - Forward Nose and Aft Inlet Rings**

Motor No.: RSRM-32	Side: Right (B)	Date: 8/26/93
--------------------	-----------------	---------------

Assessment Engineer(s)/Inspector(s): CLARK, PASSMAN, QUICK, WILKES

**Phenolic Sections:**

Yes      No      Comment #

a. Cross-ply cracking in virgin material?            ✓           

b. Ply lifting?            ✓           

**Forward Nose Ring Char and Erosion Measurements:**

Station	0°		90°		180°		270°	
Location	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
28.0	<u>1.07</u>	<u>.73</u>	<u>1.04</u>	<u>.66</u>	<u>1.22</u>	<u>.66</u>	<u>1.11</u>	<u>.66</u>
30.0	<u>.90</u>	<u>.64</u>	<u>.80</u>	<u>.78</u>	<u>.95</u>	<u>.69</u>	<u>.90</u>	<u>.65</u>
32.0	<u>.95</u>	<u>.60</u>	<u>.90</u>	<u>.65</u>	<u>.98</u>	<u>.59</u>	<u>.96</u>	<u>.56</u>

Negative Margin of Safety?            Yes ✓ No      Station:            Degree:           

**Aft Inlet Ring Char and Erosion Measurements:**

Station	0°		90°		180°		270°	
Location	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
34.0	<u>.84</u>	<u>.66</u>	<u>.85</u>	<u>.65</u>	<u>.90</u>	<u>.60</u>	<u>.88</u>	<u>.53</u>
36.0	<u>.86</u>	<u>.64</u>	<u>.87</u>	<u>.71</u>	<u>.89</u>	<u>.63</u>	<u>.89</u>	<u>.63</u>
38.0	<u>.92</u>	<u>.61</u>	<u>.94</u>	<u>.67</u>	<u>.98</u>	<u>.56</u>	<u>.95</u>	<u>.65</u>
39.0	<u>.96</u>	<u>.63</u>	<u>.98</u>	<u>.67</u>	<u>1.00</u>	<u>.64</u>	<u>.97</u>	<u>.67</u>

Negative Margin of Safety?            Yes ✓ No      Station:            Degree:           

**Notes / Comments**

Preliminary PFAR(s)?            Yes ✓ No      Preliminary PFAR Number(s):           

Clarification Form(s)?            Yes ✓ No      Number of Forms Attached:

POSTFLIGHT OBSERVATION RECORD (PFOR)

Nozzle Phenolic Sections - Nose Cap

Motor No.: RSRM-32	Side: Right (B)	Date: 8/26/93
--------------------	-----------------	---------------

Assessment Engineer(s)/Inspector(s): CLARK, PASSMAN, QUICK, WILKES

Phenolic Sections:

Yes No Comment #

a. Cross-ply cracking in virgin material?

☐ Yes ☒ No

b. Ply lifting?

☐ Yes ☒ No

Nose Cap Char and Erosion Measurements:

Station	0°		90°		180°		270°	
Location	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
1.5		.78*	.32	.51	.84*		.72*	
4.0	.37	.47	.33	.51	.47	.42	.29	.53
6.0	.37	.44	.33	.51	.38	.46	.33	.52
8.0	.41	.46	.39	.49	.41	.41	.41	.55
10.0	.49	.41	.45	.45	.48	.37	.47	.48
12.0	.51	.45	.48	.44	.57	.39	.54	.45
14.0	.59	.48	.60	.44	.61	.43	.64	.46
16.0	.71	.37	.66	.46	.73	.41	.66	.44
18.0	.80	.49	.79	.45	.94	.42	.75	.49
20.0	1.02	.64	.97	.55	1.15	.55	.95	.58
22.0	1.61	.78	1.64	.69	1.73	.73	1.52	.81
24.0	1.89	.85	1.80	.76	1.90	.84	1.80	.85
26.0	1.45	.73	1.34	.75	1.41	.74	1.39	.84

Negative Margin of Safety? ☐ Yes ☒ No Station: Degree:

Notes / Comments \* DENOTES MAX AFFECTED DEPTH

Preliminary PFAR(s)? ☐ Yes ☒ No Preliminary PFAR Number(s):

Clarification Form(s)? ☐ Yes ☒ No Number of Forms Attached:

POSTFLIGHT OBSERVATION RECORD (PFOR)

Nozzle Phenolic Sections - Cowl

Motor No.: RSRM-32	Side: Right (B)	Date: 8-24-93
--------------------	-----------------	---------------

Assessment Engineer(s)/Inspector(s): L.E. WILKES

Phenolic Sections:

- a. Cross-ply cracking in virgin material?  
b. Ply lifting?

Yes	No	Comment #
<input type="checkbox"/>	<input checked="" type="checkbox"/>	
<input type="checkbox"/>	<input checked="" type="checkbox"/>	

Cowl Char and Erosion Measurements:

Station Location	0°		90°		180°		270°	
	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
0.3	.29	.73	.28	.80	NA	1.07*	.24	.73
1.0	.30	.64	.27	.75	.30	.73	.23	.71
2.0	.29	.60	.24	.65	.30	.72	.24	.72
3.0	.25	.65	.21	.67	.24	.71	.21	.76
4.0	.24	.65	.20	.71	.21	.74	.20	.75
5.0	.19	.73	.18	.77	.18	.73	.17	.77
6.0	.17	.69	.16	.71	.15	.72	.15	.80
6.8	.20	.91	.16	.84	NA	1.05*	.12	.84

Negative Margin of Safety? ☐ Yes ☒ No Station: \_\_\_\_\_ Degree: \_\_\_\_\_

Notes / Comments \* TOTAL HEAT AFFECTED DETAIL (CHAR LINE)

Special Issue 3.3.17 POSTFIRE COWL CCP CONDITION AFTER 15 THS OF POST FLIGHT MOTOR NOZZLES. NO PLY LIFTING.

ORIGINAL PAGE IS  
OF POOR QUALITY

Preliminary PFAR(s)? ☐ Yes ☒ No

Preliminary PFAR Number(s): \_\_\_\_\_

Clarification Form(s)? ☐ Yes ☒ No

Number of Forms Attached: \_\_\_\_\_

**POSTFLIGHT OBSERVATION RECORD (PFOR)**  
**Nozzle Phenolic Sections - Fixed Housing**

Motor No.: RSRM-32 Side: Right (B) Date: 8-26-93

Assessment Engineer(s)/Inspector(s): L.E. WILKES

Phenolic Sections:	Yes	No	Comment #
a. Cross-ply cracking in virgin material?	<u>          </u>	<u>✓</u>	<u>          </u>
b. Ply lifting?	<u>          </u>	<u>✓</u>	<u>          </u>

**Fixed Housing Char and Erosion Measurements:**

Station	0°		90°		180°		270°	
Location	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
0.0	<u>.03</u>	<u>1.05</u>	<u>.06</u>	<u>.95</u>	<u>.03</u>	<u>1.05</u>	<u>.02</u>	<u>1.03</u>
1.0	<u>.02</u>	<u>1.09</u>	<u>.00</u>	<u>.90</u>	<u>.02</u>	<u>.94</u>	<u>.01</u>	<u>1.04</u>
2.0	<u>.01</u>	<u>1.05</u>	<u>          </u>	<u>1.00</u>	<u>.00</u>	<u>.87</u>	<u>.00</u>	<u>1.08</u>
3.0	<u>.03</u>	<u>1.07</u>	<u>          </u>	<u>.91</u>	<u>.03</u>	<u>.86</u>	<u>          </u>	<u>1.05</u>
4.0	<u>NA</u>	<u>1.08*</u>	<u>          </u>	<u>.88</u>	<u>.00</u>	<u>.88</u>	<u>          </u>	<u>1.03</u>
5.0	<u>.00</u>	<u>1.07</u>	<u>          </u>	<u>.84</u>	<u>          </u>	<u>.87</u>	<u>          </u>	<u>.98</u>
6.0	<u>.00</u>	<u>1.05</u>	<u>          </u>	<u>.87</u>	<u>          </u>	<u>.87</u>	<u>          </u>	<u>1.00</u>
7.0	<u>.00</u>	<u>1.00</u>	<u>          </u>	<u>.85</u>	<u>          </u>	<u>.84</u>	<u>          </u>	<u>.98</u>
8.0	<u>.00</u>	<u>.92</u>	<u>          </u>	<u>.84</u>	<u>.00</u>	<u>.73</u>	<u>.00</u>	<u>.82</u>
9.0	<u>NA</u>	<u>.70*</u>	<u>.00</u>	<u>.72</u>	<u>NA</u>	<u>.71*</u>	<u>NA</u>	<u>.78*</u>
10.75	<u>.44</u>	<u>1.09</u>	<u>.15</u>	<u>1.63</u>	<u>NA</u>	<u>1.66*</u>	<u>NA</u>	<u>1.52*</u>

Negative Margin of Safety?            Yes            No            Station:            Degree:           

Notes / Comments \* TOTAL AFFECTED DEPTH (CHAR LIFE).

ORIGINAL PAGE IS  
OF POOR QUALITY

Preliminary PFAR(s)?            Yes            No            Preliminary PFAR Number(s):           

Clarification Form(s)?            Yes            No            Number of Forms Attached:

**POSTFLIGHT OBSERVATION RECORD (PFOR)**  
**Nozzle Phenolic Sections - Outer Boot Ring and Flexible Boot**

<b>Motor No.:</b> RSRM-32	<b>Side:</b> Right (B)	<b>Date:</b> 8-24-93
---------------------------	------------------------	----------------------

**Assessment Engineer(s)/Inspector(s):** L.E. WILKES

<b>Phenolic Sections:</b>	<b>Yes</b>	<b>No</b>	<b>Comment #</b>
a. Cross-ply cracking in virgin material?	<u>          </u>	<u>✓</u>	<u>          </u>
b. Ply lifting?	<u>          </u>	<u>✓</u>	<u>          </u>

<b>Flexible Boot/Outer Boot Ring Interface:</b>	<b>Yes</b>	<b>No</b>	<b>Comment #</b>
c. Separations?	<u>✓</u>	<u>          </u>	<u>1</u>
d. Heat effects in separations (if present)?	<u>          </u>	<u>✓</u>	<u>          </u>

**Outer Boot Ring Char and Erosion Measurements:**

Station	0°		90°		180°		270°	
Location	Erosion	Char	Erosion	Char	Erosion	Char	Erosion	Char
8.0	<u>.06</u>	<u>1.02</u>	<u>.05</u>	<u>.93</u>	<u>.08</u>	<u>.91</u>	<u>NA</u>	<u>.89*</u>
9.0	<u>.04</u>	<u>1.01</u>	<u>.02</u>	<u>.90</u>	<u>.05</u>	<u>.87</u>	<u>.04</u>	<u>.86</u>
10.0	<u>.01</u>	<u>1.03</u>	<u>.03</u>	<u>.87</u>	<u>.01</u>	<u>.87</u>	<u>.06</u>	<u>.56</u>
11.3	<u>.00</u>	<u>1.01</u>	<u>.06</u>	<u>.88</u>	<u>.00</u>	<u>.92</u>	<u>.04</u>	<u>.92</u>

Negative Margin of Safety?            Yes ✓ No            Station:            Degree:           

**Number of Plies Remaining on the Flexible Boot:**

Degree Location	Plies Remaining
0	<u>3.1</u>
90	<u>3.2</u>
180	<u>3.4</u>
270	<u>3.1</u>

Negative Margin of Safety?            Yes            No            Degree:           

**Notes / Comments** \* TOTAL HEAT AFFECTED DEPTH (CHAR LINE)  
① SEPARATIONS AT 0° & 270°, NO HEAT EFFECTS.

Preliminary PFAR(s)?            Yes ✓ No            Preliminary PFAR Number(s):           

Verification Form(s)?            Yes ✓ No            Number of Forms Attached:

**POSTFLIGHT OBSERVATION RECORD (PFOR)**  
**Barrier-Booster Leak Check Port Plug and Port (At Removal) - 126 Degrees**

Motor No.: <b>RSRM-32</b>	Side: <b>Right (B)</b>	Date: <b>7/9/93</b>
---------------------------	------------------------	---------------------


Assessment Engineer(s)/Inspector(s): Eden / Nolan

Leak Check Port Plug and Port:

	Yes	No	Comment #
a. Soot to or past O-ring?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
b. Sooted surfaces?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
c. Heat affected or eroded O-ring (installed)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
d. O-ring damage (installed)?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
e. Heat affected or eroded metal?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
f. Foreign material?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	①
g. Excessive grease?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
h. Medium or heavy corrosion?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
i. Metal damage?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

Notes / Comments

① Hairlike fiber found on Leak check plug Shoulder seal. Hair was removed. It was photographed before it was removed. No evidence to indicate that hair was in place before firing. (Hair-like fiber was a result of disassembly).



Preliminary PFAR(s)? ☐ Yes ☒ No

Preliminary PFAR Number(s): \_\_\_\_\_

Clarification Form(s)? ☐ Yes ☒ No

Number of Forms Attached: \_\_\_\_\_

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Barrier-Booster Leak Check Port Plug and O-ring (Detailed) - 126 Degrees

Motor No.: RSRM-32	Side: Right (B)	Date: 7/9/93
Assessment Engineer(s)/Inspector(s): Eden / Nolan		
<u>Leak Check Port Plug:</u>	Yes	No
a. Foreign material between the O-ring and plug?	_____	✓ _____
b. Heat affected or eroded metal?	_____	✓ _____
c. Seal surface/thread damage?	_____	✓ _____
<u>Secondary O-ring:</u>		
d. Heat affected or eroded O-ring?	_____	✓ _____
e. O-ring defects/damage?	_____	✓ _____
Notes / Comments		
Preliminary PFAR(s)? _____ Yes <u>✓</u> No    Preliminary PFAR Number(s): _____		

Clarification Form(s)? \_\_\_\_\_ Yes    ✓ No    Number of Forms Attached: \_\_\_\_\_

POSTFLIGHT OBSERVATION RECORD (PFOR)

Nozzle Internal Joint Leak Check Port Plug and Port (At Removal) - Joint 2

Motor No.: RSRM-32	Side: Right (B)	Date: 7-9-93
Assessment Engineer(s)/Inspector(s): M. Offoter, W. Steiny		
<b>Leak Check Port Plug and Port:</b>		
	Yes	No
a. Soot to or past O-ring?	_____	_____✓
b. Sooted surfaces?	_____	_____✓
c. Heat affected or eroded O-ring (installed)?	_____	_____✓
d. O-ring damage (installed)?	_____	_____✓
e. Heat affected or eroded metal?	_____	_____✓
f. Foreign material?	_____	_____✓
g. Excessive grease?	_____	_____✓
h. Medium or heavy corrosion?	_____	_____✓
i. Metal damage?	_____	_____✓
Plug Break-away and Running Torques (inch-lbs):		
	Break-away:	8
	Running:	4
Notes / Comments		
Preliminary PFAR(s)? _____ Yes _____✓ No Preliminary PFAR Number(s): _____		
Clarification Form(s)? _____ Yes _____✓ No Number of Forms Attached: _____		



POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Internal Joint Leak Check Port Plug and O-ring (Detailed) - Joint 2

Motor No.: RSRM-32	Side: Right (B)	Date: 7-9-93
Assessment Engineer(s)/Inspector(s): <i>W. Sperry, M. Offalter, B. Ferguson</i>		
<b>Leak Check Port Plug:</b>		
	Yes	No
a. Foreign material between the O-ring and plug?	_____	_____✓_____
b. Heat affected or eroded metal?	_____	_____✓_____
c. Seal surface/thread damage?	_____	_____✓_____
<b>Secondary O-ring:</b>		
d. Heat affected or eroded O-ring?	_____	_____✓_____
e. O-ring defects/damage?	_____	_____✓_____
Notes / Comments		
Preliminary PFAR(s)? _____ Yes _____✓_____ No      Preliminary PFAR Number(s): _____		
Clarification Form(s)? _____ Yes _____✓_____ No      Number of Forms Attached: _____		

POSTFLIGHT OBSERVATION RECORD (PFOR)

Nozzle Internal Joint Leak Check Port Plug and Port (At Removal) - Joint 3

Motor No.: RSRM-32	Side: Right (B)	Date: 7-9-93
Assessment Engineer(s)/Inspector(s): <u>N. Sperry, M. Offalter</u>		
<b>Leak Check Port Plug and Port:</b>		
	Yes	No
a. Soot to or past O-ring?	_____	✓ _____
b. Sooted surfaces?	_____	✓ _____
c. Heat affected or eroded O-ring (installed)?	_____	✓ _____
d. O-ring damage (installed)?	_____	✓ _____
e. Heat affected or eroded metal?	_____	✓ _____
f. Foreign material?	_____	✓ _____
g. Excessive grease?	_____	✓ _____
h. Medium or heavy corrosion?	_____	✓ _____
i. Metal damage?	_____	✓ _____
Plug Break-away and Running Torques (inch-lbs):		Break-away: <u>17</u>
		Running: <u>5</u>
Notes / Comments		
Preliminary PFAR(s)? _____ Yes _____ ✓ No Preliminary PFAR Number(s): _____		

Clarification Form(s)? \_\_\_\_\_ Yes \_\_\_\_\_ ✓ No Number of Forms Attached: \_\_\_\_\_

**POSTFLIGHT OBSERVATION RECORD (PFOR)**  
**Nozzle Internal Joint Leak Check Port Plug and O-ring (Detailed) - Joint 3**

<b>Motor No.:</b> RSRM-32	<b>Side:</b> Right (B)	<b>Date:</b> 9-9-93
<b>Assessment Engineer(s)/Inspector(s):</b> W. Sperry, M. Asfalter, B. Ferguson		
<b><u>Leak Check Port Plug:</u></b>		
	<b>Yes</b>	<b>No</b>
a. Foreign material between the O-ring and plug?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
b. Heat affected or eroded metal?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
c. Seal surface/thread damage?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
<b><u>Secondary O-ring:</u></b>		
d. Heat affected or eroded O-ring?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
e. O-ring defects/damage?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
<b>Notes / Comments</b>		
<b>Preliminary PFAR(s)?</b> <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <b>Preliminary PFAR Number(s):</b> _____		
<b>Clarification Form(s)?</b> <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <b>Number of Forms Attached:</b> _____		

POSTFLIGHT OBSERVATION RECORD (PFOR)

Nozzle Internal Joint Leak Check Port Plug and Port (At Removal) - Joint 4

Motor No.: RSRM-32	Side: Right (B)	Date: 7 July 1993	
Assessment Engineer(s)/Inspector(s): A. Carlisle, B. Quick, M. Lyons, J. Richards			
<u>Leak Check Port Plug and Port:</u>	Yes	No	Comment #
a. Soot to or past O-ring?	_____	✓	_____
b. Sooted surfaces?	_____	✓	_____
c. Heat affected or eroded O-ring (installed)?	_____	✓	_____
d. O-ring damage (installed)?	_____	✓	_____
e. Heat affected or eroded metal?	_____	✓	_____
f. Foreign material?	_____	✓	_____
g. Excessive grease?	_____	✓	_____
h. Medium or heavy corrosion?	_____	✓	_____
i. Metal damage?	_____	✓	_____
Plug Break-away and Running Torques (inch-lbs):		Break-away: 37	
		Running: 5	

Notes / Comments

Preliminary PFAR(s)? \_\_\_\_\_ Yes \_\_\_\_\_ No ☒ Preliminary PFAR Number(s): \_\_\_\_\_

Clarification Form(s)? \_\_\_\_\_ Yes \_\_\_\_\_ No ☒ Number of Forms Attached: \_\_\_\_\_

REVISION \_\_\_\_\_

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Internal Joint Leak Check Port Plug and O-ring (Detailed) - Joint 4

Motor No.: RSRM-32	Side: Right (B)	Date: 7 July 1993
Assessment Engineer(s)/Inspector(s): A. Carlisle, B. Quick, M. Lyons, J. Richards		
<b>Leak Check Port Plug:</b>		
	Yes	No
a. Foreign material between the O-ring and plug?	_____	✓ _____
b. Heat affected or eroded metal?	_____	✓ _____
c. Seal surface/thread damage?	_____	✓ _____
<b>Secondary O-ring:</b>		
	Yes	No
d. Heat affected or eroded O-ring?	_____	✓ _____
e. O-ring defects/damage?	_____	✓ _____
Notes / Comments		
Preliminary PFAR(s)? _____ Yes _____ No ✓		
Preliminary PFAR Number(s): _____		
Clarification Form(s)? _____ Yes _____ No ✓		
Number of Forms Attached: _____		

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Nozzle Internal Joint Leak Check Port Plug and Port (At Removal) - Joint 5

Motor No.: RSRM-32	Side: Right (B)	Date: 8 July 1993
Assessment Engineer(s)/Inspector(s): A. Carlisle, M. Lyons, J. Richards		
<b>Leak Check Port Plug and Port:</b>		
	Yes	No
a. Soot to or past O-ring?	_____	✓ _____
b. Sooted surfaces?	_____	✓ _____
c. Heat affected or eroded O-ring (installed)?	_____	✓ _____
d. O-ring damage (installed)?	_____	✓ _____
e. Heat affected or eroded metal?	_____	✓ _____
f. Foreign material?	_____	✓ _____
g. Excessive grease?	_____	✓ _____
h. Medium or heavy corrosion?	_____	✓ _____
i. Metal damage?	_____	✓ _____
Plug Break-away and Running Torques (inch-lbs):		Break-away: 42
		Running: 5
Notes / Comments		
Preliminary PFAR(s)? _____ Yes    ✓ _____ No    Preliminary PFAR Number(s): _____		

Clarification Form(s)? \_\_\_\_\_ Yes    ✓ \_\_\_\_\_ No    Number of Forms Attached: \_\_\_\_\_

REVISION \_\_\_\_\_

POSTFLIGHT OBSERVATION RECORD (PFOR)

Nozzle Internal Joint Leak Check Port Plug and O-ring (Detailed) - Joint 5

Motor No.: RSRM-32	Side: Right (B)	Date: 8 July 1993
Assessment Engineer(s)/Inspector(s): A. Carlisle, M. Lyons, J. Richards		
<b>Leak Check Port Plug:</b>		
a. Foreign material between the O-ring and plug?	Yes _____	No _____ ✓
b. Heat affected or eroded metal?	_____	_____ ✓
c. Seal surface/thread damage?	_____	_____ ✓
<b>Secondary O-ring:</b>		
d. Heat affected or eroded O-ring?	_____	_____ ✓
e. O-ring defects/damage?	_____	_____ ✓
Notes / Comments		
Preliminary PFAR(s)? _____ Yes _____ No ✓		
Preliminary PFAR Number(s): _____		

Clarification Form(s)? \_\_\_\_\_ Yes \_\_\_\_\_ No ✓      Number of Forms Attached: \_\_\_\_\_

REVISION \_\_\_\_\_

POSTFLIGHT OBSERVATION RECORD (PFOR)

Case Factory Joint - Forward Dome

Motor No.: RSRM-32	Side: Right (B)	Date: 29 SEP 1993
--------------------	-----------------	-------------------

Assessment Engineer(s)/Inspector(s): Birch

Joint Seals and Metal:

- a. Heat affected or eroded O-ring?
- b. Heavy corrosion (pitting) in joint?
- c. Heavy corrosion (pitting) in leak check port?

Yes

No

Comment #

<u>X</u>	<u>X</u>	<u>1</u>
<u>X</u>	<u>X</u>	

Note: Remove corrosion to determine if pitting has occurred. Care should be taken not to damage the hardware. Solvent and/or green Scotch-Brite® pads may be used to remove the corrosion. Corrosion removal is to be done in a circumferential direction only.

Notes / Comments

FWD DOME Tang Joint

1 - At Approximately 119°, Corrosion Was Removed With Green Scotchbrite, Revealing Some Pitting,

At Approximately 297°, Chemlock Was Removed With Green Scotchbrite, Revealing A Large Pit In The Tang Sealing Zone

At Approximately 186°, Chemlock/Corrosion Combination Was Removed With Green Scotchbrite Revealing Some Pitting In The Tang Seal Zone

Preliminary PFAR(s)?   /   Yes        No

Preliminary PFAR Number(s): 57C-03

Clarification Form(s)?        Yes        No

Number of Forms Attached:       

REVISION



POSTFLIGHT OBSERVATION RECORD (PFOR)  
Case Factory Joint - Forward Cylinder/Cylinder

Motor No.: RSRM-32	Side: Right (B)	Date: 29 Sept 93
--------------------	-----------------	------------------

Assessment Engineer(s)/Inspector(s): Birch

Joint Seals and Metal:

Yes

No

Comment #

a. Heat affected or eroded O-ring?

\_\_\_\_\_

X

\_\_\_\_\_

b. Heavy corrosion (pitting) in joint?

\_\_\_\_\_

X

\_\_\_\_\_

c. Heavy corrosion (pitting) in leak check port?

\_\_\_\_\_

X

\_\_\_\_\_

Note: Remove corrosion to determine if pitting has occurred. Care should be taken not to damage the hardware. Solvent and/or green Scotch-Brite® pads may be used to remove the corrosion. Corrosion removal is to be done in a circumferential direction only.

Notes / Comments

Preliminary PFAR(s)? \_\_\_\_\_ Yes X No

Preliminary PFAR Number(s): \_\_\_\_\_

Clarification Form(s)? \_\_\_\_\_ Yes X No

Number of Forms Attached: \_\_\_\_\_

REVISION \_\_\_\_\_

DOC NO.	TWR-64240	VOL
SEC	PAGE	A-122

POSTFLIGHT OBSERVATION RECORD (PFOR)

Case Factory Joint - Forward Center

Motor No.: RSRM-32	Side: Right (B)	Date: 10-25-93
--------------------	-----------------	----------------

Assessment Engineer(s)/Inspector(s): H. ZAREMBA

Joint Seals and Metal:

	Yes	No	Comment #
a. Heat affected or eroded O-ring?	_____	<input checked="" type="checkbox"/>	_____
b. Heavy corrosion (pitting) in joint?	_____	<input checked="" type="checkbox"/>	_____
c. Heavy corrosion (pitting) in leak check port?	_____	<input checked="" type="checkbox"/>	_____

Note: Remove corrosion to determine if pitting has occurred. Care should be taken not to damage the hardware. Solvent and/or green Scotch-Brite® pads may be used to remove the corrosion. Corrosion removal is to be done in a circumferential direction only.

Notes / Comments

Preliminary PFAR(s)? \_\_\_\_\_ Yes ☒ No Preliminary PFAR Number(s): \_\_\_\_\_

Clarification Form(s)? \_\_\_\_\_ Yes ☒ No Number of Forms Attached: \_\_\_\_\_

REVISION \_\_\_\_\_

DOC NO. TWR-64240  
SEC \_\_\_\_\_

VOL \_\_\_\_\_  
PAGE A-123

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Case Factory Joint - Aft Center

Motor No.: RSRM-32	Side: Right (B)	Date: 10-15-92
--------------------	-----------------	----------------

Assessment Engineer(s)/Inspector(s): ERIC HAY

Joint Seals and Metal:

- a. Heat affected or eroded O-ring?  
b. Heavy corrosion (pitting) in joint?  
c. Heavy corrosion (pitting) in leak check port?

Yes


No

Comment #

	<input checked="" type="checkbox"/>	
	<input checked="" type="checkbox"/>	
	<input checked="" type="checkbox"/>	

Note: Remove corrosion to determine if pitting has occurred. Care should be taken not to damage the hardware. Solvent and/or green Scotch-Brite® pads may be used to remove the corrosion. Corrosion removal is to be done in a circumferential direction only.

Notes / Comments



OCT 15 1993  
ERRR

NONE

Preliminary PFAR(s)? ☐ Yes ☒ No

Preliminary PFAR Number(s): N/A

Clarification Form(s)? ☐ Yes ☒ No

Number of Forms Attached: \_\_\_\_\_

REVISION \_\_\_\_\_

DOC NO. TWR-64240 | VOL  
SEC | PAGE A-124

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Case Factory Joint - ET Attach/Stiffener

Motor No.: RSRM-32	Side: Right (B)	Date: 8-23-93
Assessment Engineer(s)/Inspector(s): G. Rich		
<b>Joint Seals and Metal:</b>		
	Yes	No
a. Heat affected or eroded O-ring?	_____	_____/_____
b. Heavy corrosion (pitting) in joint?	_____	_____/_____
c. Heavy corrosion (pitting) in leak check port?	_____	_____/_____
<p>Note: Remove corrosion to determine if pitting has occurred. Care should be taken not to damage the hardware. Solvent and/or green Scotch-Brite® pads may be used to remove the corrosion. Corrosion removal is to be done in a circumferential direction only.</p>		
Notes / Comments		
Preliminary PFAR(s)? _____ Yes _____/_____ No		
Preliminary PFAR Number(s): _____		

Clarification Form(s)? \_\_\_\_\_ Yes \_\_\_\_\_/\_\_\_\_\_ No      Number of Forms Attached: \_\_\_\_\_

REVISION \_\_\_\_\_

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Case Factory Joint - Stiffener/Stiffener

Motor No.: RSRM-32	Side: Right (B)	Date: 08 20 93
--------------------	-----------------	----------------

Assessment Engineer(s)/Inspector(s): DARRYL MARBLE

Joint Seals and Metal:

	Yes	No	Comment #
a. Heat affected or eroded O-ring?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
b. Heavy corrosion (pitting) in joint?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
c. Heavy corrosion (pitting) in leak check port?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Note: Remove corrosion to determine if pitting has occurred. Care should be taken not to damage the hardware. Solvent and/or green Scotch-Brite® pads may be used to remove the corrosion. Corrosion removal is to be done in a circumferential direction only.

Notes / Comments


STIFF TO STIFF JOINT

Preliminary PFAR(s)? ☐ Yes ☒ No Preliminary PFAR Number(s): ☐

Clarification Form(s)? ☐ Yes ☒ No Number of Forms Attached: ☐

POSTFLIGHT OBSERVATION RECORD (PFOR)  
Case Factory Joint - Aft Dome

Motor No.: RSRM-32	Side: Right (B)	Date: 08-20-93
Assessment Engineer(s)/Inspector(s): DAERYL MARBLE		
<b>Joint Seals and Metal</b>		
Yes	No	Comment #
_____	✓	_____
_____	✓	_____
_____	✓	_____
<p>a. Heat affected or eroded O-ring?</p> <p>b. Heavy corrosion (pitting) in joint?</p> <p>c. Heavy corrosion (pitting) in leak check port?</p>		
<p>Note: Remove corrosion to determine if pitting has occurred. Care should be taken not to damage the hardware. Solvent and/or green Scotch-Brite® pads may be used to remove the corrosion. Corrosion removal is to be done in a circumferential direction only.</p>		
<p>Notes / Comments</p> <p style="font-size: 2em; margin-left: 100px;">NONE</p>		
<p>Preliminary PFAR(s)? _____ Yes _____ No ✓</p>		
<p>Preliminary PFAR Number(s): _____</p>		
<p>Clarification Form(s)? _____ Yes _____ No ✓</p>		
<p>Number of Forms Attached: _____</p>		



## **Appendix B**

### **Nozzle Postfire Data**

## **Final Postflight Hardware Evaluation Report**

### **RSRM-32 (STS-57)**

**November 1993**

**Prepared for:**

**NATIONAL AERONAUTICS AND SPACE ADMINISTRATION  
GEORGE C. MARSHALL SPACE FLIGHT CENTER  
MARSHALL SPACE FLIGHT CENTER, ALABAMA 35812**

<b>Contract No.</b>	<b>NAS8-38100</b>
<b>DR No.</b>	<b>4-23</b>
<b>WBS No.</b>	<b>4C601-04-01</b>
<b>ECS No.</b>	<b>SS4775</b>

***Thiokol* CORPORATION**  
**SPACE OPERATIONS**

P.O. Box 707, Brigham City, Utah 84302-0707 (801) 863-3511

## Table of Contents

<u>Table</u>	<u>Description</u>	<u>Page</u>
B-I	LH Forward Exit Cone Assembly Char and Erosion Data .....	B-2
B-II	LH Throat Assembly Char and Erosion Data .....	B-3
B-III	RH Throat Assembly Char and Erosion Data .....	B-4
B-IV	LH Nose Inlet Assembly Char and Erosion Data .....	B-5
B-V	RH Nose Inlet Assembly Char and Erosion Data .....	B-7
B-VI	LH Cowl/OBR Char and Erosion Data .....	B-9
B-VII	RH Cowl/OBR Char and Erosion Data .....	B-10
B-VIII	LH Fixed Housing Assembly Char and Erosion Data .....	B-11
B-IX	RH Fixed Housing Assembly Char and Erosion Data .....	B-12
B-X	LH Aft Exit Cone Assembly Char and Erosion Data .....	B-13



RSRM-32A Forward Exit Cone Assembly Erosion and Char Data

Angular Location	Stations											
	0	4.0	4.6	8.0	12.0	16.0	20.0	24.0	28.0	32.0	32.9	34.0
0 degrees												
Measured Erosion	0.37	0.36	0.37	0.36	0.35	NA	NA	NA	0.30	0.21	0.18	0.15
Measured Char *	0.75	0.73	0.71	0.71	0.76	NA	NA	NA	0.70	0.75	0.70	0.67
Adjusted Char *	0.60	0.58	0.57	0.57	0.61	NA	NA	NA	0.56	0.60	0.56	0.54
Denominator	1.38	1.34	1.12	1.32	1.36	NA	NA	NA	1.21	1.11	0.83	0.93
RSRM Liner Thickness	1.807	1.731	1.411	1.629	1.524	NA	NA	NA	1.328	1.372	1.127	1.408
Margin of Safety	0.31	0.29	0.26	0.23	0.12	NA	NA	NA	0.10	0.24	0.36	0.52
90 degrees												
Measured Erosion	0.37	0.35	0.37	0.37	0.32	NA	NA	NA	NA	0.19	0.19	0.15
Measured Char *	0.76	0.76	0.72	0.68	0.73	NA	NA	NA	NA	0.78	0.75	0.75
Adjusted Char *	0.61	0.61	0.58	0.54	0.58	NA	NA	NA	NA	0.62	0.60	0.60
Denominator	1.39	1.36	1.13	1.31	1.27	NA	NA	NA	NA	1.10	0.89	1.01
RSRM Liner Thickness	1.807	1.731	1.411	1.629	1.524	NA	NA	NA	1.328	1.372	1.127	1.408
Margin of Safety	0.30	0.28	0.25	0.24	0.20	NA	NA	NA	NA	0.24	0.27	0.40
180 degrees												
Measured Erosion	0.33	0.34	0.36	0.35	0.33	NA	NA	NA	0.28	0.25	0.18	0.15
Measured Char *	0.78	0.74	0.75	0.70	0.70	NA	NA	NA	0.70	0.68	0.71	0.74
Adjusted Char *	0.62	0.59	0.60	0.56	0.56	NA	NA	NA	0.56	0.54	0.57	0.59
Denominator	1.34	1.32	1.14	1.29	1.26	NA	NA	NA	1.18	1.10	0.84	0.99
RSRM Liner Thickness	1.807	1.731	1.411	1.629	1.524	NA	NA	NA	1.328	1.372	1.127	1.408
Margin of Safety	0.35	0.31	0.24	0.26	0.21	NA	NA	NA	0.13	0.24	0.34	0.42
270 degrees												
Measured Erosion	0.36	0.37	0.36	0.35	0.33	NA	NA	NA	0.28	0.19	0.15	0.14
Measured Char *	0.76	0.74	0.77	0.74	0.65	NA	NA	NA	0.77	0.82	0.81	0.82
Adjusted Char *	0.61	0.59	0.62	0.59	0.52	NA	NA	NA	0.62	0.66	0.65	0.66
Denominator	1.37	1.37	1.16	1.33	1.21	NA	NA	NA	1.25	1.14	0.87	1.06
RSRM Liner Thickness	1.807	1.731	1.411	1.629	1.524	NA	NA	NA	1.328	1.372	1.127	1.408
Margin of Safety	0.32	0.26	0.22	0.22	0.26	NA	NA	NA	0.07	0.20	0.29	0.33
Minimum margin of safety is 0.07 at station 28.00 degree 270.00												
Maximum margin of safety is 0.52 at station 34.00 degree 0.00												

\* Measured char adjusted to end of action time

Margin of safety =  $\frac{\text{minimum liner thickness}}{1.70 \times \text{erosion} + 1.25 \times \text{adj char}}$  - 1

RSRM-32A Throat Assembly Erosion and Char Data

Angular Location	Stations													
	0 degrees	1.0	2.0	4.0	6.0	8.0	10.0	12.0	14.0	16.0	18.0	20.0	22.0	23.0
Measured Erosion	1.07	1.11	1.17	1.23	1.29	1.29	1.18	1.15	1.13	1.08	0.96	0.76	0.53	0.44
Measured Char	0.62	0.71	0.68	0.63	0.50	0.50	0.56	0.60	0.62	0.69	0.78	0.80	0.80	0.82
Adjusted Char	0.47	0.53	0.51	0.47	0.38	0.42	0.45	0.47	0.47	0.52	0.62	0.64	0.64	0.66
Denominator	2.72	2.69	2.98	3.05	3.05	3.05	2.88	2.86	2.84	2.81	2.70	2.32	1.86	1.70
RSRM Liner Thickness	3.174	3.247	3.314	3.280	3.183	3.183	3.397	3.517	3.626	3.710	3.586	3.231	2.583	2.110
Margin of Safety	0.17	0.13	0.11	0.08	0.04	0.04	0.18	0.23	0.28	0.32	0.33	0.39	0.39	0.24
90 degrees														
Measured Erosion	1.06	1.08	1.14	1.20	1.20	1.21	1.19	1.16	1.16	1.05	0.95	0.78	0.51	0.47
Measured Char	0.62	0.61	0.68	0.64	0.64	0.56	0.54	0.57	0.58	0.68	0.76	0.71	0.81	0.80
Adjusted Char	0.47	0.46	0.51	0.48	0.42	0.42	0.41	0.43	0.43	0.51	0.61	0.57	0.65	0.64
Denominator	2.70	2.73	2.92	3.00	2.94	2.94	2.89	2.85	2.86	2.74	2.66	2.27	1.83	1.74
RSRM Liner Thickness	3.174	3.247	3.314	3.280	3.183	3.183	3.397	3.517	3.626	3.710	3.586	3.231	2.583	2.110
Margin of Safety	0.18	0.19	0.14	0.09	0.08	0.08	0.18	0.23	0.27	0.36	0.35	0.42	0.41	0.21
180 degrees														
Measured Erosion	1.06	1.09	1.16	1.20	1.20	1.25	1.18	1.14	1.15	1.10	0.96	0.77	0.51	0.44
Measured Char	0.68	0.66	0.59	0.64	0.50	0.50	0.55	0.62	0.59	0.65	0.68	0.75	0.81	0.80
Adjusted Char	0.51	0.50	0.44	0.48	0.38	0.41	0.47	0.47	0.44	0.49	0.54	0.60	0.65	0.64
Denominator	2.76	2.80	2.87	3.00	2.97	2.97	2.88	2.86	2.85	2.81	2.60	2.29	1.83	1.66
RSRM Liner Thickness	3.174	3.247	3.314	3.280	3.183	3.183	3.397	3.517	3.626	3.710	3.586	3.231	2.583	2.110
Margin of Safety	0.15	0.16	0.15	0.09	0.07	0.07	0.18	0.23	0.27	0.32	0.38	0.41	0.41	0.26
270 degrees														
Measured Erosion	1.03	1.07	1.12	1.19	1.23	1.23	1.15	1.13	1.13	1.14	0.94	0.72	0.47	0.41
Measured Char	0.62	0.65	0.68	0.70	0.70	0.55	0.55	0.60	0.56	0.58	0.66	0.77	0.84	0.82
Adjusted Char	0.47	0.49	0.51	0.53	0.41	0.41	0.41	0.45	0.42	0.43	0.53	0.62	0.67	0.66
Denominator	2.64	2.75	2.88	3.04	2.98	2.98	2.82	2.82	2.78	2.82	2.54	2.21	1.78	1.64
RSRM Liner Thickness	3.174	3.247	3.314	3.280	3.183	3.183	3.397	3.517	3.626	3.710	3.586	3.231	2.583	2.110
Margin of Safety	0.20	0.18	0.15	0.08	0.07	0.07	0.31	0.25	0.30	0.31	0.46	0.46	0.45	0.29

Minimum margin of safety is 0.04 at station 8.00 degree 0.00  
Maximum margin of safety is 0.46 at station 20.00 degree 270.00

\* Measured char adjusted to end of action time

Margin of Safety =  $\frac{\text{minimum liner thickness}}{2.00 \times \text{erosion} + 1.25 \times \text{adj char}}$  - 1

# Thiokol CORPORATION

## SPACE OPERATIONS

RSRM-32B Throat Assembly Erosion and Char Data

Angular Location	Stations													
	0 degrees	1.0	2.0	4.0	6.0	8.0	10.0	12.0	14.0	16.0	18.0	20.0	22.0	23.0
Measured Erosion		1.10	1.10	1.16	1.21	1.19	1.18	1.13	1.12	1.04	0.93	0.73	0.52	0.41
Measured Char		0.64	0.66	0.57	0.55	0.58	0.54	0.55	0.56	0.63	0.64	0.76	0.75	0.78
Adjusted Char *		0.48	0.50	0.43	0.41	0.43	0.41	0.41	0.42	0.47	0.51	0.61	0.60	0.62
Denominator		2.80	2.82	2.85	2.94	2.92	2.87	2.78	2.77	2.67	2.50	2.22	1.79	1.60
RSRM Liner Thickness		3.174	3.247	3.314	3.280	3.183	3.397	3.517	3.626	3.710	3.586	3.231	2.583	2.110
Margin of Safety		0.13	0.15	0.16	0.12	0.09	0.19	0.27	0.31	0.39	0.43	0.46	0.44	0.32
90 degrees														
Measured Erosion		1.11	1.15	1.18	1.23	1.25	1.23	1.19	1.17	1.10	0.95	0.74	0.50	0.40
Measured Char		0.62	0.66	0.67	0.66	0.61	0.65	0.58	0.63	0.58	0.71	0.80	0.83	0.85
Adjusted Char *		0.47	0.50	0.50	0.50	0.46	0.49	0.43	0.47	0.43	0.57	0.64	0.66	0.68
Denominator		2.80	2.92	2.99	3.08	3.07	3.07	2.92	2.93	2.74	2.61	2.28	1.83	1.65
RSRM Liner Thickness		3.174	3.247	3.314	3.280	3.183	3.397	3.517	3.626	3.710	3.586	3.231	2.583	2.110
Margin of Safety		0.13	0.11	0.11	0.07	0.04	0.11	0.20	0.24	0.35	0.37	0.42	0.41	0.28
180 degrees														
Measured Erosion		1.05	1.07	1.14	1.20	1.23	1.16	1.15	1.12	1.15	0.93	0.75	0.49	0.41
Measured Char		0.64	0.70	0.59	0.63	0.63	0.58	0.58	0.59	0.63	0.71	0.78	0.81	0.79
Adjusted Char *		0.48	0.53	0.44	0.47	0.47	0.43	0.43	0.44	0.47	0.57	0.62	0.65	0.63
Denominator		2.70	2.80	2.83	2.99	3.05	2.86	2.84	2.79	2.89	2.57	2.28	1.79	1.61
RSRM Liner Thickness		3.174	3.247	3.314	3.280	3.183	3.397	3.517	3.626	3.710	3.586	3.231	2.583	2.110
Margin of Safety		0.18	0.16	0.17	0.10	0.04	0.19	0.24	0.30	0.28	0.40	0.42	0.44	0.31
270 degrees														
Measured Erosion		1.07	1.11	1.16	1.21	1.21	1.22	1.18	1.17	1.09	0.93	0.73	0.55	0.46
Measured Char		0.68	0.65	0.68	0.67	0.57	0.56	0.58	0.59	0.65	0.75	0.81	0.77	0.81
Adjusted Char *		0.51	0.49	0.51	0.50	0.43	0.42	0.43	0.44	0.49	0.60	0.65	0.62	0.65
Denominator		2.78	2.83	2.96	3.05	2.95	2.96	2.90	2.89	2.79	2.61	2.27	1.87	1.73
RSRM Liner Thickness		3.174	3.247	3.314	3.280	3.183	3.397	3.517	3.626	3.710	3.586	3.231	2.583	2.110
Margin of Safety		0.14	0.15	0.12	0.08	0.08	0.15	0.21	0.25	0.33	0.37	0.42	0.38	0.22

Minimum margin of safety is 0.04 at station 8.00 degree 90.00  
Maximum margin of safety is 0.46 at station 20.00 degree 0.00

\* Measured char adjusted to end of action time

Margin of Safety =  $\frac{\text{minimum liner thickness}}{2.00 \times \text{erosion} + 1.25 \times \text{adj char}}$  - 1

# Thiokol CORPORATION

## SPACE OPERATIONS

RSRM-32A Nose Inlet Assembly Erosion and Char Data

Angular Location	Stations													
0 degrees	1.5	4.0	6.0	8.0	10.0	12.0	14.0	16.0	18.0	20.0	22.0	24.0	26.0	
Measured Erosion	0.29	0.40	0.41	0.49	0.56	0.58	0.70	0.78	0.94	1.15	1.79	1.94	1.40	
Measured Char *	0.50	0.48	0.53	0.51	0.47	0.51	0.44	0.46	0.44	0.51	0.63	0.70	0.70	
Adjusted Char *	0.40	0.38	0.42	0.41	0.38	0.41	0.35	0.37	0.35	0.41	0.50	0.56	0.53	
Denominator	1.08	1.28	1.35	1.49	1.59	1.67	1.84	2.02	2.32	2.81	4.21	4.58	3.46	
RSRM Liner Thickness	1.776	2.038	2.248	2.458	2.668	2.878	3.088	3.298	3.507	4.055	4.713	4.691	3.863	
Margin of Safety	0.64	0.59	0.67	0.65	0.68	0.72	0.68	0.63	0.51	0.44	0.12	0.02	0.12	
90 degrees														
Measured Erosion	NA	0.40	0.42	0.44	0.50	0.48	0.65	0.69	0.81	1.05	1.69	1.79	1.27	
Measured Char *	NA	0.43	0.48	0.49	0.48	0.49	0.51	0.43	0.38	0.39	0.55	0.71	0.76	
Adjusted Char *	NA	0.34	0.38	0.39	0.38	0.39	0.41	0.34	0.30	0.31	0.44	0.57	0.57	
Denominator	NA	1.23	1.32	1.37	1.48	1.45	1.81	1.81	2.00	2.49	3.93	4.29	3.25	
RSRM Liner Thickness	1.776	2.038	2.248	2.458	2.668	2.878	3.088	3.298	3.507	4.055	4.713	4.691	3.863	
Margin of Safety	NA	0.66	0.70	0.79	0.80	0.98	0.71	0.82	0.75	0.63	0.20	0.09	0.19	
180 degrees														
Measured Erosion	NA	0.32	0.33	0.44	0.45	0.45	0.58	0.61	0.76	0.93	1.57	1.76	1.30	
Measured Char *	NA	0.51	0.53	0.39	0.45	0.49	0.42	0.46	0.41	0.47	0.63	0.78	0.77	
Adjusted Char *	NA	0.41	0.42	0.31	0.36	0.39	0.34	0.37	0.33	0.38	0.50	0.62	0.58	
Denominator	NA	1.15	1.19	1.27	1.35	1.39	1.58	1.68	1.93	2.33	3.77	4.30	3.32	
RSRM Liner Thickness	1.776	2.038	2.248	2.458	2.668	2.878	3.088	3.298	3.507	4.055	4.713	4.691	3.863	
Margin of Safety	NA	0.77	0.89	0.94	0.98	1.07	0.95	0.96	0.82	0.74	0.25	0.09	0.16	
270 degrees														
Measured Erosion	NA	0.33	0.37	0.43	0.49	0.49	0.59	0.62	0.71	0.95	1.49	1.85	1.45	
Measured Char *	NA	0.56	0.47	0.49	0.50	0.50	0.48	0.45	0.47	0.47	0.88	0.89	0.79	
Adjusted Char *	NA	0.45	0.38	0.39	0.40	0.40	0.38	0.36	0.38	0.38	0.70	0.71	0.59	
Denominator	NA	1.22	1.21	1.35	1.48	1.48	1.66	1.69	1.89	2.37	3.86	4.59	3.64	
RSRM Liner Thickness	1.776	2.038	2.248	2.458	2.668	2.878	3.088	3.298	3.507	4.055	4.713	4.691	3.863	
Margin of Safety	NA	0.67	0.86	0.82	0.80	0.94	0.86	0.95	0.86	0.71	0.22	0.02	0.06	

Minimum margin of safety is 0.02 at station 24.00 degree 270.00  
Maximum margin of safety is 1.07 at station 12.00 degree 180.00

\* Measured char adjusted to end of action time

Margin of Safety =  $\frac{\text{minimum liner thickness}}{2.00 \times \text{erosion} + 1.25 \times \text{adj char}}$  - 1

**Thiokol CORPORATION**  
SPACE OPERATIONS

RSRM-32A Nose Inlet Assembly Erosion and Char Data  
Forward Nose Ring and Aft Inlet Ring

Angular Location	Stations							
	0	28.0	30.0	32.0	34.0	36.0	38.0	39.0
0 degrees								
Measured Erosion		1.22	0.93	0.93	0.88	0.90	0.96	0.99
Measured Char *		0.66	0.60	0.64	0.61	0.60	0.53	0.56
Adjusted Char *		0.50	0.45	0.48	0.46	0.45	0.42	0.42
Denominator		3.06	2.42	2.46	2.33	2.36	2.42	2.50
RSRM Liner Thickness		3.508	3.252	2.950	3.182	3.200	3.026	3.000
Margin of Safety		0.15	0.34	0.20	0.36	0.35	0.25	0.20
90 degrees								
Measured Erosion		1.10	0.87	0.90	0.83	0.86	0.94	0.94
Measured Char *		0.58	0.67	0.59	0.60	0.59	0.64	0.56
Adjusted Char *		0.43	0.50	0.44	0.45	0.44	0.48	0.42
Denominator		2.74	2.37	2.35	2.22	2.27	2.48	2.40
RSRM Liner Thickness		3.508	3.252	2.950	3.182	3.200	3.026	3.000
Margin of Safety		0.28	0.37	0.25	0.43	0.41	0.22	0.25
180 degrees								
Measured Erosion	NA		0.82	0.92	0.90	0.92	0.98	1.00
Measured Char *	NA		0.66	0.55	0.53	0.55	0.56	0.61
Adjusted Char *	NA		0.50	0.41	0.40	0.41	0.42	0.46
Denominator	NA		2.26	2.36	2.30	2.36	2.48	2.57
RSRM Liner Thickness	3.508		3.252	2.950	3.182	3.200	3.026	3.000
Margin of Safety	NA		0.44	0.25	0.39	0.36	0.22	0.17
270 degrees								
Measured Erosion		1.15	0.93	1.01	0.87	0.91	0.98	1.01
Measured Char *		0.67	0.64	0.66	0.63	0.67	0.72	0.70
Adjusted Char *		0.50	0.48	0.50	0.47	0.50	0.54	0.53
Denominator		2.93	2.46	2.64	2.33	2.45	2.64	2.68
RSRM Liner Thickness		3.508	3.252	2.950	3.182	3.200	3.026	3.000
Margin of Safety		0.20	0.32	0.12	0.37	0.31	0.15	0.12

\* Measured char adjusted to end of action time

Margin of Safety =  $\frac{\text{minimum liner thickness}}{2.00 \times \text{erosion} + 1.25 \times \text{adj char}}$  - 1

# Thiokol CORPORATION

## SPACE OPERATIONS

RSRM-32B Nose Inlet Assembly Erosion and Char Data

Angular Location	Stations													
	0 degrees	1.5	4.0	6.0	8.0	10.0	12.0	14.0	16.0	18.0	20.0	22.0	24.0	26.0
Measured Erosion	NA	0.37	0.41	0.37	0.41	0.49	0.51	0.59	0.71	0.80	1.02	1.61	1.89	1.45
Measured Char	NA	0.47	0.44	0.44	0.46	0.41	0.45	0.48	0.37	0.49	0.64	0.78	0.85	0.73
Adjusted Char	NA	0.38	0.33	0.35	0.33	0.33	0.36	0.38	0.30	0.39	0.51	0.62	0.68	0.55
Denominator	NA	1.21	1.18	1.18	1.28	1.39	1.47	1.66	1.79	2.09	2.68	4.00	4.63	3.58
RSRM Liner Thickness	1.776	2.038	2.248	2.248	2.458	2.668	2.878	3.088	3.298	3.507	4.055	4.713	4.691	3.863
Margin of Safety	NA	0.68	0.91	0.92	0.92	0.92	0.96	0.86	0.84	0.68	0.51	0.18	0.01	0.08
90 degrees														
Measured Erosion	0.32	0.33	0.33	0.33	0.39	0.45	0.48	0.60	0.66	0.79	0.97	1.64	1.80	1.34
Measured Char	0.51	0.51	0.51	0.51	0.49	0.45	0.44	0.44	0.46	0.45	0.55	0.69	0.76	0.75
Adjusted Char	0.41	0.41	0.41	0.41	0.39	0.36	0.35	0.35	0.37	0.36	0.44	0.55	0.61	0.56
Denominator	1.15	1.17	1.17	1.17	1.27	1.35	1.40	1.64	1.78	2.03	2.49	3.97	4.36	3.38
RSRM Liner Thickness	1.776	2.038	2.248	2.248	2.458	2.668	2.878	3.088	3.298	3.507	4.055	4.713	4.691	3.863
Margin of Safety	0.54	0.74	0.92	0.92	0.94	0.98	1.06	0.88	0.85	0.73	0.63	0.19	0.08	0.14
180 degrees														
Measured Erosion	NA	0.47	0.38	0.38	0.41	0.48	0.57	0.61	0.73	0.94	1.15	1.73	1.90	1.41
Measured Char	NA	0.42	0.46	0.46	0.41	0.37	0.39	0.43	0.41	0.42	0.55	0.73	0.84	0.74
Adjusted Char	NA	0.34	0.37	0.37	0.33	0.30	0.31	0.34	0.33	0.34	0.44	0.58	0.67	0.56
Denominator	NA	1.36	1.22	1.22	1.23	1.33	1.53	1.65	1.87	2.30	2.85	4.19	4.64	3.51
RSRM Liner Thickness	1.776	2.038	2.248	2.248	2.458	2.668	2.878	3.088	3.298	3.507	4.055	4.713	4.691	3.863
Margin of Safety	NA	0.50	0.84	0.84	1.00	1.01	0.88	0.87	0.76	0.52	0.42	0.12	0.01	0.10
270 degrees														
Measured Erosion	NA	0.29	0.33	0.33	0.41	0.47	0.54	0.64	0.66	0.75	0.95	1.52	1.80	1.39
Measured Char	NA	0.53	0.52	0.52	0.55	0.48	0.45	0.46	0.44	0.49	0.58	0.81	0.85	0.84
Adjusted Char	NA	0.42	0.42	0.42	0.44	0.38	0.36	0.37	0.35	0.39	0.46	0.65	0.68	0.63
Denominator	NA	1.11	1.18	1.18	1.37	1.42	1.53	1.74	1.76	1.99	2.48	3.85	4.45	3.57
RSRM Liner Thickness	1.776	2.038	2.248	2.248	2.458	2.668	2.878	3.088	3.298	3.507	4.055	4.713	4.691	3.863
Margin of Safety	NA	0.84	0.91	0.91	0.79	0.88	0.88	0.77	0.67	0.76	0.64	0.22	0.05	0.08

Minimum margin of safety is 0.01 at station 24.00 degree 180.00  
Maximum margin of safety is 1.06 at station 12.00 degree 90.00

\* Measured char adjusted to end of action time

Margin of Safety =  $\frac{\text{minimum liner thickness}}{2.00 \times \text{erosion} + 1.25 \times \text{adj char}}$  - 1

RSRM-32B Nose Inlet Assembly Erosion and Char Data  
Forward Nose Ring and Aft Inlet Ring

Angular Location	Stations							
	0 degrees	28.0	30.0	32.0	34.0	36.0	38.0	39.0
Measured Erosion		1.07	0.90	0.95	0.84	0.86	0.92	0.96
Measured Char *		0.73	0.64	0.60	0.66	0.64	0.61	0.63
Adjusted Char *		0.55	0.48	0.45	0.50	0.48	0.46	0.47
Denominator		2.82	2.40	2.46	2.30	2.32	2.41	2.51
RSRM Liner Thickness		3.508	3.252	2.950	3.182	3.200	3.026	3.000
Margin of Safety		0.24	0.35	0.20	0.38	0.38	0.25	0.19
90 degrees								
Measured Erosion		1.04	0.80	0.90	0.85	0.87	0.94	0.98
Measured Char *		0.66	0.78	0.65	0.65	0.71	0.67	0.67
Adjusted Char *		0.50	0.59	0.49	0.49	0.53	0.50	0.50
Denominator		2.70	2.33	2.41	2.31	2.41	2.51	2.59
RSRM Liner Thickness		3.508	3.252	2.950	3.182	3.200	3.026	3.000
Margin of Safety		0.30	0.39	0.22	0.38	0.33	0.21	0.16
180 degrees								
Measured Erosion		1.22	0.95	0.98	0.90	0.89	0.98	1.00
Measured Char *		0.66	0.69	0.59	0.60	0.63	0.56	0.64
Adjusted Char *		0.50	0.52	0.44	0.45	0.47	0.42	0.48
Denominator		3.06	2.55	2.51	2.36	2.37	2.48	2.60
RSRM Liner Thickness		3.508	3.252	2.950	3.182	3.200	3.026	3.000
Margin of Safety		0.15	0.28	0.17	0.35	0.35	0.22	0.15
270 degrees								
Measured Erosion		1.11	0.90	0.96	0.88	0.89	0.95	0.97
Measured Char *		0.66	0.65	0.56	0.53	0.63	0.65	0.67
Adjusted Char *		0.50	0.49	0.42	0.40	0.47	0.49	0.50
Denominator		2.84	2.41	2.44	2.26	2.37	2.51	2.57
RSRM Liner Thickness		3.508	3.252	2.950	3.182	3.200	3.026	3.000
Margin of Safety		0.24	0.35	0.21	0.41	0.35	0.21	0.17

\* Measured char adjusted to end of action time

$$\text{Margin of Safety} = \frac{\text{minimum liner thickness}}{2.00 \times \text{erosion} + 1.25 \times \text{adj char}} - 1$$

RSRM-32A Cowl, Outer Boot Ring Assembly Erosion and Char Data

Angular Location	Stations													
	0	degrees	0.3	1.0	2.0	3.0	4.0	5.0	6.0	6.8	8.0	9.0	10.0	11.3
Measured Erosion	0.30		0.29	0.27	0.25	0.22	0.19	0.18	0.15	0.15	0.10	0.10	0.08	0.07
Measured Char	0.80		0.73	0.69	0.68	0.69	0.68	0.72	0.67	0.87	0.82	0.80	0.79	0.81
Adjusted Char *	0.64		0.58	0.55	0.54	0.55	0.54	0.58	0.54	0.70	0.66	0.64	0.63	0.65
Denominator	1.40		1.31	1.23	1.17	1.10	1.06	1.08	1.03	1.27	1.23	1.11	1.07	1.08
RSRM Liner Thickness	1.438		1.499	1.577	1.655	1.733	1.811	1.889	1.943	1.943	1.600	1.674	1.687	1.703
Margin of Safety	0.03		0.14	0.28	0.41	0.58	0.75	0.84	0.53	0.41	0.28	0.36	0.46	0.41
90 degrees														
Measured Erosion	0.31		0.32	0.25	0.25	0.22	0.19	0.18	0.15	0.15	0.10	0.10	0.08	0.07
Measured Char	0.72		0.66	0.68	0.68	0.69	0.68	0.72	0.67	0.87	0.82	0.80	0.79	0.81
Adjusted Char *	0.58		0.53	0.54	0.55	0.54	0.55	0.58	0.54	0.70	0.66	0.64	0.63	0.65
Denominator	1.34		1.30	1.18	1.13	1.06	1.06	1.08	1.03	1.27	1.23	1.11	1.07	1.08
RSRM Liner Thickness	1.438		1.499	1.577	1.655	1.733	1.811	1.889	1.943	1.943	1.600	1.674	1.687	1.703
Margin of Safety	0.07		0.15	0.34	0.46	0.63	0.84	0.68	0.53	0.41	0.28	0.36	0.46	0.41
180 degrees														
Measured Erosion	0.30		0.27	0.23	0.23	0.20	0.18	0.15	0.14	0.18	0.07	0.03	0.01	0.00
Measured Char	0.71		0.68	0.62	0.62	0.66	0.63	0.69	0.76	0.82	0.95	0.94	0.92	0.90
Adjusted Char *	0.57		0.54	0.50	0.50	0.53	0.50	0.55	0.61	0.66	0.76	0.75	0.74	0.72
Denominator	1.31		1.22	1.08	1.08	1.06	0.99	0.99	1.12	1.25	1.25	1.17	1.12	1.08
RSRM Liner Thickness	1.438		1.499	1.577	1.655	1.733	1.811	1.889	1.943	1.943	1.600	1.674	1.687	1.703
Margin of Safety	0.10		0.23	0.46	0.56	0.75	0.83	0.68	0.55	0.43	0.29	0.43	0.51	0.58
270 degrees														
Measured Erosion	0.28		0.26	0.22	0.22	0.21	0.18	0.16	0.14	0.23	0.14	0.05	0.04	0.05
Measured Char	0.78		0.70	0.67	0.71	0.72	0.72	0.71	0.70	0.82	0.92	1.01	0.94	0.97
Adjusted Char *	0.62		0.56	0.54	0.57	0.58	0.58	0.57	0.56	0.66	0.74	0.81	0.75	0.78
Denominator	1.34		1.22	1.11	1.13	1.08	1.03	1.03	1.05	1.33	1.31	1.29	1.19	1.24
RSRM Liner Thickness	1.438		1.499	1.577	1.655	1.733	1.811	1.889	1.943	1.943	1.600	1.674	1.687	1.703
Margin of Safety	0.07		0.23	0.42	0.46	0.60	0.76	0.80	0.68	0.46	0.22	0.30	0.42	0.37
Minimum margin of safety is 0.03 at station 0.30 degree 0.00														
Maximum margin of safety is 0.84 at station 6.00 degree 90.00														
* Measured char adjusted to end of action time														
Margin of Safety = $\frac{\text{Minimum liner thickness}}{1.50 \times \text{erosion} + 1.50 \times \text{adj char}} - 1$														



# Thiokol CORPORATION

## SPACE OPERATIONS

RSRM-328 Cowl, Outer Boot Ring Assembly Erosion and Char Data

Angular Location	Stations										
	0	1.0	2.0	3.0	4.0	5.0	6.0	6.8	8.0	9.0	10.0
0 degrees											11.3
Measured Erosion	0.29	0.30	0.29	0.25	0.24	0.19	0.17	0.20	0.06	0.04	0.01
Measured Char	0.73	0.64	0.60	0.65	0.68	0.73	0.69	0.91	1.02	1.01	1.01
Adjusted Char *	0.58	0.51	0.48	0.52	0.54	0.58	0.55	0.73	0.82	0.81	0.81
Denominator	1.31	1.24	1.18	1.15	1.16	1.11	1.08	1.39	1.31	1.27	1.25
RSRM Liner Thickness	1.438	1.499	1.577	1.655	1.733	1.811	1.889	1.943	1.600	1.674	1.703
Margin of Safety	0.10	0.21	0.34	0.44	0.49	0.63	0.74	0.40	0.22	0.32	0.35
90 degrees											
Measured Erosion	0.28	0.27	0.24	0.21	0.20	0.18	0.16	0.16	0.05	0.02	0.03
Measured Char	0.80	0.75	0.65	0.67	0.71	0.77	0.71	0.84	0.93	0.90	0.87
Adjusted Char *	0.64	0.60	0.52	0.54	0.57	0.62	0.57	0.67	0.74	0.72	0.70
Denominator	1.36	1.29	1.13	1.09	1.11	1.13	1.09	1.25	1.19	1.11	1.09
RSRM Liner Thickness	1.438	1.499	1.577	1.655	1.733	1.811	1.889	1.943	1.600	1.674	1.703
Margin of Safety	0.06	0.16	0.40	0.52	0.56	0.60	0.73	0.56	0.34	0.51	0.55
180 degrees											
Measured Erosion	NA	0.30	0.30	0.24	0.21	0.18	0.15	NA	0.08	0.05	0.01
Measured Char	NA	0.73	0.72	0.71	0.74	0.73	0.72	NA	0.91	0.87	0.87
Adjusted Char *	NA	0.58	0.56	0.57	0.59	0.58	0.58	NA	0.73	0.70	0.70
Denominator	NA	1.33	1.32	1.19	1.16	1.09	1.09	NA	1.21	1.12	1.06
RSRM Liner Thickness	1.438	1.499	1.577	1.655	1.733	1.811	1.889	1.943	1.600	1.674	1.703
Margin of Safety	NA	0.13	0.19	0.39	0.49	0.66	0.73	NA	0.32	0.50	0.54
270 degrees											
Measured Erosion	0.24	0.23	0.24	0.21	0.20	0.17	0.15	0.12	NA	0.04	0.04
Measured Char	0.73	0.71	0.72	0.76	0.75	0.77	0.80	0.84	NA	0.86	0.92
Adjusted Char *	0.58	0.57	0.58	0.61	0.60	0.62	0.64	0.67	NA	0.69	0.74
Denominator	1.21	1.17	1.20	1.18	1.15	1.11	1.19	1.19	NA	1.09	1.12
RSRM Liner Thickness	1.438	1.499	1.577	1.655	1.733	1.811	1.889	1.943	1.600	1.674	1.703
Margin of Safety	0.19	0.28	0.31	0.40	0.51	0.63	0.59	0.64	NA	0.53	0.46

Minimum margin of safety is 0.06 at station 0.30 degree 90.00  
Maximum margin of safety is 0.74 at station 6.00 degree 0.00

\* Measured char adjusted to end of action time

Margin of Safety =  $\frac{\text{minimum liner thickness}}{1.50 \times \text{erosion} + 1.50 \times \text{adj char}}$  - 1

RSRM-32A Fixed Housing Assembly Erosion and Char Data

Angular Location	Stations												
	0	degrees	0.00	1.00	2.00	3.00	4.00	5.00	6.00	7.00	8.00	9.00	10.75
Measured Erosion	0.08	0.04	0.00	0.03	0.03	0.03	0.01	0.01	0.01	0.01	0.00	0.00	0.02
Adjusted Char *	1.20	1.13	1.07	0.97	0.97	0.97	0.93	0.91	0.95	0.92	0.92	0.93	1.84
Denominator	0.96	0.90	0.86	0.78	0.80	0.80	0.81	0.80	0.83	0.82	0.74	0.74	1.47
RSRM Liner Thickness	1.36	1.21	1.07	1.03	1.07	1.07	1.07	1.02	1.06	1.04	0.92	0.93	1.88
Margin of Safety	3.807	2.081	1.825	1.827	1.829	1.829	1.831	1.831	1.832	1.834	1.836	2.426	3.048
90 degrees	1.80	0.72	0.71	0.77	0.71	0.77	0.71	0.80	0.73	0.76	1.00	1.61	0.62
Measured Erosion	0.05	0.06	0.01	0.01	0.01	0.01	0.01	0.01	0.00	0.00	0.00	NA	NA
Adjusted Char *	1.12	1.06	0.96	0.97	0.93	0.93	0.93	0.91	0.95	0.92	0.78	NA	NA
Denominator	0.90	0.85	0.77	0.78	0.74	0.74	0.74	0.73	0.76	0.74	0.62	NA	NA
RSRM Liner Thickness	1.22	1.18	0.98	0.99	0.98	0.99	0.95	0.93	0.93	0.92	0.78	NA	NA
Margin of Safety	3.807	2.081	1.825	1.827	1.829	1.829	1.831	1.831	1.832	1.834	1.836	2.426	3.048
180 degrees	2.12	0.76	0.86	0.85	0.93	0.85	0.93	0.97	0.93	0.99	1.35	NA	NA
Measured Erosion	0.04	0.02	0.02	0.00	0.01	0.00	0.01	0.00	0.00	0.01	0.00	0.00	0.15
Adjusted Char *	1.13	1.03	1.10	1.13	1.07	1.04	1.07	1.04	1.04	0.99	0.86	0.83	1.45
Denominator	0.90	0.82	0.88	0.90	0.86	0.83	0.86	0.83	0.83	0.79	0.69	0.66	1.16
RSRM Liner Thickness	1.21	1.07	1.14	1.13	1.09	1.04	1.04	1.04	1.04	1.01	0.86	0.83	1.75
Margin of Safety	3.807	2.081	1.825	1.827	1.829	1.831	1.829	1.831	1.832	1.834	1.836	2.426	3.048
270 degrees	2.15	0.94	0.60	0.62	0.68	0.62	0.68	0.76	0.76	0.82	1.13	1.92	0.74
Measured Erosion	0.00	0.01	0.04	0.03	0.04	0.03	0.04	0.03	0.05	0.00	0.00	0.00	0.00
Adjusted Char *	1.21	1.08	1.00	1.05	1.02	1.01	1.02	1.01	1.00	0.96	0.93	0.78	1.73
Denominator	0.97	0.86	0.80	0.84	0.82	0.81	0.82	0.81	0.80	0.77	0.74	0.62	1.38
RSRM Liner Thickness	1.21	1.10	1.08	1.11	1.10	1.07	1.10	1.07	1.10	0.96	0.93	0.78	1.73
Margin of Safety	3.807	2.081	1.825	1.827	1.829	1.831	1.829	1.831	1.832	1.834	1.836	2.426	3.048
270 degrees	2.15	0.89	0.69	0.65	0.66	0.65	0.66	0.71	0.67	0.91	0.97	2.11	0.76

Minimum margin of safety is 0.60 at station 2.00 degree 180.00  
Maximum margin of safety is 2.15 at station 0.00 degree 180.00

\* Measured char adjusted to end of action time

Margin of Safety =  $\frac{\text{Minimum liner thickness}}{2.00 \times \text{erosion} + 1.25 \times \text{adj char}}$  - 1

RSRM-32B Fixed Housing Assembly Erosion and Char Data

Angular Location	Stations									
	0	1.00	2.00	3.00	4.00	5.00	6.00	7.00	8.00	9.00 10.75
0 degrees										
Measured Erosion	0.03	0.02	0.01	0.03	NA	0.00	0.00	0.00	0.00	0.44
Measured Char	1.05	1.09	1.05	1.07	NA	1.07	1.05	1.00	0.92	NA
Adjusted Char	0.84	0.87	0.84	0.86	NA	0.86	0.84	0.80	0.74	NA
Denominator	1.11	1.13	1.07	1.13	NA	1.07	1.05	1.00	0.92	NA
RSRM Liner Thickness	3.807	2.081	1.825	1.827	1.829	1.831	1.832	1.834	1.836	2.426
Margin of Safety	2.43	0.84	0.71	0.62	NA	0.71	0.74	0.83	1.00	0.55
90 degrees										
Measured Erosion	0.06	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.15
Measured Char	0.95	0.90	1.00	0.91	0.88	0.84	0.87	0.85	0.84	0.72
Adjusted Char	0.76	0.72	0.80	0.76	0.70	0.67	0.70	0.68	0.67	0.58
Denominator	1.07	0.90	1.00	0.91	0.88	0.84	0.87	0.85	0.84	0.72
RSRM Liner Thickness	3.807	2.081	1.825	1.827	1.829	1.831	1.832	1.834	1.836	2.426
Margin of Safety	2.56	1.31	0.82	1.01	1.08	1.10	1.11	1.16	1.19	0.58
180 degrees										
Measured Erosion	0.03	0.02	0.00	0.03	0.00	0.00	0.00	0.00	0.00	NA
Measured Char	1.05	0.94	0.87	0.86	0.88	0.87	0.87	0.84	0.73	NA
Adjusted Char	0.84	0.75	0.70	0.69	0.70	0.70	0.70	0.67	0.58	NA
Denominator	1.11	0.98	0.87	0.92	0.88	0.87	0.87	0.84	0.73	NA
RSRM Liner Thickness	3.807	2.081	1.825	1.827	1.829	1.831	1.832	1.834	1.836	2.426
Margin of Safety	2.43	1.12	1.10	0.99	1.08	1.10	1.11	1.16	1.52	NA
270 degrees										
Measured Erosion	0.02	0.01	0.00	0.00	0.00	0.00	0.00	0.00	0.00	NA
Measured Char	1.03	1.04	1.08	1.05	1.03	0.98	1.00	0.98	0.82	NA
Adjusted Char	0.82	0.83	0.86	0.84	0.82	0.78	0.80	0.78	0.66	NA
Denominator	1.07	1.06	1.08	1.05	1.03	0.98	1.00	0.98	0.82	NA
RSRM Liner Thickness	3.807	2.081	1.825	1.827	1.829	1.831	1.832	1.834	1.836	2.426
Margin of Safety	2.56	0.96	0.69	0.74	0.78	0.87	0.83	0.87	1.24	NA

Minimum margin of safety is 0.55 at station 10.75 degree 0.00  
Maximum margin of safety is 2.56 at station 0.00 degree 90.00

\* Measured char adjusted to end of action time

Margin of Safety =  $\frac{\text{minimum liner thickness}}{2.00 \times \text{erosion} + 1.25 \times \text{adj char}}$  - 1

**Thiokol CORPORATION**  
SPACE OPERATIONS

RSRM-32B Aft Exit Cone Assembly Erosion and Char Data

Angular Location	Stations										
	1.00	6.00	18.00	30.00	42.00	54.00	64.00	73.77	77.77	83.77	89.77
0 degrees											
Measured Erosion	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Measured Char	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Adjusted Char	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Denominator	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
RSRM Liner Thickness	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Margin of Safety	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
15 degrees											
Measured Erosion	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Measured Char	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Adjusted Char	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Denominator	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
RSRM Liner Thickness	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Margin of Safety	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
30 degrees											
Measured Erosion	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Measured Char	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Adjusted Char	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Denominator	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
RSRM Liner Thickness	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Margin of Safety	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
60 degrees											
Measured Erosion	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Measured Char	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Adjusted Char	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Denominator	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
RSRM Liner Thickness	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Margin of Safety	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
90 degrees											
Measured Erosion	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Measured Char	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Adjusted Char	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Denominator	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
RSRM Liner Thickness	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Margin of Safety	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
165 degrees											
Measured Erosion	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Measured Char	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Adjusted Char	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Denominator	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
RSRM Liner Thickness	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Margin of Safety	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA

RSRM-32B Aft Exit Cone Assembly Erosion and Char Data

Stations

Angular Location

0 degrees 107.77 113.77 118.77

Measured Erosion NA NA NA  
Measured Char NA NA NA  
Adjusted Char NA NA NA  
Denominator NA NA NA  
RSRM Liner Thickness 1.131 1.160 NA  
Margin of Safety NA NA NA

15 degrees

Measured Erosion 0.27 NA NA  
Measured Char 0.54 NA NA  
Adjusted Char 0.46 NA NA  
Denominator 1.03 NA NA  
RSRM Liner Thickness 1.131 1.160 NA  
Margin of Safety 0.10 NA NA

30 degrees

Measured Erosion NA 0.19 NA  
Measured Char NA 0.51 NA  
Adjusted Char NA 0.43 NA  
Denominator NA 0.86 NA  
RSRM Liner Thickness 1.131 1.160 NA  
Margin of Safety NA 0.34 NA

60 degrees

Measured Erosion 0.11 NA NA  
Measured Char 0.59 NA NA  
Adjusted Char 0.50 NA NA  
Denominator 0.81 NA NA  
RSRM Liner Thickness 1.131 1.160 NA  
Margin of Safety 0.39 NA NA

90 degrees

Measured Erosion 0.17 NA NA  
Measured Char 0.58 NA NA  
Adjusted Char 0.49 NA NA  
Denominator 0.91 NA NA  
RSRM Liner Thickness 1.131 1.160 NA  
Margin of Safety 0.25 NA NA

165 degrees

Measured Erosion 0.12 NA NA  
Measured Char 0.60 NA NA  
Adjusted Char 0.51 NA NA  
Denominator 0.84 NA NA  
RSRM Liner Thickness 1.131 1.160 NA  
Margin of Safety 0.34 NA NA

# Thiokol CORPORATION

## SPACE OPERATIONS

RSRM-32B Aft Exit Cone Assembly Erosion and Char Data

Angular Location	Stations															
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
195 degrees																
Measured Erosion	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Measured Char	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Adjusted Char	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Denominator	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
RSRM Liner Thickness	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	1.095
Margin of Safety	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
210 degrees																
Measured Erosion	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Measured Char	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Adjusted Char	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Denominator	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
RSRM Liner Thickness	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	1.095
Margin of Safety	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
255 degrees																
Measured Erosion	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Measured Char	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Adjusted Char	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Denominator	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
RSRM Liner Thickness	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	1.095
Margin of Safety	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
270 degrees																
Measured Erosion	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Measured Char	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Adjusted Char	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Denominator	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
RSRM Liner Thickness	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	1.095
Margin of Safety	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
285 degrees																
Measured Erosion	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	0.19
Measured Char	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	0.59
Adjusted Char	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	0.50
Denominator	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	0.95
RSRM Liner Thickness	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	1.095
Margin of Safety	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	0.15
300 degrees																
Measured Erosion	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	0.18
Measured Char	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	0.57
Adjusted Char	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	0.48
Denominator	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	0.91
RSRM Liner Thickness	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	1.095
Margin of Safety	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	0.20

RSRM-32B Aft Exit Cone Assembly Erosion and Char Data

Stations

Angular Location

195 degrees

Measured Erosion	0.17	NA	NA
Measured Char	0.63	NA	NA
Adjusted Char	0.54	NA	NA
Denominator	0.96	NA	NA
RSRM Liner Thickness	1.131	1.160	NA
Margin of Safety	0.18	NA	NA

210 degrees

Measured Erosion	0.18	NA	NA
Measured Char	0.56	NA	NA
Adjusted Char	0.48	NA	NA
Denominator	0.90	NA	NA
RSRM Liner Thickness	1.131	1.160	NA
Margin of Safety	0.26	NA	NA

255 degrees

Measured Erosion	0.34	0.16	NA
Measured Char	0.49	0.55	NA
Adjusted Char	0.42	0.47	NA
Denominator	1.10	0.86	NA
RSRM Liner Thickness	1.131	1.160	NA
Margin of Safety	0.03	0.35	NA

270 degrees

Measured Erosion	0.21	NA	NA
Measured Char	0.58	NA	NA
Adjusted Char	0.49	NA	NA
Denominator	0.97	NA	NA
RSRM Liner Thickness	1.131	1.160	NA
Margin of Safety	0.16	NA	NA

285 degrees

Measured Erosion	NA	0.18	NA
Measured Char	NA	0.57	NA
Adjusted Char	NA	0.48	NA
Denominator	NA	0.91	NA
RSRM Liner Thickness	1.131	1.160	NA
Margin of Safety	NA	0.27	NA

300 degrees

Measured Erosion	0.20	0.21	NA
Measured Char	0.51	0.53	NA
Adjusted Char	0.43	0.45	NA
Denominator	0.88	0.92	NA
RSRM Liner Thickness	1.131	1.160	NA
Margin of Safety	0.28	0.26	NA

RSRM-32B Aft Exit Cone Assembly Erosion and Char Data

Angular Location	Stations									
	330 degrees	335 degrees	340 degrees	345 degrees	350 degrees	355 degrees	360 degrees	365 degrees	370 degrees	375 degrees
Measured Erosion	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Measured Char *	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Adjusted Char *	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Denominator	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
RSRM Liner Thickness	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Margin of Safety	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
345 degrees										
Measured Erosion	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Measured Char *	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Adjusted Char *	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Denominator	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
RSRM Liner Thickness	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Margin of Safety	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA

Minimum margin of safety is 0.03 at station 107.77 degree 255.00  
Maximum margin of safety is 0.45 at station 107.77 degree 345.00

\* Measured char adjusted to end of action time

Margin of Safety =  $\frac{\text{minimum liner thickness}}{1.70 \times \text{erosion} + 1.25 \times \text{adj char}}$  - 1




RSRM-32B Att Exit Cone Assembly Erosion and Char Data

Angular Location	Stations			
330 degrees				
Measured Erosion	NA	NA	NA	NA
Measured Char	NA	NA	NA	NA
Adjusted Char *	NA	NA	NA	NA
Denominator	NA	NA	NA	NA
RSRM Liner Thickness	1.131	1.160	NA	NA
Margin of Safety	NA	NA	NA	NA
345 degrees				
Measured Erosion	0.07	NA	NA	NA
Measured Char	0.62	NA	NA	NA
Adjusted Char *	0.53	NA	NA	NA
Denominator	0.78	NA	NA	NA
RSRM Liner Thickness	1.131	1.160	NA	NA
Margin of Safety	0.45	NA	NA	NA

\* Measured char adjusted to end of action time

$$\text{Margin of Safety} = \frac{\text{minimum liner thickness}}{1.70 \times \text{erosion} + 1.25 \times \text{adj char}} - 1$$

0-3



## **Appendix C Insulation Postfire Data**

# **Final Postflight Hardware Evaluation Report RSRM-32 (STS-57)**

**November 1993**

**Prepared for:**

**NATIONAL AERONAUTICS AND SPACE ADMINISTRATION  
GEORGE C. MARSHALL SPACE FLIGHT CENTER  
MARSHALL SPACE FLIGHT CENTER, ALABAMA 35812**

**Contract No. NAS8-38100**

**DR No. 4-23**

**WBS No. 4C601-04-01**

**ECS No. SS4775**

***Thiokol* CORPORATION**  
**SPACE OPERATIONS**

**P.O. Box 707, Brigham City, Utah 84302-0707 (801) 863-3511**

## Table of Contents

### List of Tables

<u>Table</u>	<u>Description</u>	<u>Page</u>
C-I	LH Igniter Chamber and Adapter Insulation Performance .....	C-2
C-II	RH Igniter Chamber and Adapter Insulation Performance .....	C-5
C-III	LH Forward Center NBR Inhibitor Measurements .....	C-8
C-IV	RH Forward Center NBR Inhibitor Measurements .....	C-8
C-V	LH Aft Center NBR Inhibitor Measurements .....	C-8
C-VI	RH Aft Center NBR Inhibitor Measurements .....	C-8
C-VII	LH Aft NBR Inhibitor Measurements .....	C-9
C-VIII	RH Aft NBR Inhibitor Measurements .....	C-9

RSRM-32A IGNITER CHAMBER AND ADAPTER INSULATION PERFORMANCE

CHAMBER PART NO. 1U75162-02  
CHAMBER SERIAL NO. 0000013  
ADAPTER PART NO. 1U77392-01  
ADAPTER SERIAL NO. 0000020

PREFIRE MEASUREMENTS  
INCHES

STATION (NO.)	0.0	60.0	90.0	150.0	180.0	240.0	270.0	330.0	MEDIAN	MINIMUM
1.0										
2.0										
3.0										
4.0										
5.0										
6.0										
7.0										
8.0										
9.0										
10.0										
11.0	0.540	0.540	0.540	0.540	0.540	0.540	0.540	0.540	0.540	0.540

A BLANK INDICATES NO DATA WAS TAKEN AT THAT STATION

CHAMBER PART NO. N/A  
CHAMBER SERIAL NO. 0000000  
ADAPTER PART NO. 1U77547-01  
ADAPTER SERIAL NO. 0000003

POSTFIRE MEASUREMENTS  
INCHES

STATION (NO.)	0.0	60.0	90.0	150.0	180.0	240.0	270.0	330.0	MEDIAN	MINIMUM
1.0										
2.0										
3.0										
4.0										
5.0										
6.0										
7.0										
8.0										
9.0										
10.0										
11.0	0.405	0.404	0.407	0.392	0.411	0.406	0.406	0.400	0.405	0.392

A BLANK INDICATES NO DATA WAS TAKEN AT THAT STATION

RSRM-32A IGNITER CHAMBER AND ADAPTER INSULATION PERFORMANCE

COMPLIANCE SAFETY FACTORS (CSF)

STATION (NO.)	0.0	60.0	90.0	150.0	180.0	240.0	270.0	330.0	MINIMUM	PLANE
1.0										
2.0										
3.0										
4.0										
5.0										
6.0										
7.0										
8.0										
9.0										
10.0										
11.0	3.35	3.32	3.40	3.05	3.50	3.37	3.37	3.23	3.05	150.0

SF= + INDICATES THAT NEGLIGIBLE MDD OCCURRED

A BLANK INDICATES NO DATA AVAILABLE FOR THAT STATION

ACTUAL SAFETY FACTORS (ASF)

STATION (NO.)	0.0	60.0	90.0	150.0	180.0	240.0	270.0	330.0	MINIMUM	PLANE
1.0										
2.0										
3.0										
4.0										
5.0										
6.0										
7.0										
8.0										
9.0										
10.0										
11.0	4.00	3.97	4.06	3.65	4.19	4.03	4.03	3.86	3.65	150.0

SF= + INDICATES THAT NEGLIGIBLE MDD OCCURRED

A BLANK INDICATES NO DATA AVAILABLE FOR THAT STATION

RSRM-32A IGNITER CHAMBER AND ADAPTER INSULATION PERFORMANCE

STATION (NO.)	MATERIAL DECOMPOSITION DEPTH (MDD) (INCHES)				DEGREE LOCATION					
	0.0	60.0	90.0	150.0	180.0	240.0	270.0	330.0	MEDIAN	MAXIMUM
1.0										
2.0										
3.0										
4.0										
5.0										
6.0										
7.0										
8.0										
9.0										
10.0										
11.0	0.135	0.136	0.133	0.148	0.129	0.134	0.134	0.140	0.135	0.148

A BLANK INDICATES NO DATA AVAILABLE FOR THAT STATION

STATION (NO.)	MATERIAL DECOMPOSITION RATE (MDR) (MILS/SEC)				DEGREE LOCATION				
	0.0	60.0	90.0	150.0	180.0	240.0	270.0	330.0	AVERAGE
1.0									
2.0									
3.0									
4.0									
5.0									
6.0									
7.0									
8.0									
9.0									
10.0									
11.0	1.1	1.1	1.1	1.2	1.1	1.1	1.1	1.1	1.1

MOTOR ACTION (EXPOSURE) TIME = 122.20 SEC

A MDR=0 INDICATES THAT MDR < .1 MIL/SEC

A BLANK INDICATES NO DATA AVAILABLE FOR THAT STATION

RSRM-32B IGNITER CHAMBER AND ADAPTER INSULATION PERFORMANCE

CHAMBER PART NO. 1U75162-02  
CHAMBER SERIAL NO. 0000014  
ADAPTER PART NO. 1U77392-01  
ADAPTER SERIAL NO. 0000021

PREFIRE MEASUREMENTS  
INCHES

STATION (NO.)	0.0	60.0	90.0	150.0	180.0	240.0	270.0	330.0	MEDIAN	MINIMUM
1.0										
2.0										
3.0										
4.0										
5.0										
6.0										
7.0										
8.0										
9.0										
10.0										
11.0	0.540	0.540	0.540	0.540	0.540	0.540	0.540	0.540	0.540	0.540

A BLANK INDICATES NO DATA WAS TAKEN AT THAT STATION

CHAMBER PART NO. N/A  
CHAMBER SERIAL NO. 0000000  
ADAPTER PART NO. 1U77457-01  
ADAPTER SERIAL NO. 0000004

POSTFIRE MEASUREMENTS  
INCHES

STATION (NO.)	0.0	60.0	90.0	150.0	180.0	240.0	270.0	330.0	MEDIAN	MINIMUM
1.0										
2.0										
3.0										
4.0										
5.0										
6.0										
7.0										
8.0										
9.0										
10.0										
11.0	0.401	0.394	0.414	0.402	0.399	0.398	0.391	0.406	0.400	0.391

A BLANK INDICATES NO DATA WAS TAKEN AT THAT STATION

*Thiokol* CORPORATION  
SPACE OPERATIONS

KSMM-32B IGNITER CHAMBER AND ADAPTER INSULATION PERFORMANCE

COMPLIANCE SAFETY FACTORS (CSF)

STATION (NO.)	0.0	60.0	90.0	150.0	180.0	240.0	270.0	330.0	MINIMUM	PLANE
1.0										
2.0										
3.0										
4.0										
5.0										
6.0										
7.0										
8.0										
9.0										
10.0										
11.0	3.25	3.10	3.59	3.28	3.21	3.18	3.03	3.37	3.03	270.0

SF= + INDICATES THAT NEGLIGIBLE MDD OCCURRED

A BLANK INDICATES NO DATA AVAILABLE FOR THAT STATION

ACTUAL SAFETY FACTORS (ASF)

STATION (NO.)	0.0	60.0	90.0	150.0	180.0	240.0	270.0	330.0	MINIMUM	PLANE
1.0										
2.0										
3.0										
4.0										
5.0										
6.0										
7.0										
8.0										
9.0										
10.0										
11.0	3.88	3.70	4.29	3.91	3.83	3.80	3.62	4.03	3.62	270.0

SF= + INDICATES THAT NEGLIGIBLE MDD OCCURRED

A BLANK INDICATES NO DATA AVAILABLE FOR THAT STATION



RSRM-32B IGNITER CHAMBER AND ADAPTER INSULATION PERFORMANCE

STATION (NO.)	MATERIAL DECOMPOSITION DEPTH (MDD) (INCHES)				DEGREE LOCATION					
	0.0	60.0	90.0	150.0	180.0	240.0	270.0	330.0	MEDIAN	MAXIMUM
1.0										
2.0										
3.0										
4.0										
5.0										
6.0										
7.0										
8.0										
9.0										
10.0										
11.0	0.139	0.146	0.126	0.138	0.141	0.142	0.149	0.134	0.140	0.149

A BLANK INDICATES NO DATA AVAILABLE FOR THAT STATION

STATION (NO.)	MATERIAL DECOMPOSITION RATE (MDR) (MILS/SEC)				DEGREE LOCATION				
	0.0	60.0	90.0	150.0	180.0	240.0	270.0	330.0	AVERAGE
1.0									
2.0									
3.0									
4.0									
5.0									
6.0									
7.0									
8.0									
9.0									
10.0									
11.0	1.1	1.2	1.0	1.1	1.2	1.2	1.1	1.1	1.1

MOTOR ACTION (EXPOSURE) TIME = 122.10 SEC

A MDR=0 INDICATES THAT MDR < .1 MIL/SEC

A BLANK INDICATES NO DATA AVAILABLE FOR THAT STATION

## Tables 3, 4, 5, 6

## C-III

## RSRM-32A FORWARD CENTER NBR INHBITOR MEASUREMENTS

DEGREE LOCATION	INCH STATION						
	4.2	4.7	10.7	15.7	18.7	23.7	26.6
0	0.764	0.757	0.712	0.572	0.529	0.423	0.418
60	0.890	0.895	0.761	0.723	0.572	0.416	N/A
120	0.863	0.878	0.715	0.634	0.478	0.399	N/A
180	0.869	0.852	0.748	0.695	0.581	0.500	N/A
240	0.863	0.848	0.718	0.616	0.474	N/A	N/A
300	0.899	0.905	0.798	0.648	0.509	0.365	N/A

\*NOTE: AN N/A INDICATES INHIBITOR ERODED PAST INCH STATION

## C-IV

## RSRM-32B FORWARD CENTER NBR INHBITOR MEASUREMENTS

DEGREE LOCATION	INCH STATION						
	4.2	4.7	10.7	15.7	18.7	23.7	26.6
0	0.920	0.887	0.862	0.697	0.642	0.566	N/A
60	0.945	0.952	0.823	0.838	0.660	0.519	N/A
120	0.992	0.997	0.982	0.690	0.582	0.515	N/A
180	0.890	0.887	0.833	0.706	0.734	0.563	N/A
240	0.941	0.960	0.811	0.694	0.612	N/A	N/A
300	0.955	0.968	0.802	0.860	0.614	0.445	N/A

\*NOTE: AN N/A INDICATES INHIBITOR ERODED PAST INCH STATION

## C-V

## RSRM-32A AFT CENTER NBR INHBITOR MEASUREMENTS

DEGREE LOCATION	INCH STATION						
	4.2	4.7	10.7	15.7	18.7	23.7	26.6
0	0.696	0.666	0.400	N/A	N/A	N/A	N/A
60	0.729	0.718	0.397	N/A	N/A	N/A	N/A
120	0.702	0.661	0.415	N/A	N/A	N/A	N/A
180	0.709	0.675	0.470	N/A	N/A	N/A	N/A
240	0.740	0.707	0.415	N/A	N/A	N/A	N/A
300	0.702	0.669	N/A	N/A	N/A	N/A	N/A

\*NOTE: AN N/A INDICATES INHIBITOR ERODED PAST INCH STATION

## C-VI

## RSRM-32B AFT CENTER NBR INHBITOR MEASUREMENTS

DEGREE LOCATION	INCH STATION						
	4.2	4.7	10.7	15.7	18.7	23.7	26.6
0	0.762	0.745	0.418	N/A	N/A	N/A	N/A
60	0.770	0.765	0.370	N/A	N/A	N/A	N/A
120	0.803	0.770	0.499	N/A	N/A	N/A	N/A
180	0.825	0.790	0.455	N/A	N/A	N/A	N/A
240	0.794	0.772	0.457	N/A	N/A	N/A	N/A
300	0.796	0.792	0.414	N/A	N/A	N/A	N/A

\*NOTE: AN N/A INDICATES INHIBITOR ERODED PAST INCH STATION

Tables 7, 8

C-VII

RSRM-32A AFT NBR INHBITOR MEASUREMENTS

DEGREE LOCATION	INCH STATION	
	3.9	4.9
0	0.510	0.369
60	0.428	0.051
120	0.430	N/A
180	0.253	N/A
270	0.405	N/A
315	0.413	N/A

\*NOTE: AN N/A INDICATES INHIBITOR ERODED PAST INCH STATION

C-VIII

RSRM-32B AFT NBR INHBITOR MEASUREMENTS

DEGREE LOCATION	INCH STATION	
	3.9	4.9
0	N/A	N/A
60	N/A	N/A
120	0.513	0.365
180	N/A	N/A
270	0.437	N/A
315	N/A	N/A

\*NOTE: AN N/A INDICATES INHIBITOR ERODED PAST INCH STATION